

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1	WLK1622	3% < Cross Slope < 5%		driveway integrated with sidewalk. driveway flares in travel path.	NEW MARKET ST SW - E	Other	5/7/2020
2	WLK1621	3% < Cross Slope < 5%		driveway flares in travel path at timberland library	NEW MARKET ST SW - W	Other	5/7/2020
3	WLK1621	3% < Cross Slope < 5%		driveway flares in travel path at timberland library	NEW MARKET ST SW - W	Other	5/7/2020
4	WLK1621	Crack between 3/4 inch and 1-1/4 inch	Age	large sidewalk expansion joint	NEW MARKET ST SW - W	Other	5/7/2020
5	WLK1614	No passing space		sidewalk less than 4' wide due to overgrowth	ISRAEL RD SW - S	Urban Collector	5/7/2020
6	WLK1614	3% < Cross Slope < 5%		driveway flares in travel path at Israel and gaston	ISRAEL RD SW - S	Urban Collector	5/7/2020
7	WLK1615	3% < Cross Slope < 5%		driveway flares in travel path	ISRAEL RD SW - S	Urban Collector	5/7/2020
8	WLK1615	Hole > 1-1/4 inch	Age	horrible condition driveway. not safe	ISRAEL RD SW - S	Urban Collector	5/7/2020
9	WLK1615	3% < Cross Slope < 5%		driveway flares in travel way	ISRAEL RD SW - S	Urban Collector	5/7/2020
10	WLK1618	Severe Cracking	Age	badly broken driveway entrance to 727, 729, 731 on israel	ISRAEL RD SW - S	Urban Collector	5/7/2020
11	WLK1618	3% < Cross Slope < 5%		driveway flares in travel path	ISRAEL RD SW - S	Urban Collector	5/7/2020
12	WLK1618	Cross Slope > 5%		cross slope measured 10% on driveway flares in travel path	ISRAEL RD SW - S	Urban Collector	5/7/2020
13	WLK1619	Moderate Cracking		driveway is very beaten up. in path of pedestrians. at entrance to meadowood parking area	ISRAEL RD SW - S	Urban Collector	5/7/2020
14	WLK1619	No passing space		sidewalks are less than 60" wide	ISRAEL RD SW - S	Urban Collector	5/7/2020
15	WLK1619	Cross Slope > 5%		driveway flares in travel path. measured 16.5%	ISRAEL RD SW - S	Urban Collector	5/7/2020
16	WLK1619	Hole between 3/4 inch and 1-1/4 inch	Age	hole was roughly 1" x 0.5"	ISRAEL RD SW - S	Urban Collector	5/7/2020
17	WLK1619	Cross Slope > 5%		driveway flares in travel path. measured 7.7%	ISRAEL RD SW - S	Urban Collector	5/7/2020
18	WLK1619	Minor Spalling		looks as if overlay got on driveway. raised and cracked portion in travel path	ISRAEL RD SW - S	Urban Collector	5/7/2020
19	WLK1627	Cross Slope > 5%	Root System	roots uplifting sidewalk. 9.4% cross slope	LINDERSON WAY SW - E		5/7/2020
20	WLK1627	Vertical displacement < 3/4 inch	Root System	measured 0.5"	LINDERSON WAY SW - E		5/7/2020
21	WLK1627	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System	measured 0" low side to 1.1" displacement on high side	LINDERSON WAY SW - E		5/7/2020
22	WLK1627	Cross Slope > 5%	Root System	measured 7.2%	LINDERSON WAY SW - E		5/7/2020
23	WLK1627	3% < Cross Slope < 5%	Root System	measured 4.8%	LINDERSON WAY SW - E		5/7/2020
24	WLK1628	Cross Slope > 5%		measured 10.4%. driveway flares in travel path	LINDERSON WAY SW - E		5/7/2020
25	WLK1628	Cross Slope > 5%		just needs to be cleaned of piled dirt.	LINDERSON WAY SW - E		5/7/2020
26	WLK1628	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement	measured about 0.8"	LINDERSON WAY SW - E		5/7/2020
27	WLK1628	Cross Slope > 5%		measured 8.4%. driveway flares in travel path	LINDERSON WAY SW - E		5/7/2020
28	WLK1629	No passing space		sidewalks are less than 60" wide.	LINDERSON WAY SW - E		5/7/2020
29	WLK1641	Vertical displacement < 3/4 inch	Root System	highest edge is about 0.7"	TUMWATER BLVD SW - N	Principal Arterial	5/7/2020
30	WLK1646	Vertical displacement > 1-1/4 inch	Root System	roots pulling up panels	TUMWATER BLVD SW - N	Principal Arterial	5/7/2020
31	WLK1648	Vertical displacement > 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	5/7/2020
32	WLK1648	Vertical displacement > 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	5/7/2020
33	WLK1172	Cross Slope > 5%		driveway flares in travel path. measured 6%		Principal Arterial	5/7/2020
34	WLK1610	Cross Slope > 5%		driveway flares in travel path. measured 14.3%	ISRAEL RD SW - S	Urban Collector	5/7/2020
35	WLK1610	Minor Cracking		driveway of firestation. needs thicker pavement section for stationary load	ISRAEL RD SW - S	Urban Collector	5/7/2020
36	WLK1605	Vertical displacement > 1-1/4 inch	Root System	measured 2.5"	6TH AVE SW - W	Other	5/8/2020
37	WLK1605	Cross Slope > 5%	Root System	measured 9.2%	6TH AVE SW - W	Other	5/8/2020
38	WLK1617	3% < Cross Slope < 5%	Root System	measured 3.4%	ISRAEL RD SW - N	Urban Collector	5/8/2020
39	WLK1617	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System	measured 0.9"	ISRAEL RD SW - N	Urban Collector	5/8/2020
40	WLK1620	3% < Cross Slope < 5%	Root System	measured 4.1%	ISRAEL RD SW - N	Urban Collector	5/8/2020
41	WLK1620	3% < Cross Slope < 5%	Root System	measured 4.4%	ISRAEL RD SW - N	Urban Collector	5/8/2020
42	WLK1620	Vertical displacement > 1-1/4 inch	Root System	measured 2"	ISRAEL RD SW - N	Urban Collector	5/8/2020
43	WLK1623	Vertical displacement > 1-1/4 inch	Root System	measured 2"	LINDERSON WAY SW - E		5/8/2020
44	WLK1623	Vertical displacement < 3/4 inch	Root System	measured 0.6"	LINDERSON WAY SW - E		5/8/2020
45	WLK1623	Vertical displacement > 1-1/4 inch	Root System	measured 1.5"	LINDERSON WAY SW - E		5/8/2020
46	WLK1623	Running Slope > 8.33%		steep flare	LINDERSON WAY SW - E		7/28/2020
47	WLK1623	Crack < 3/4 inch	Root System	busted panel	LINDERSON WAY SW - E		7/28/2020
48	WLK1623	Crack < 3/4 inch		crack at street light	LINDERSON WAY SW - E		7/28/2020
49	WLK1624	Running Slope > 8.33%		driveway flare 9.6%	LINDERSON WAY SW - W	Urban Collector	7/28/2020
50	WLK1624	Running Slope > 8.33%		driveway flare 13.2%	LINDERSON WAY SW - W	Urban Collector	7/28/2020
51	WLK1624	Crack < 3/4 inch		small cracked portion	LINDERSON WAY SW - W	Urban Collector	7/28/2020
52	WLK1600	Running Slope > 8.33%		driveway flare 11.3%	DENNIS ST SW - S	Urban Collector	7/28/2020
53	WLK1600	Running Slope > 8.33%	Root System	9.8% slope	DENNIS ST SW - S	Urban Collector	7/28/2020
54	WLK1600	Crack < 3/4 inch	Root System	crack 2 panels	DENNIS ST SW - S	Urban Collector	7/28/2020
55	WLK1600	Running Slope > 8.33%	Root System	9.0%	DENNIS ST SW - S	Urban Collector	7/28/2020
56	WLK1601	Running Slope > 8.33%		driveway flare too steep	DENNIS ST SW - S	Urban Collector	7/28/2020
57	WLK1601	Running Slope > 8.33%		11.1%	DENNIS ST SW - S	Urban Collector	7/28/2020
58	WLK1601	No passing space		4' sidewalk	DENNIS ST SW - S	Urban Collector	7/28/2020
59	WLK1604	Cross Slope > 5%		driveway flare	DENNIS ST SW - S	Urban Collector	7/28/2020
60	WLK1604	200' < Passing Space < 400'			DENNIS ST SW - S	Urban Collector	7/28/2020
61	WLK1607	Running Slope > 8.33%		driveway flare	DENNIS ST SW - S	Urban Collector	7/28/2020
62	WLK1607	Cross Slope > 5%		12.6%	DENNIS ST SW - S	Urban Collector	7/28/2020
63	WLK1607	Vertical displacement < 3/4 inch		water meter boxes not at grade	DENNIS ST SW - S	Urban Collector	7/28/2020
64	WLK1607	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
65	WLK1607	No passing space	Settlement	less than 36". prune brush	DENNIS ST SW - S	Urban Collector	7/28/2020
66	WLK1607	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
67	WLK1608	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
68	WLK1608	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
69	WLK1608	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
70	WLK1608	Cross Slope > 5%		driveway	DENNIS ST SW - S	Urban Collector	7/28/2020
71	WLK1608	Vertical displacement < 3/4 inch	Root System	roughly 3/4"	DENNIS ST SW - S	Urban Collector	7/28/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
72	WLK1171	Cross Slope > 5%	Root System	9%		Principal Arterial	7/28/2020
73	WLK1171	Cross Slope > 5%	Root System	5.1%		Principal Arterial	7/28/2020
74	WLK1171	Cross Slope > 5%	Root System	5.6%		Principal Arterial	7/28/2020
75	WLK1171	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
76	WLK1610	Cross Slope > 5%		5.6%		Principal Arterial	7/28/2020
77	WLK1609	Vertical displacement < 3/4 inch		small lip	ISRAEL RD SW - S	Urban Collector	7/28/2020
78	WLK1609	Vertical displacement < 3/4 inch	Root System		ISRAEL RD SW - N	Urban Collector	7/28/2020
79	WLK1609	Severe Cracking			ISRAEL RD SW - N	Urban Collector	7/28/2020
80	WLK1609	Cross Slope > 5%			ISRAEL RD SW - N	Urban Collector	7/28/2020
81	WLK1609	No passing space			ISRAEL RD SW - N	Urban Collector	7/28/2020
82	WLK1609	Cross Slope > 5%		driveway	ISRAEL RD SW - N	Urban Collector	7/28/2020
83	WLK1609	200' < Passing Space < 400'			ISRAEL RD SW - N	Urban Collector	7/28/2020
84	WLK1612	200' < Passing Space < 400'			ISRAEL RD SW - N	Urban Collector	7/28/2020
85	WLK1615	Vertical displacement is in the vicinity of a sensitive location			ISRAEL RD SW - S	Urban Collector	7/28/2020
86	WLK1617	Vertical displacement is in the vicinity of a sensitive location			ISRAEL RD SW - N	Urban Collector	7/28/2020
87	WLK1620	Vertical displacement is in the vicinity of a sensitive location	Root System		ISRAEL RD SW - N	Urban Collector	7/28/2020
88	WLK1620	Vertical displacement is in the vicinity of a sensitive location	Root System		ISRAEL RD SW - N	Urban Collector	7/28/2020
89	WLK1541	Cross Slope > 5%		really bad	LINDERSON WAY SW - E	Urban Collector	7/28/2020
90	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
91	WLK1541	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		LINDERSON WAY SW - E	Urban Collector	7/28/2020
92	WLK1541	Moderate Spalling			LINDERSON WAY SW - E	Urban Collector	7/28/2020
93	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
94	WLK1541	Vertical displacement < 3/4 inch			LINDERSON WAY SW - E	Urban Collector	7/28/2020
95	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
96	WLK1541	200' < Passing Space < 400'		need to remove grass overtopping sidewalk	LINDERSON WAY SW - E	Urban Collector	7/28/2020
97	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
98	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
99	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
100	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
101	WLK1541	No passing space			LINDERSON WAY SW - E	Urban Collector	7/28/2020
102	WLK1541	Cross Slope > 5%			LINDERSON WAY SW - E	Urban Collector	7/28/2020
103	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
104	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
105	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
106	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
107	WLK1541	Cross Slope > 5%		driveway	LINDERSON WAY SW - E	Urban Collector	7/28/2020
108	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
109	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
110	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
111	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
112	WLK1533	No passing space			LEE ST SW - S	Urban Collector	7/28/2020
113	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
114	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
115	WLK1533	Cross Slope > 5%		driveway	LEE ST SW - S	Urban Collector	7/28/2020
116	WLK1156	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
117	WLK1156	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
118	WLK1160	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
119	WLK1160	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
120	WLK1160	Cross Slope > 5%		driveway flare		Principal Arterial	7/28/2020
121	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
122	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
123	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
124	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
125	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
126	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
127	WLK1162	Cross Slope > 5%		driveway		Principal Arterial	7/28/2020
128	WLK1162	Cross Slope > 5%		driveway flare		Principal Arterial	7/28/2020
129	WLK1165	Cross Slope > 5%		driveway flare		Principal Arterial	7/28/2020
130	WLK1158	Cross Slope > 5%		driveway flare	M ST SE - S	Principal Arterial	7/28/2020
131	WLK1158	Cross Slope > 5%		driveway flare	M ST SE - S	Principal Arterial	7/28/2020
132	WLK1532	Severe Cracking		major cracking	LEE ST SW - N	Urban Collector	7/28/2020
133	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
134	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
135	WLK1532	No passing space			LEE ST SW - N	Urban Collector	7/28/2020
136	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
137	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
138	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
139	WLK1532	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		LEE ST SW - N	Urban Collector	7/28/2020
140	WLK1532	Cross Slope > 5%		driveway flare	LEE ST SW - N	Urban Collector	7/28/2020
141	WLK1600	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - S	Urban Collector	7/29/2020
142	WLK1596	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
143	WLK1596	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
144	WLK1596	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
145	WLK1596	Running Slope > 8.33%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
146	WLK1596	No passing space			DENNIS ST SW - N	Urban Collector	7/29/2020
147	WLK1595	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
148	WLK1595	Vertical displacement > 1-1/4 inch	Root System		HIGHLAND DR SW - W	Other	7/29/2020
149	WLK1595	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
150	WLK1595	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
151	WLK1594	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
152	WLK1594	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
153	WLK1593	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
154	WLK1593	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
155	WLK1593	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
156	WLK1592	Running Slope > 8.33%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
157	WLK1592	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
158	WLK1592	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
159	WLK1591	Cross Slope > 5%		crosswalk ramp	BONNIE LN SW - E	Other	7/29/2020
160	WLK1590	Cross Slope > 5%	Driveway/Driveway Flare		BONNIE LN SW - E	Other	7/29/2020
161	WLK1591	Cross Slope > 5%	Driveway/Driveway Flare		BONNIE LN SW - E	Other	7/29/2020
162	WLK1591	Cross Slope > 5%	Driveway/Driveway Flare		BONNIE LN SW - E	Other	7/29/2020
163	WLK1590	Cross Slope > 5%	Driveway/Driveway Flare		BONNIE LN SW - E	Other	7/29/2020
164	WLK1589	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
165	WLK1589	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
166	WLK1589	No passing space			TARTAN DR SW - N	Other	7/29/2020
167	WLK1588	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
168	WLK1588	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
169	WLK1588	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
170	WLK1587	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
171	WLK1587	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
172	WLK1587	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - W	Other	7/29/2020
173	WLK1586	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
174	WLK1586	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
175	WLK1584	Cross Slope > 5%	Driveway/Driveway Flare		HEATHER LN SW - N	Other	7/29/2020
176	WLK1585	Cross Slope > 5%	Root System		HEATHER LN SW - N	Other	7/29/2020
177	WLK1584	Cross Slope > 5%	Driveway/Driveway Flare		HEATHER LN SW - N	Other	7/29/2020
178	WLK1585	Running Slope > 8.33%	Driveway/Driveway Flare		HEATHER LN SW - N	Other	7/29/2020
179	WLK1584	Cross Slope > 5%	Driveway/Driveway Flare		HEATHER LN SW - N	Other	7/29/2020
180	WLK1585	Running Slope > 8.33%	Driveway/Driveway Flare		HEATHER LN SW - N	Other	7/29/2020
181	WLK1583	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
182	WLK1583	Vertical displacement < 3/4 inch	Root System		TARTAN DR SW - N	Other	7/29/2020
183	WLK1583	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - N	Other	7/29/2020
184	WLK1569	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	7/29/2020
185	WLK1572	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	7/29/2020
186	WLK1572	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	7/29/2020
187	WLK1569	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	7/29/2020
188	WLK1568	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	7/29/2020
189	WLK1572	No passing space			7TH AVE SW - E	Other	7/29/2020
190	WLK1566	Cross Slope > 5%		crosswalk ramp	Y ST SW - S	Other	7/29/2020
191	WLK1569	No passing space			7TH AVE SW - W	Other	7/29/2020
192	WLK1573	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
193	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
194	WLK1573	No passing space		4' sidewalk	65TH WAY SW - S	Other	7/29/2020
195	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
196	WLK1566	No passing space			Y ST SW - S	Other	7/29/2020
197	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
198	WLK1573	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
199	WLK1573	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
200	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
201	WLK1574	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
202	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
203	WLK1574	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
204	WLK1574	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System	1"	65TH WAY SW - S	Other	7/29/2020
205	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/29/2020
206	WLK1574	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
207	WLK1574	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
208	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020
209	WLK1563	No passing space			65TH WAY SW - S	Other	7/29/2020
210	WLK1564	Vertical displacement < 3/4 inch	Root System		65TH WAY SW - N	Other	7/29/2020
211	WLK1564	3% < Cross Slope < 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020
212	WLK1563	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
213	WLK1564	5% < Running Slope < 8.33%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
214	WLK1563	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/29/2020
215	WLK1564	3% < Cross Slope < 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020
216	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020
217	WLK1564	3% < Cross Slope < 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/29/2020
218	WLK1575	Vertical displacement < 3/4 inch	Root System		DENNIS PL SW - W	Other	7/29/2020
219	WLK1562	Cross Slope > 5%	Driveway/Driveway Flare		PARK LN SW - E	Other	7/29/2020
220	WLK1575	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - W	Other	7/29/2020
221	WLK1562	No passing space			PARK LN SW - E	Other	7/29/2020
222	WLK1575	No passing space			DENNIS PL SW - W	Other	7/29/2020
223	WLK1575	Vertical displacement < 3/4 inch	Root System		DENNIS PL SW - W	Other	7/29/2020
224	WLK1575	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - W	Other	7/29/2020
225	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/29/2020
226	WLK1560	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/29/2020
227	WLK1560	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/29/2020
228	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/29/2020
229	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/29/2020
230	WLK1576	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - W	Other	7/29/2020
231	WLK1559	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - E	Other	7/29/2020
232	WLK1576	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - W	Other	7/29/2020
233	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
234	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
235	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
236	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
237	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
238	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/29/2020
239	WLK1577	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
240	WLK1577	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
241	WLK1577	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
242	WLK1578	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
243	WLK1578	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
244	WLK1602	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - W	Other	7/29/2020
245	WLK1602	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - W	Other	7/29/2020
246	WLK1603	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - E	Other	7/29/2020
247	WLK1602	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - W	Other	7/29/2020
248	WLK1603	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - E	Other	7/29/2020
249	WLK1603	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - E	Other	7/29/2020
250	WLK1602	Cross Slope > 5%	Driveway/Driveway Flare		STANTON CT SW - W	Other	7/29/2020
251	WLK1570	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	7/29/2020
252	WLK1571	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	7/29/2020
253	WLK1571	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	7/29/2020
254	WLK1582	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
255	WLK1582	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
256	WLK1581	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
257	WLK1581	No passing space			TARTAN DR SW - S	Other	7/29/2020
258	WLK1581	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
259	WLK1581	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
260	WLK1581	Cross Slope > 5%	Driveway/Driveway Flare		TARTAN DR SW - S	Other	7/29/2020
261	WLK1580	No passing space			HIGHLAND DR SW - E	Other	7/29/2020
262	WLK1580	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - E	Other	7/29/2020
263	WLK1580	Cross Slope > 5%	Driveway/Driveway Flare		HIGHLAND DR SW - E	Other	7/29/2020
264	WLK1601	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - S	Urban Collector	7/29/2020
265	WLK1579	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
266	WLK1579	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
267	WLK1579	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
268	WLK1579	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
269	WLK1579	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SW - N	Urban Collector	7/29/2020
270	WLK99	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
271	WLK99	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
272	WLK99	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
273	WLK99	Vertical displacement is in the vicinity of a sensitive location			TROSPER RD SW - S	Minor Arterial	7/29/2020
274	WLK100	Vertical displacement is in the vicinity of a sensitive location			TROSPER RD SW - S	Minor Arterial	7/29/2020
275	WLK100	Vertical displacement is in the vicinity of a sensitive location			TROSPER RD SW - S	Minor Arterial	7/29/2020
276	WLK100	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
277	WLK100	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
278	WLK100	No passing space			TROSPER RD SW - S	Minor Arterial	7/29/2020
279	WLK100	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
280	WLK101	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
281	WLK102	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
282	WLK102	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
283	WLK103	No passing space			SCHOTH ST SW - E	Other	7/29/2020
284	WLK306	Cross Slope > 5%	Driveway/Driveway Flare		RURAL RD SW - E	Urban Collector	7/29/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
285	WLK103	Crack < 3/4 inch	Root System		SCHOTH ST SW - E	Other	7/29/2020
286	WLK103	Cross Slope > 5%	Driveway/Driveway Flare		SCHOTH ST SW - E	Other	7/29/2020
287	WLK104	Cross Slope > 5%	Driveway/Driveway Flare		SCHOTH ST SW - W	Other	7/29/2020
288	WLK104	No passing space			SCHOTH ST SW - W	Other	7/29/2020
289	WLK105	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
290	WLK105	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
291	WLK105	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
292	WLK106	No passing space			TROSPER RD SW - S	Minor Arterial	7/29/2020
293	WLK106	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	7/29/2020
294	WLK300	Vertical displacement is in the vicinity of a sensitive location	Root System		TROSPER RD SW - N	Minor Arterial	7/29/2020
295	WLK300	Vertical displacement is in the vicinity of a sensitive location	Root System		TROSPER RD SW - N	Minor Arterial	7/29/2020
296	WLK302	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Minor Arterial	7/29/2020
297	WLK302	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Minor Arterial	7/29/2020
298	WLK303	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Minor Arterial	7/29/2020
299	WLK303	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Minor Arterial	7/29/2020
300	WLK303	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Minor Arterial	7/29/2020
301	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
302	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
303	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
304	WLK307	No passing space		4'	LAKE PARK DR SW - W	Urban Collector	7/29/2020
305	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
306	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
307	WLK307	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
308	WLK311	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
309	WLK311	3% < Cross Slope < 5%		4.4%	LAKE PARK DR SW - W	Urban Collector	7/29/2020
310	WLK311	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
311	WLK311	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	7/29/2020
312	WLK311	Vertical displacement > 1-1/4 inch	Settlement		LAKE PARK DR SW - W	Urban Collector	7/29/2020
313	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
314	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
315	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
316	WLK313	2% < Cross Slope < 3%			LANA LN SW - E	Other	7/29/2020
317	WLK313	Cross Slope > 5%		panel uplifted in corners causing significant cross slope	LANA LN SW - E	Other	7/29/2020
318	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
319	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
320	WLK313	Crack between 3/4 inch and 1-1/4 inch	Settlement	1"	LANA LN SW - E	Other	7/29/2020
321	WLK313	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - E	Other	7/29/2020
322	WLK314	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - W	Other	7/29/2020
323	WLK314	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - W	Other	7/29/2020
324	WLK314	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - W	Other	7/29/2020
325	WLK314	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - W	Other	7/29/2020
326	WLK314	Cross Slope > 5%	Driveway/Driveway Flare		LANA LN SW - W	Other	7/29/2020
327	WLK314	No passing space		4'	LANA LN SW - W	Other	7/29/2020
328	WLK312	No passing space			LAKE PARK DR SW - E	Urban Collector	7/29/2020
329	WLK312	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	7/29/2020
330	WLK312	Vertical displacement > 1-1/4 inch	Root System	2"+	LAKE PARK DR SW - E	Urban Collector	7/29/2020
331	WLK308	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	7/29/2020
332	WLK308	No passing space			LAKE PARK DR SW - E	Urban Collector	7/29/2020
333	WLK308	Cross Slope > 5%			LAKE PARK DR SW - E	Urban Collector	7/29/2020
334	WLK308	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	7/29/2020
335	WLK308	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	7/29/2020
336	WLK308	3% < Cross Slope < 5%		4.8%	LAKE PARK DR SW - E	Urban Collector	7/29/2020
337	WLK308	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	7/29/2020
338	WLK313	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		LANA LN SW - E	Other	7/29/2020
339	WLK19	Cross Slope > 5%			TYEE DR SW - W	Minor Arterial	7/29/2020
340	WLK19	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System	1"	TYEE DR SW - W	Minor Arterial	7/29/2020
341	WLK19	3% < Cross Slope < 5%		4.3%	TYEE DR SW - W	Minor Arterial	7/29/2020
342	WLK19	Vertical displacement > 1-1/4 inch	Root System	3"	TYEE DR SW - W	Minor Arterial	7/29/2020
343	WLK19	3% < Cross Slope < 5%	Root System	4.8%	TYEE DR SW - W	Minor Arterial	7/29/2020
344	WLK19	Cross Slope > 5%	Root System	5.2%	TYEE DR SW - W	Minor Arterial	7/29/2020
345	WLK19	Cross Slope > 5%	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
346	WLK19	3% < Cross Slope < 5%	Root System	4.3%	TYEE DR SW - W	Minor Arterial	7/29/2020
347	WLK19	2% < Cross Slope < 3%	Root System	3%	TYEE DR SW - W	Minor Arterial	7/29/2020
348	WLK19	3% < Cross Slope < 5%	Settlement		TYEE DR SW - W	Minor Arterial	7/29/2020
349	WLK19	2% < Cross Slope < 3%	Settlement		TYEE DR SW - W	Minor Arterial	7/29/2020
350	WLK19	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
351	WLK48	2% < Cross Slope < 3%	Root System		KINGSWOOD DR SW - S	Commercial/Industrial Collector	7/29/2020
352	WLK18	3% < Cross Slope < 5%	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
353	WLK18	Cross Slope > 5%	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
354	WLK18	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
355	WLK18	Vertical displacement > 1-1/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
356	WLK18	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
357	WLK18	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
358	WLK18	3% < Cross Slope < 5%	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
359	WLK18	Vertical displacement < 3/4 inch	Root System		TYEE DR SW - W	Minor Arterial	7/29/2020
360	WLK17	Moderate Cracking	Settlement		TYEE DR SW - W		7/29/2020
361	WLK44	3% < Cross Slope < 5%	Settlement		LITTLEROCK RD SW - E	Minor Arterial	7/29/2020
362	WLK30	Vertical displacement > 1-1/4 inch	Root System		MCIVER CT SW - E	Other	7/29/2020
363	WLK30	FALSE			MCIVER CT SW - E	Other	7/30/2020
364	WLK1542	3% < Cross Slope < 5%			X ST SW - N	Other	7/30/2020
365	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
366	WLK1542	No passing space			X ST SW - N	Other	7/30/2020
367	WLK1542	3% < Cross Slope < 5%			X ST SW - N	Other	7/30/2020
368	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
369	WLK1542	3% < Cross Slope < 5%			X ST SW - N	Other	7/30/2020
370	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
371	WLK1542	3% < Cross Slope < 5%			X ST SW - N	Other	7/30/2020
372	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
373	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
374	WLK1542	No passing space			X ST SW - N	Other	7/30/2020
375	WLK1542	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
376	WLK1542	Cross Slope > 5%			X ST SW - N	Other	7/30/2020
377	WLK1561	Moderate Cracking			X ST SW - S	Other	7/30/2020
378	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
379	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
380	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
381	WLK1561	3% < Cross Slope < 5%	Settlement		X ST SW - S	Other	7/30/2020
382	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
383	WLK1561	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
384	WLK1561	3% < Cross Slope < 5%	Settlement		X ST SW - S	Other	7/30/2020
385	WLK1560	No passing space			X ST SW - S	Other	7/30/2020
386	WLK1557	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
387	WLK1557	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
388	WLK1557	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
389	WLK1557	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
390	WLK1557	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
391	WLK1556	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
392	WLK1556	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - S	Other	7/30/2020
393	WLK1555	No passing space			X ST SW - N	Other	7/30/2020
394	WLK1555	Cross Slope > 5%	Root System		X ST SW - N	Other	7/30/2020
395	WLK1555	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
396	WLK1558	No passing space			X ST SW - N	Other	7/30/2020
397	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
398	WLK1558	3% < Cross Slope < 5%			X ST SW - N	Other	7/30/2020
399	WLK1558	Cross Slope > 5%	Settlement		X ST SW - N	Other	7/30/2020
400	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
401	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
402	WLK1558	Cross Slope > 5%	Driveway/Driveway Flare		X ST SW - N	Other	7/30/2020
403	WLK1559	No passing space			DENNIS PL SW - E	Other	7/30/2020
404	WLK1559	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS PL SW - E	Other	7/30/2020
405	WLK1562	Cross Slope > 5%	Driveway/Driveway Flare		PARK LN SW - E	Other	7/30/2020
406	WLK1562	Cross Slope > 5%	Driveway/Driveway Flare		PARK LN SW - E	Other	7/30/2020
407	WLK1562	No passing space			PARK LN SW - E	Other	7/30/2020
408	WLK1567	3% < Cross Slope < 5%	Settlement		Y ST SW - N	Other	7/30/2020
409	WLK1567	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - N	Other	7/30/2020
410	WLK1567	No passing space			Y ST SW - N	Other	7/30/2020
411	WLK1567	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - N	Other	7/30/2020
412	WLK1567	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - N	Other	7/30/2020
413	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
414	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
415	WLK1566	No passing space			Y ST SW - S	Other	7/30/2020
416	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
417	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
418	WLK1566	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
419	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
420	WLK1565	No passing space			Y ST SW - S	Other	7/30/2020
421	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
422	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
423	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
424	WLK1565	2% < Cross Slope < 3%	Settlement		Y ST SW - S	Other	7/30/2020
425	WLK1565	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SW - S	Other	7/30/2020
426	WLK1564	2% < Cross Slope < 3%	Settlement		65TH WAY SW - N	Other	7/30/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
427	WLK1564	No passing space			65TH WAY SW - N	Other	7/30/2020
428	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
429	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
430	WLK1564	2% < Cross Slope < 3%	Settlement		65TH WAY SW - N	Other	7/30/2020
431	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
432	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
433	WLK1564	No passing space			65TH WAY SW - N	Other	7/30/2020
434	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
435	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
436	WLK1564	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - N	Other	7/30/2020
437	WLK1563	Cross Slope > 5%	Driveway/Driveway Flare		65TH WAY SW - S	Other	7/30/2020
439	WLK1552	No passing space			W ST SW - S	Other	7/30/2020
440	WLK1552	No passing space			W ST SW - S	Other	7/30/2020
441	WLK1552	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		W ST SW - S	Other	7/30/2020
442	WLK1552	Cross Slope > 5%	Driveway/Driveway Flare		W ST SW - S	Other	7/30/2020
443	WLK1552	Cross Slope > 5%	Driveway/Driveway Flare		W ST SW - S	Other	7/30/2020
444	WLK1552	No passing space			W ST SW - S	Other	7/30/2020
445	WLK1552	Cross Slope > 5%	Driveway/Driveway Flare		W ST SW - S	Other	7/30/2020
446	WLK1552	3% < Cross Slope < 5%	Settlement		W ST SW - S	Other	7/30/2020
447	WLK1552	No passing space			W ST SW - S	Other	7/30/2020
448	WLK1553	Cross Slope > 5%	Driveway/Driveway Flare		ESTHER ST SW - E	Other	7/30/2020
449	WLK1553	Cross Slope > 5%	Driveway/Driveway Flare		ESTHER ST SW - E	Other	7/30/2020
450	WLK1553	3% < Cross Slope < 5%	Settlement		ESTHER ST SW - E	Other	7/30/2020
451	WLK1554	No passing space			ESTHER ST SW - W	Other	7/30/2020
452	WLK1554	Cross Slope > 5%	Driveway/Driveway Flare		ESTHER ST SW - W	Other	7/30/2020
453	WLK1548	Cross Slope > 5%	Driveway/Driveway Flare		ESTHER ST SW - W	Other	7/30/2020
454	WLK1548	Cross Slope > 5%	Driveway/Driveway Flare		ESTHER ST SW - W	Other	7/30/2020
455	WLK1552	Cross Slope > 5%	Root System		W ST SW - S	Other	7/30/2020
456	WLK1552	Cross Slope > 5%	Driveway/Driveway Flare		W ST SW - S	Other	7/30/2020
457	WLK1550	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - W	Other	7/30/2020
458	WLK1550	No passing space			JANET ST SW - W	Other	7/30/2020
459	WLK1551	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - W	Other	7/30/2020
460	WLK1545	2% < Cross Slope < 3%			JANET ST SW - W	Other	7/30/2020
461	WLK1545	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - W	Other	7/30/2020
462	WLK1545	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - W	Other	7/30/2020
463	WLK1545	No passing space			JANET ST SW - W	Other	7/30/2020
464	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
465	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
466	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
467	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
468	WLK1546	2% < Cross Slope < 3%			V ST SW - S	Other	7/30/2020
469	WLK1546	Running Slope > 8.33%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
470	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
471	WLK1546	No passing space			V ST SW - S	Other	7/30/2020
472	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
473	WLK1546	Vertical displacement < 3/4 inch	Root System		V ST SW - S	Other	7/30/2020
474	WLK1546	3% < Cross Slope < 5%	Root System		V ST SW - S	Other	7/30/2020
475	WLK1546	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - S	Other	7/30/2020
476	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
477	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
478	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
479	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
480	WLK1547	No passing space			V ST SW - N	Other	7/30/2020
481	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
482	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
483	WLK1547	No passing space			V ST SW - N	Other	7/30/2020
484	WLK1547	Cross Slope > 5%	Driveway/Driveway Flare		V ST SW - N	Other	7/30/2020
486	WLK1544	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - E	Other	7/30/2020
487	WLK1544	Cross Slope > 5%	Driveway/Driveway Flare		JANET ST SW - E	Other	7/30/2020
488	WLK1534	Hole > 1-1/4 inch			GERTH ST SW - N	Other	7/30/2020
489	WLK1534	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - N	Other	7/30/2020
490	WLK1534	No passing space			GERTH ST SW - N	Other	7/30/2020
491	WLK1534	2% < Cross Slope < 3%			GERTH ST SW - N	Other	7/30/2020
492	WLK1534	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - N	Other	7/30/2020
493	WLK1535	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - S	Other	7/30/2020
494	WLK1535	No passing space			GERTH ST SW - S	Other	7/30/2020
495	WLK1535	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - S	Other	7/30/2020
496	WLK1535	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - S	Other	7/30/2020
497	WLK1535	3% < Cross Slope < 5%			GERTH ST SW - S	Other	7/30/2020
498	WLK1535	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GERTH ST SW - S	Other	7/30/2020
499	WLK1535	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - S	Other	7/30/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
500	WLK1535	No passing space			GERTH ST SW - S	Other	7/30/2020
501	WLK1535	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - S	Other	7/30/2020
502	WLK1534	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - N	Other	7/30/2020
503	WLK1534	Vertical displacement > 1-1/4 inch		tall weeds in joint	GERTH ST SW - N	Other	7/30/2020
504	WLK1534	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - N	Other	7/30/2020
505	WLK1534	No passing space			GERTH ST SW - N	Other	7/30/2020
506	WLK1534	Cross Slope > 5%	Driveway/Driveway Flare		GERTH ST SW - N	Other	7/30/2020
507	WLK1536	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - N	Other	7/30/2020
508	WLK1536	Minor Cracking			T ST SW - N	Other	7/30/2020
509	WLK1536	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - N	Other	7/30/2020
510	WLK1536	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - N	Other	7/30/2020
511	WLK1536	No passing space			T ST SW - N	Other	7/30/2020
512	WLK1536	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - N	Other	7/30/2020
513	WLK1539	Vertical displacement < 3/4 inch	Root System		PINEHURST DR SW - S	Other	7/30/2020
514	WLK1539	Vertical displacement < 3/4 inch	Root System		PINEHURST DR SW - S	Other	7/30/2020
515	WLK1539	Vertical displacement < 3/4 inch	Root System		PINEHURST DR SW - S	Other	7/30/2020
516	WLK1539	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SW - S	Other	7/30/2020
517	WLK1540	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SW - N	Other	7/30/2020
518	WLK1540	Crack < 3/4 inch	Root System		PINEHURST DR SW - N	Other	7/30/2020
519	WLK1540	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		PINEHURST DR SW - N	Other	7/30/2020
520	WLK1537	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - S	Other	7/30/2020
521	WLK1537	Running Slope > 8.33%	Driveway/Driveway Flare		T ST SW - S	Other	7/30/2020
522	WLK1537	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - S	Other	7/30/2020
523	WLK1537	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - S	Other	7/30/2020
524	WLK1537	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - S	Other	7/30/2020
525	WLK1537	No passing space			T ST SW - S	Other	7/30/2020
526	WLK1428	2% < Cross Slope < 3%	Driveway/Driveway Flare		DENNIS ST SE - N	Urban Collector	7/30/2020
527	WLK1427	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - N	Urban Collector	7/30/2020
528	WLK1427	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - N	Urban Collector	7/30/2020
529	WLK1430	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - N	Urban Collector	7/30/2020
530	WLK1432	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - S	Urban Collector	7/30/2020
531	WLK1432	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - S	Urban Collector	7/30/2020
532	WLK1432	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - S	Urban Collector	7/30/2020
533	WLK1432	Moderate Cracking			DENNIS ST SE - S	Urban Collector	7/30/2020
534	WLK1434	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS ST SE - N	Urban Collector	7/30/2020
535	WLK1434	Crack < 3/4 inch			DENNIS ST SE - N	Urban Collector	7/30/2020
536	WLK1452	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	7/30/2020
537	WLK1453	Crack < 3/4 inch			ELM ST SE - E	Urban Collector	7/30/2020
538	WLK1453	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	7/30/2020
539	WLK1453	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	7/30/2020
540	WLK1453	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	7/30/2020
541	WLK1453	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	7/30/2020
542	WLK1453	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	7/30/2020
543	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
544	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
545	WLK1462	No passing space			Z ST SE - S	Other	7/30/2020
546	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
547	WLK1462	Moderate Cracking	Settlement		Z ST SE - S	Other	7/30/2020
548	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
549	WLK1462	3% < Cross Slope < 5%			Z ST SE - S	Other	7/30/2020
550	WLK1462	No passing space			Z ST SE - S	Other	7/30/2020
551	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
552	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
553	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
554	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
555	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
556	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
557	WLK1462	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		Z ST SE - S	Other	7/30/2020
558	WLK1462	3% < Cross Slope < 5%			Z ST SE - S	Other	7/30/2020
559	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
560	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
561	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
562	WLK1462	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	7/30/2020
563	WLK1461	3% < Cross Slope < 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
564	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
565	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
566	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
567	WLK1461	3% < Cross Slope < 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
568	WLK1461	3% < Cross Slope < 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
569	WLK1461	No passing space			Z ST SE - N	Other	7/30/2020
570	WLK1461	5% < Running Slope < 8.33%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
571	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
572	WLK1461	Cross Slope > 5%	Root System		Z ST SE - N	Other	7/30/2020
573	WLK1461	Vertical displacement > 1-1/4 inch	Root System		Z ST SE - N	Other	7/30/2020
574	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
575	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
576	WLK1461	Vertical displacement < 3/4 inch	Root System		Z ST SE - N	Other	7/30/2020
577	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
578	WLK1461	No passing space			Z ST SE - N	Other	7/30/2020
579	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
580	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
581	WLK1461	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		Z ST SE - N	Other	7/30/2020
582	WLK1461	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	7/30/2020
583	WLK58	Crack < 3/4 inch	Settlement		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
584	WLK58	Vertical displacement < 3/4 inch	Root System		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
585	WLK58	3% < Cross Slope < 5%			LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
586	WLK55	3% < Cross Slope < 5%			LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
587	WLK55	FALSE		vegetation over sidewalk	LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
588	WLK54	2% < Cross Slope < 3%			LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
589	WLK53	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
590	WLK53	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
591	WLK53	Cross Slope > 5%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
592	WLK49	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
593	WLK49	Running Slope > 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
594	WLK43	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
595	WLK37	Running Slope > 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
596	WLK37	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
597	WLK33	Running Slope > 8.33%	Driveway/Driveway Flare		GLENWOOD DR SW - E	Minor Arterial	8/4/2020
598	WLK27	Running Slope > 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
599	WLK27	Vertical displacement < 3/4 inch		vault	LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
600	WLK27	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
601	WLK27	Vertical displacement < 3/4 inch		vault	LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
602	WLK10	2% < Cross Slope < 3%	Root System		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
603	WLK10	2% < Cross Slope < 3%	Root System		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
604	WLK10	Crack < 3/4 inch			LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
605	WLK10	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
606	WLK10	2% < Cross Slope < 3%	Driveway/Driveway Flare		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
607	WLK10	2% < Cross Slope < 3%			LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
608	WLK9	Minor Cracking	Root System		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
609	WLK10	Vertical displacement < 3/4 inch	Root System		LITTLE ROCK RD SW - W	Minor Arterial	8/4/2020
610	WLK9	Minor Cracking			LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
611	WLK32	Vertical displacement < 3/4 inch		vault	LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
612	WLK36	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
613	WLK36	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
614	WLK41	Vertical displacement < 3/4 inch	Root System		BISHOP RD SW - N	Minor Arterial	8/4/2020
615	WLK41	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BISHOP RD SW - N	Minor Arterial	8/4/2020
616	WLK41	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BISHOP RD SW - N	Minor Arterial	8/4/2020
617	WLK40	3% < Cross Slope < 5%	Driveway/Driveway Flare		BISHOP RD SW - N	Minor Arterial	8/4/2020
618	WLK40	Vertical displacement < 3/4 inch	Root System		BISHOP RD SW - N	Minor Arterial	8/4/2020
619	WLK39	Cross Slope > 5%	Driveway/Driveway Flare		BISHOP RD SW - S	Other	8/4/2020
620	WLK39	No passing space			BISHOP RD SW - S	Other	8/4/2020
621	WLK39	Cross Slope > 5%	Driveway/Driveway Flare		BISHOP RD SW - S	Other	8/4/2020
622	WLK42	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
623	WLK44	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
624	WLK44	Running Slope > 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
625	WLK51	3% < Cross Slope < 5%			LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
626	WLK56	5% < Running Slope < 8.33%	Driveway/Driveway Flare		LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
627	WLK56	2% < Cross Slope < 3%			LITTLE ROCK RD SW - E	Minor Arterial	8/4/2020
628	WLK20	No passing space			TYEE DR SW - W	Minor Arterial	8/4/2020
629	WLK23	3% < Cross Slope < 5%	Root System		TYEE DR SW - E	Minor Arterial	8/4/2020
630	WLK11	2% < Cross Slope < 3%			ISRAEL RD SW - S	Urban Collector	8/4/2020
631	WLK14	3% < Cross Slope < 5%			ISRAEL RD SW - S	Urban Collector	8/4/2020
632	WLK1625	2% < Cross Slope < 3%			ISRAEL RD SW - N	Urban Collector	8/4/2020
633	WLK14	No passing space			ISRAEL RD SW - S	Urban Collector	8/4/2020
634	WLK14	2% < Cross Slope < 3%			ISRAEL RD SW - S	Urban Collector	8/4/2020
644	WLK1632	Vertical displacement < 3/4 inch	Root System		LINDERSON WAY SW - W	Urban Collector	8/4/2020
645	WLK1631	2% < Cross Slope < 3%			LINDERSON WAY SW - E		8/4/2020
646	WLK1628	Cross Slope > 5%	Driveway/Driveway Flare		LINDERSON WAY SW - E		8/4/2020
648	WLK1628	Cross Slope > 5%	Driveway/Driveway Flare		LINDERSON WAY SW - E		8/4/2020
649	WLK1627	Vertical displacement < 3/4 inch	Root System		LINDERSON WAY SW - E		8/4/2020
650	WLK1627	Vertical displacement < 3/4 inch	Root System		LINDERSON WAY SW - E		8/4/2020
651	WLK1627	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		LINDERSON WAY SW - E		8/4/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
652	WLK1625	2% < Cross Slope < 3%	Root System		ISRAEL RD SW - N	Urban Collector	8/4/2020
653	WLK1625	3% < Cross Slope < 5%	Root System		ISRAEL RD SW - N	Urban Collector	8/4/2020
654	WLK1625	Minor Cracking			ISRAEL RD SW - N	Urban Collector	8/4/2020
655	WLK1438	Minor Cracking			DENNIS ST SE - S	Other	8/4/2020
656	WLK1438	2% < Cross Slope < 3%			DENNIS ST SE - S	Other	8/4/2020
657	WLK1440	No passing space			SILVER RIDGE DR SE - E	Other	8/4/2020
658	WLK1441	No passing space			SILVER RIDGE DR SE - E	Other	8/4/2020
659	WLK1441	2% < Cross Slope < 3%			SILVER RIDGE DR SE - E	Other	8/4/2020
660	WLK1444	Vertical displacement > 1-1/4 inch	Root System		SILVER RIDGE CT SE - E	Other	8/4/2020
661	WLK1444	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVER RIDGE CT SE - E	Other	8/4/2020
662	WLK1444	No passing space	Age		SILVER RIDGE CT SE - E	Other	8/4/2020
663	WLK1444	2% < Cross Slope < 3%			SILVER RIDGE CT SE - E	Other	8/4/2020
664	WLK1447	No passing space			SILVER RIDGE WAY SE - N	Other	8/4/2020
665	WLK1449	Vertical displacement < 3/4 inch			DENNIS ST SE - S	Urban Collector	8/4/2020
666	WLK1449	Cross Slope > 5%	Settlement		DENNIS ST SE - S	Urban Collector	8/4/2020
667	WLK1449	3% < Cross Slope < 5%			DENNIS ST SE - S	Urban Collector	8/4/2020
668	WLK1449	Cross Slope > 5%			DENNIS ST SE - S	Urban Collector	8/4/2020
669	WLK1449	Crack < 3/4 inch			DENNIS ST SE - S	Urban Collector	8/4/2020
670	WLK1449	Vertical displacement < 3/4 inch		vault	DENNIS ST SE - S	Urban Collector	8/4/2020
671	WLK1450	3% < Cross Slope < 5%				Other	8/4/2020
672	WLK1450	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/4/2020
673	WLK1437	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - S	Other	8/4/2020
674	WLK1437	No passing space			DENNIS CT SE - S	Other	8/4/2020
675	WLK1437	Moderate Cracking			DENNIS CT SE - S	Other	8/4/2020
676	WLK1437	Running Slope > 8.33%	Driveway/Driveway Flare		DENNIS CT SE - S	Other	8/4/2020
677	WLK1437	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - S	Other	8/4/2020
678	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
679	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
680	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
681	WLK1436	3% < Cross Slope < 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
682	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
683	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
684	WLK1436	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - N	Other	8/4/2020
685	WLK1436	No passing space			DENNIS CT SE - N	Other	8/4/2020
686	WLK1435	Moderate Cracking	Settlement		DENNIS CT SE - W	Other	8/4/2020
687	WLK1435	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - W	Other	8/4/2020
688	WLK1435	Moderate Cracking	Settlement		DENNIS CT SE - W	Other	8/4/2020
689	WLK1435	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - W	Other	8/4/2020
690	WLK1435	Cross Slope > 5%	Driveway/Driveway Flare		DENNIS CT SE - W	Other	8/4/2020
691	WLK1435	Hole < 3/4 inch			DENNIS CT SE - W	Other	8/4/2020
692	WLK1435	3% < Cross Slope < 5%			DENNIS CT SE - W	Other	8/4/2020
693	WLK1460	No passing space			Z ST SE - N	Other	8/4/2020
694	WLK1460	Vertical displacement < 3/4 inch	Root System		Z ST SE - N	Other	8/4/2020
695	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
696	WLK1460	3% < Cross Slope < 5%			Z ST SE - N	Other	8/4/2020
697	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
698	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
699	WLK1460	3% < Cross Slope < 5%			Z ST SE - N	Other	8/4/2020
700	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
701	WLK1460	Vertical displacement < 3/4 inch	Root System		Z ST SE - N	Other	8/4/2020
702	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
703	WLK1460	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
704	WLK1459	No passing space			DOE ST SE - E	Other	8/4/2020
705	WLK1458	No passing space			Z ST SE - N	Other	8/4/2020
706	WLK1458	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
707	WLK1458	3% < Cross Slope < 5%	Root System		Z ST SE - N	Other	8/4/2020
708	WLK1458	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
709	WLK1458	No passing space			Z ST SE - N	Other	8/4/2020
710	WLK1458	Cross Slope > 5%	Root System		Z ST SE - N	Other	8/4/2020
711	WLK1458	Running Slope > 8.33%	Driveway/Driveway Flare		Z ST SE - N	Other	8/4/2020
712	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
713	WLK1454	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		Z ST SE - S	Other	8/4/2020
714	WLK1454	Vertical displacement < 3/4 inch	Root System		Z ST SE - S	Other	8/4/2020
715	WLK1454	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		Z ST SE - S	Other	8/4/2020
716	WLK1454	Vertical displacement < 3/4 inch	Root System		Z ST SE - S	Other	8/4/2020
717	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
718	WLK1454	Moderate Cracking	Settlement		Z ST SE - S	Other	8/4/2020
719	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
720	WLK1454	No passing space			Z ST SE - S	Other	8/4/2020
721	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
722	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
723	WLK1454	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
724	WLK1454	Crack < 3/4 inch			Z ST SE - S	Other	8/4/2020
725	WLK1455	Cross Slope > 5%	Driveway/Driveway Flare		DOE ST SE - W	Other	8/4/2020
726	WLK1455	Vertical displacement < 3/4 inch	Settlement		DOE ST SE - W	Other	8/4/2020
727	WLK1455	Cross Slope > 5%	Driveway/Driveway Flare		DOE ST SE - W	Other	8/4/2020
728	WLK1456	Cross Slope > 5%	Driveway/Driveway Flare		DOE ST SE - E	Other	8/4/2020
729	WLK1456	Cross Slope > 5%	Driveway/Driveway Flare		DOE ST SE - E	Other	8/4/2020
730	WLK1457	No passing space			Z ST SE - S	Other	8/4/2020
731	WLK1457	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
732	WLK1457	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
733	WLK1457	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
734	WLK1457	5% < Running Slope < 8.33%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
735	WLK1457	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
736	WLK1457	Cross Slope > 5%	Driveway/Driveway Flare		Z ST SE - S	Other	8/4/2020
737	WLK1463	5% < Running Slope < 8.33%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
738	WLK1463	Running Slope > 8.33%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
739	WLK1466	Running Slope > 8.33%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
740	WLK1484	3% < Cross Slope < 5%			ELM ST SE - W	Urban Collector	8/4/2020
741	WLK1484	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
742	WLK1484	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
743	WLK1484	No passing space			ELM ST SE - W	Urban Collector	8/4/2020
744	WLK1484	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
745	WLK1484	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
746	WLK1522	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - W	Urban Collector	8/4/2020
747	WLK1522	No passing space			ELM ST SE - W	Urban Collector	8/4/2020
748	WLK1487	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	8/4/2020
749	WLK1487	Moderate Spalling	Age		ELM ST SE - E	Urban Collector	8/4/2020
750	WLK1487	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	8/4/2020
751	WLK1487	No passing space			ELM ST SE - E	Urban Collector	8/4/2020
752	WLK1465	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	8/4/2020
753	WLK1464	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	8/4/2020
754	WLK1464	Cross Slope > 5%	Driveway/Driveway Flare		ELM ST SE - E	Urban Collector	8/4/2020
755	WLK1149	No passing space			LINDA ST SE - S	Other	8/5/2020
756	WLK1149	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - S	Other	8/5/2020
757	WLK1149	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - S	Other	8/5/2020
758	WLK1149	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - S	Other	8/5/2020
759	WLK1149	Minor Cracking	Age		LINDA ST SE - S	Other	8/5/2020
760	WLK1149	No passing space			LINDA ST SE - S	Other	8/5/2020
761	WLK1149	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - S	Other	8/5/2020
762	WLK1149	Moderate Cracking	Age		LINDA ST SE - S	Other	8/5/2020
763	WLK1149	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - S	Other	8/5/2020
764	WLK1149	2% < Cross Slope < 3%			LINDA ST SE - S	Other	8/5/2020
765	WLK1148	2% < Cross Slope < 3%			LINDA ST SE - N	Other	8/5/2020
766	WLK1148	2% < Cross Slope < 3%			LINDA ST SE - N	Other	8/5/2020
767	WLK1148	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - N	Other	8/5/2020
768	WLK1148	FALSE		vegetation over sidewalk	LINDA ST SE - N	Other	8/5/2020
769	WLK1148	Cross Slope > 5%	Driveway/Driveway Flare		LINDA ST SE - N	Other	8/5/2020
770	WLK1152	3% < Cross Slope < 5%			RUBY ST SE - S	Other	8/5/2020
771	WLK1152	Crack < 3/4 inch	Age		RUBY ST SE - S	Other	8/5/2020
772	WLK1152	Crack < 3/4 inch	Age		RUBY ST SE - S	Other	8/5/2020
773	WLK1152	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - S	Other	8/5/2020
774	WLK1151	Vertical displacement < 3/4 inch	Root System		RUBY ST SE - N	Other	8/5/2020
775	WLK1152	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - S	Other	8/5/2020
776	WLK1152	Crack < 3/4 inch			RUBY ST SE - S	Other	8/5/2020
777	WLK1152	No passing space			RUBY ST SE - S	Other	8/5/2020
778	WLK1152	3% < Cross Slope < 5%	Root System		RUBY ST SE - S	Other	8/5/2020
779	WLK1152	Crack < 3/4 inch	Root System		RUBY ST SE - S	Other	8/5/2020
780	WLK1152	Vertical displacement > 1-1/4 inch	Root System		RUBY ST SE - S	Other	8/5/2020
781	WLK1152	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - S	Other	8/5/2020
782	WLK1153	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	8/5/2020
783	WLK1151	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - N	Other	8/5/2020
784	WLK1151	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - N	Other	8/5/2020
785	WLK1151	No passing space			RUBY ST SE - N	Other	8/5/2020
786	WLK1151	Crack < 3/4 inch	Age		RUBY ST SE - N	Other	8/5/2020
787	WLK1151	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - N	Other	8/5/2020
788	WLK1151	3% < Cross Slope < 5%	Age		RUBY ST SE - N	Other	8/5/2020
789	WLK1151	Cross Slope > 5%	Driveway/Driveway Flare		RUBY ST SE - N	Other	8/5/2020
790	WLK1531	3% < Cross Slope < 5%			LEE ST SE - S	Urban Collector	8/5/2020
791	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
792	WLK1531	3% < Cross Slope < 5%			LEE ST SE - S	Urban Collector	8/5/2020
793	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
794	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
795	WLK1531	No passing space			LEE ST SE - S	Urban Collector	8/5/2020
796	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
797	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
798	WLK1531	Crack < 3/4 inch	Settlement		LEE ST SE - S	Urban Collector	8/5/2020
799	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
800	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
801	WLK1531	Running Slope > 8.33%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
802	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
803	WLK1531	3% < Cross Slope < 5%			LEE ST SE - S	Urban Collector	8/5/2020
804	WLK1531	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - S	Urban Collector	8/5/2020
805	WLK1531	3% < Cross Slope < 5%			LEE ST SE - S	Urban Collector	8/5/2020
806	WLK1529	Cross Slope > 5%	Driveway/Driveway Flare		BOSTON ST SE - E	Urban Collector	8/5/2020
807	WLK1529	No passing space			BOSTON ST SE - E	Urban Collector	8/5/2020
808	WLK1529	Cross Slope > 5%	Driveway/Driveway Flare		BOSTON ST SE - E	Urban Collector	8/5/2020
809	WLK1529	Cross Slope > 5%	Driveway/Driveway Flare		BOSTON ST SE - E	Urban Collector	8/5/2020
810	WLK1529	Cross Slope > 5%	Driveway/Driveway Flare		BOSTON ST SE - E	Urban Collector	8/5/2020
811	WLK1530	Minor Cracking	Settlement		LEE ST SE - N	Urban Collector	8/5/2020
812	WLK1530	Running Slope > 8.33%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
813	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
814	WLK1530	No passing space			LEE ST SE - N	Urban Collector	8/5/2020
815	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
816	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
817	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
818	WLK1530	Crack < 3/4 inch	Age		LEE ST SE - N	Urban Collector	8/5/2020
819	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
820	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
821	WLK1530	No passing space			LEE ST SE - N	Urban Collector	8/5/2020
822	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
823	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
824	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
825	WLK1530	Cross Slope > 5%	Driveway/Driveway Flare		LEE ST SE - N	Urban Collector	8/5/2020
826	WLK1530	Moderate Cracking	Settlement		LEE ST SE - N	Urban Collector	8/5/2020
827	WLK1530	Crack < 3/4 inch	Settlement		LEE ST SE - N	Urban Collector	8/5/2020
828	WLK1530	Crack between 3/4 inch and 1-1/4 inch	Root System		LEE ST SE - N	Urban Collector	8/5/2020
829	WLK1530	Minor Cracking	Settlement		LEE ST SE - N	Urban Collector	8/5/2020
830	WLK1530	Crack < 3/4 inch	Age		LEE ST SE - N	Urban Collector	8/5/2020
831	WLK1528	2% < Cross Slope < 3%			HILLCREST DR SE - N	Other	8/5/2020
832	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
833	WLK1528	No passing space			HILLCREST DR SE - N	Other	8/5/2020
834	WLK1528	Crack < 3/4 inch	Age		HILLCREST DR SE - N	Other	8/5/2020
835	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
836	WLK1528	Hole > 1-1/4 inch			HILLCREST DR SE - N	Other	8/5/2020
837	WLK1528	3% < Cross Slope < 5%	Root System		HILLCREST DR SE - N	Other	8/5/2020
838	WLK1528	Cross Slope > 5%	Root System		HILLCREST DR SE - N	Other	8/5/2020
839	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
840	WLK1528	Crack between 3/4 inch and 1-1/4 inch	Root System		HILLCREST DR SE - N	Other	8/5/2020
841	WLK1528	No passing space			HILLCREST DR SE - N	Other	8/5/2020
842	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
843	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
844	WLK1528	No passing space			HILLCREST DR SE - N	Other	8/5/2020
845	WLK1528	Severe Cracking	Root System		HILLCREST DR SE - N	Other	8/5/2020
846	WLK1528	Running Slope > 8.33%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
847	WLK1528	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - N	Other	8/5/2020
848	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
849	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
850	WLK1527	Crack < 3/4 inch	Root System		HILLCREST DR SE - S	Other	8/5/2020
851	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
852	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
853	WLK1527	Crack < 3/4 inch	Root System		HILLCREST DR SE - S	Other	8/5/2020
854	WLK1527	Running Slope > 8.33%	Driveway/Driveway Flare	very steep	HILLCREST DR SE - S	Other	8/5/2020
855	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
856	WLK1527	Cross Slope > 5%	Driveway/Driveway Flare		HILLCREST DR SE - S	Other	8/5/2020
857	WLK1527	Vertical displacement < 3/4 inch	Settlement		HILLCREST DR SE - S	Other	8/5/2020
858	WLK1526	Cross Slope > 5%	Driveway/Driveway Flare		HIXON DR SE - E	Other	8/5/2020
859	WLK1523	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - S	Other	8/5/2020
860	WLK1523	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - S	Other	8/5/2020
861	WLK1523	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - S	Other	8/5/2020
862	WLK1523	No passing space			HAZELHURST DR SE - S	Other	8/5/2020
863	WLK1523	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - S	Other	8/5/2020
864	WLK1524	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - N	Urban Collector	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
865	WLK1524	No passing space			HAZELHURST DR SE - N	Urban Collector	8/5/2020
866	WLK1524	Cross Slope > 5%	Driveway/Driveway Flare		HAZELHURST DR SE - N	Urban Collector	8/5/2020
867	WLK1510	5% < Running Slope < 8.33%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
868	WLK1510	Vertical displacement < 3/4 inch	Settlement		T ST SE - S	Other	8/5/2020
869	WLK1510	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
870	WLK1510	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
871	WLK1510	Cross Slope > 5%	Settlement		T ST SE - S	Other	8/5/2020
872	WLK1510	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		T ST SE - S	Other	8/5/2020
873	WLK1510	Cross Slope > 5%	Root System		T ST SE - S	Other	8/5/2020
874	WLK1510	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
875	WLK1509	No passing space			BELL ST SE - W	Other	8/5/2020
876	WLK1509	Cross Slope > 5%	Driveway/Driveway Flare		BELL ST SE - W	Other	8/5/2020
877	WLK1509	Cross Slope > 5%	Driveway/Driveway Flare		BELL ST SE - W	Other	8/5/2020
878	WLK1509	Cross Slope > 5%	Driveway/Driveway Flare		BELL ST SE - W	Other	8/5/2020
879	WLK1508	Cross Slope > 5%	Driveway/Driveway Flare		BELL ST SE - W	Other	8/5/2020
880	WLK1506	Cross Slope > 5%	Settlement		T ST SE - S	Other	8/5/2020
881	WLK1506	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
882	WLK1506	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
883	WLK1506	No passing space			T ST SE - S	Other	8/5/2020
884	WLK1506	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
885	WLK1506	3% < Cross Slope < 5%	Settlement		T ST SE - S	Other	8/5/2020
886	WLK1504	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
887	WLK1504	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
888	WLK1504	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
889	WLK1504	2% < Cross Slope < 3%	Settlement		T ST SE - S	Other	8/5/2020
890	WLK1504	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
891	WLK1504	3% < Cross Slope < 5%	Settlement		T ST SE - S	Other	8/5/2020
892	WLK1504	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
893	WLK1502	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
894	WLK1502	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - S	Other	8/5/2020
895	WLK1500	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
896	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
897	WLK1500	Minor Cracking	Root System		T ST SE - S	Other	8/5/2020
898	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
899	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
900	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
901	WLK1500	Vertical displacement > 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
902	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
903	WLK1500	Vertical displacement > 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
904	WLK1500	Vertical displacement < 3/4 inch	Root System		T ST SE - S	Other	8/5/2020
905	WLK1499	Vertical displacement > 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
906	WLK1499	Vertical displacement > 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
907	WLK1499	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
908	WLK1499	Vertical displacement > 1-1/4 inch	Root System		T ST SE - S	Other	8/5/2020
909	WLK1498	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
910	WLK1498	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
911	WLK1498	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - E	Other	8/5/2020
912	WLK1498	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
913	WLK1498	Crack < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
914	WLK1498	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - E	Other	8/5/2020
915	WLK1498	Running Slope > 8.33%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
916	WLK1501	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - E	Other	8/5/2020
917	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
918	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
919	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
920	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
921	WLK1501	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		T ST SE - E	Other	8/5/2020
922	WLK1501	Vertical displacement > 1-1/4 inch	Root System		T ST SE - E	Other	8/5/2020
923	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
924	WLK1501	Vertical displacement < 3/4 inch	Root System		T ST SE - E	Other	8/5/2020
925	WLK1501	5% < Running Slope < 8.33%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
926	WLK1505	5% < Running Slope < 8.33%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
927	WLK1505	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
928	WLK1505	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
929	WLK1505	5% < Running Slope < 8.33%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
930	WLK1505	5% < Running Slope < 8.33%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
931	WLK1505	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
932	WLK1507	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
933	WLK1507	Crack < 3/4 inch	Age		T ST SE - E	Other	8/5/2020
934	WLK1507	Crack < 3/4 inch	Age		T ST SE - E	Other	8/5/2020
935	WLK1507	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
936	WLK1507	3% < Cross Slope < 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
937	WLK1511	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
938	WLK1511	Vertical displacement < 3/4 inch	Settlement		T ST SE - E	Other	8/5/2020
939	WLK1511	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
940	WLK1511	Cross Slope > 5%	Driveway/Driveway Flare		T ST SE - E	Other	8/5/2020
941	WLK1511	No passing space			T ST SE - E	Other	8/5/2020
942	WLK1490	Cross Slope > 5%	Driveway/Driveway Flare		V ST SE - N	Other	8/5/2020
943	WLK1490	Cross Slope > 5%	Driveway/Driveway Flare		V ST SE - N	Other	8/5/2020
944	WLK1490	No passing space			V ST SE - N	Other	8/5/2020
945	WLK1491	No passing space			V ST SE - N	Other	8/5/2020
946	WLK1492	No passing space			V ST SE - N	Other	8/5/2020
947	WLK1492	3% < Cross Slope < 5%			V ST SE - N	Other	8/5/2020
948	WLK1492	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		V ST SE - N	Other	8/5/2020
949	WLK1497	Running Slope > 8.33%			V ST SE - N	Other	8/5/2020
950	WLK1489	Cross Slope > 5%	Driveway/Driveway Flare		V ST SE - S	Other	8/5/2020
951	WLK1489	Cross Slope > 5%	Driveway/Driveway Flare		V ST SE - S	Other	8/5/2020
952	WLK1489	Cross Slope > 5%	Driveway/Driveway Flare		V ST SE - S	Other	8/5/2020
953	WLK1521	No passing space			PINEHURST DR SE - N	Other	8/5/2020
954	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
955	WLK1520	Crack < 3/4 inch	Age		PINEHURST DR SE - S	Other	8/5/2020
956	WLK1520	Crack < 3/4 inch			PINEHURST DR SE - S	Other	8/5/2020
957	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
958	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
959	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
960	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
961	WLK1520	Crack < 3/4 inch	Age		PINEHURST DR SE - S	Other	8/5/2020
962	WLK1520	Crack < 3/4 inch	Age		PINEHURST DR SE - S	Other	8/5/2020
963	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
964	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
965	WLK1520	Crack < 3/4 inch	Age		PINEHURST DR SE - S	Other	8/5/2020
966	WLK1520	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		PINEHURST DR SE - S	Other	8/5/2020
967	WLK1520	3% < Cross Slope < 5%	Root System		PINEHURST DR SE - S	Other	8/5/2020
968	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
969	WLK1520	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		PINEHURST DR SE - S	Other	8/5/2020
970	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
971	WLK1520	200' < Passing Space < 400'			PINEHURST DR SE - S	Other	8/5/2020
972	WLK1520	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - S	Other	8/5/2020
973	WLK1520	Vertical displacement > 1-1/4 inch	Root System		PINEHURST DR SE - S	Other	8/5/2020
974	WLK1520	Cross Slope > 5%	Root System		PINEHURST DR SE - S	Other	8/5/2020
975	WLK1519	Cross Slope > 5%	Root System		MARGO PL SE - E	Other	8/5/2020
976	WLK1519	Cross Slope > 5%	Root System		MARGO PL SE - E	Other	8/5/2020
977	WLK1519	Cross Slope > 5%	Driveway/Driveway Flare		MARGO PL SE - E	Other	8/5/2020
978	WLK1519	Vertical displacement < 3/4 inch	Root System		MARGO PL SE - E	Other	8/5/2020
979	WLK1516	No passing space			MARGO PL SE - E	Other	8/5/2020
980	WLK1516	Cross Slope > 5%	Driveway/Driveway Flare		MARGO PL SE - E	Other	8/5/2020
981	WLK1515	3% < Cross Slope < 5%	Root System		LAURELHURST DR SE - N	Other	8/5/2020
982	WLK1515	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
983	WLK1515	Minor Cracking	Age		LAURELHURST DR SE - N	Other	8/5/2020
984	WLK1515	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
985	WLK1515	Crack < 3/4 inch	Root System		LAURELHURST DR SE - N	Other	8/5/2020
986	WLK1515	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
987	WLK1515	No passing space			LAURELHURST DR SE - N	Other	8/5/2020
988	WLK1514	Crack < 3/4 inch	Age		LAURELHURST DR SE - N	Other	8/5/2020
989	WLK1514	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
990	WLK1514	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
991	WLK1514	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
992	WLK1514	Vertical displacement < 3/4 inch	Settlement		LAURELHURST DR SE - N	Other	8/5/2020
993	WLK1514	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
994	WLK1514	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - N	Other	8/5/2020
995	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
996	WLK1512	Crack < 3/4 inch	Age		LAURELHURST DR SE - S	Other	8/5/2020
997	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
998	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
999	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1000	WLK1512	Crack between 3/4 inch and 1-1/4 inch	Age		LAURELHURST DR SE - S	Other	8/5/2020
1001	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1002	WLK1512	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1003	WLK1513	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1004	WLK1513	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1005	WLK1513	Cross Slope > 5%	Driveway/Driveway Flare		LAURELHURST DR SE - S	Other	8/5/2020
1006	WLK1513	Crack < 3/4 inch	Age		LAURELHURST DR SE - S	Other	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1007	WLK1513	3% < Cross Slope < 5%	Settlement		LAURELHURST DR SE - S	Other	8/5/2020
1008	WLK1517	Cross Slope > 5%	Driveway/Driveway Flare		U ST SE - S	Other	8/5/2020
1009	WLK1517	3% < Cross Slope < 5%	Settlement		U ST SE - S	Other	8/5/2020
1010	WLK1517	Cross Slope > 5%	Driveway/Driveway Flare		U ST SE - S	Other	8/5/2020
1011	WLK1518	3% < Cross Slope < 5%	Age		U ST SE - N	Other	8/5/2020
1012	WLK1518	Cross Slope > 5%	Driveway/Driveway Flare		U ST SE - N	Other	8/5/2020
1013	WLK1518	Cross Slope > 5%	Driveway/Driveway Flare		U ST SE - N	Other	8/5/2020
1014	WLK1518	No passing space			U ST SE - N	Other	8/5/2020
1016	WLK1521	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - N	Other	8/5/2020
1017	WLK1521	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - N	Other	8/5/2020
1018	WLK1521	No passing space			PINEHURST DR SE - N	Other	8/5/2020
1019	WLK1521	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - N	Other	8/5/2020
1020	WLK1521	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - N	Other	8/5/2020
1021	WLK1521	Crack < 3/4 inch	Age		PINEHURST DR SE - N	Other	8/5/2020
1022	WLK1521	Cross Slope > 5%	Driveway/Driveway Flare		PINEHURST DR SE - N	Other	8/5/2020
1023	WLK1471	No passing space			BOSTON ST SE - W	Other	8/5/2020
1024	WLK1471	Crack < 3/4 inch	Age		BOSTON ST SE - W	Other	8/5/2020
1025	WLK1471	Crack between 3/4 inch and 1-1/4 inch	Age		BOSTON ST SE - W	Other	8/5/2020
1026	WLK1471	Crack < 3/4 inch	Age		BOSTON ST SE - W	Other	8/5/2020
1027	WLK1471	Crack < 3/4 inch	Age		BOSTON ST SE - W	Other	8/5/2020
1028	WLK1467	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1029	WLK1485	Vertical displacement < 3/4 inch	Root System		W ST SE - S	Other	8/5/2020
1030	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1031	WLK1485	No passing space			W ST SE - S	Other	8/5/2020
1032	WLK1485	Crack < 3/4 inch	Age		W ST SE - S	Other	8/5/2020
1033	WLK1485	3% < Cross Slope < 5%			W ST SE - S	Other	8/5/2020
1034	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1035	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1036	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1037	WLK1485	3% < Cross Slope < 5%	Settlement		W ST SE - S	Other	8/5/2020
1038	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1039	WLK1486	No passing space			W ST SE - N	Other	8/5/2020
1040	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1041	WLK1486	Vertical displacement > 1-1/4 inch	Root System		W ST SE - N	Other	8/5/2020
1042	WLK1486	Vertical displacement > 1-1/4 inch	Root System		W ST SE - N	Other	8/5/2020
1043	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1044	WLK1486	Cross Slope > 5%	Root System		W ST SE - N	Other	8/5/2020
1045	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1046	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1047	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1048	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1049	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1050	WLK1486	3% < Cross Slope < 5%			W ST SE - N	Other	8/5/2020
1051	WLK1486	3% < Cross Slope < 5%			W ST SE - N	Other	8/5/2020
1052	WLK1486	Minor Cracking	Settlement		W ST SE - N	Other	8/5/2020
1053	WLK1486	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - N	Other	8/5/2020
1054	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1055	WLK1485	Crack < 3/4 inch	Root System		W ST SE - S	Other	8/5/2020
1056	WLK1485	Crack < 3/4 inch	Age		W ST SE - S	Other	8/5/2020
1057	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1058	WLK1485	Crack < 3/4 inch	Age		W ST SE - S	Other	8/5/2020
1059	WLK1485	Cross Slope > 5%	Driveway/Driveway Flare		W ST SE - S	Other	8/5/2020
1060	WLK1479	Minor Cracking	Root System		X ST SE - N	Other	8/5/2020
1061	WLK1475	Cross Slope > 5%			X ST SE - S	Other	8/5/2020
1062	WLK1475	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1063	WLK1475	3% < Cross Slope < 5%			X ST SE - S	Other	8/5/2020
1064	WLK1475	Vertical displacement < 3/4 inch	Root System		X ST SE - S	Other	8/5/2020
1065	WLK1475	Cross Slope > 5%	Root System		X ST SE - S	Other	8/5/2020
1066	WLK1475	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		X ST SE - S	Other	8/5/2020
1067	WLK1475	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1068	WLK1475	No passing space			X ST SE - S	Other	8/5/2020
1069	WLK1474	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1070	WLK1474	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1071	WLK1473	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1072	WLK1473	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1073	WLK1473	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1074	WLK1473	Crack < 3/4 inch	Root System		X ST SE - S	Other	8/5/2020
1075	WLK1473	Crack < 3/4 inch	Age		X ST SE - S	Other	8/5/2020
1076	WLK1473	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1077	WLK1473	Crack < 3/4 inch	Age		X ST SE - S	Other	8/5/2020
1078	WLK1473	Vertical displacement < 3/4 inch	Settlement		X ST SE - S	Other	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1079	WLK1473	Minor Cracking	Settlement		X ST SE - S	Other	8/5/2020
1080	WLK1473	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1081	WLK1473	No passing space			X ST SE - S	Other	8/5/2020
1082	WLK1470	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1083	WLK1470	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1084	WLK1470	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1085	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1086	WLK1470	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		Y ST SE - N	Other	8/5/2020
1087	WLK1470	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1088	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1089	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1090	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1091	WLK1470	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1092	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1093	WLK1467	3% < Cross Slope < 5%			Y ST SE - N	Other	8/5/2020
1094	WLK1467	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1095	WLK1467	Moderate Spalling	Age		Y ST SE - N	Other	8/5/2020
1096	WLK1467	Moderate Spalling	Age		Y ST SE - N	Other	8/5/2020
1097	WLK1467	Crack between 3/4 inch and 1-1/4 inch	Age		Y ST SE - N	Other	8/5/2020
1098	WLK1467	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1099	WLK1467	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1100	WLK1467	No passing space			Y ST SE - N	Other	8/5/2020
1101	WLK1467	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1102	WLK1467	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - N	Other	8/5/2020
1103	WLK1467	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1104	WLK1467	Crack between 3/4 inch and 1-1/4 inch	Age		Y ST SE - N	Other	8/5/2020
1105	WLK1467	Crack between 3/4 inch and 1-1/4 inch	Age		Y ST SE - N	Other	8/5/2020
1106	WLK1467	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1107	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1108	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1109	WLK1468	Vertical displacement < 3/4 inch	Root System		Y ST SE - S	Other	8/5/2020
1110	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1111	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1112	WLK1468	No passing space			Y ST SE - S	Other	8/5/2020
1113	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1114	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1115	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1116	WLK1468	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1117	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1118	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1119	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1120	WLK1468	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1121	WLK1469	Crack < 3/4 inch	Age		Y ST SE - S	Other	8/5/2020
1122	WLK1469	Minor Spalling	Age		Y ST SE - S	Other	8/5/2020
1123	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1124	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1125	WLK1469	No passing space			Y ST SE - S	Other	8/5/2020
1126	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1127	WLK1470	Crack < 3/4 inch	Age		Y ST SE - N	Other	8/5/2020
1128	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1129	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1130	WLK1469	Cross Slope > 5%	Driveway/Driveway Flare		Y ST SE - S	Other	8/5/2020
1131	WLK1472	Cross Slope > 5%			X ST SE - S	Other	8/5/2020
1132	WLK1472	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/5/2020
1133	WLK1476	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1134	WLK1476	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1135	WLK1476	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1136	WLK1476	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1137	WLK1476	No passing space			X ST SE - N	Other	8/5/2020
1138	WLK1477	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1139	WLK1477	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1140	WLK1477	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1141	WLK1477	Crack < 3/4 inch	Age		X ST SE - N	Other	8/5/2020
1142	WLK1477	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1143	WLK1477	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1144	WLK1477	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1145	WLK1477	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1146	WLK1478	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1147	WLK1478	3% < Cross Slope < 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1148	WLK1478	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1149	WLK1479	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1150	WLK1479	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/5/2020
1151	WLK1479	Crack < 3/4 inch	Age		X ST SE - N	Other	8/5/2020
1152	WLK1605	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		6TH AVE SW - W	Other	8/5/2020
1153	WLK1605	Vertical displacement > 1-1/4 inch	Root System		6TH AVE SW - W	Other	8/5/2020
1154	WLK1605	Vertical displacement > 1-1/4 inch	Root System		6TH AVE SW - W	Other	8/5/2020
1155	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1156	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1157	WLK1605	No passing space			6TH AVE SW - W	Other	8/5/2020
1158	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1159	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1160	WLK1605	3% < Cross Slope < 5%			6TH AVE SW - W	Other	8/5/2020
1161	WLK1605	3% < Cross Slope < 5%	Root System		6TH AVE SW - W	Other	8/5/2020
1162	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1163	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1164	WLK1605	Minor Cracking	Settlement		6TH AVE SW - W	Other	8/5/2020
1165	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1166	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1167	WLK1605	3% < Cross Slope < 5%	Root System		6TH AVE SW - W	Other	8/5/2020
1168	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1169	WLK1605	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/5/2020
1170	WLK1605	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/5/2020
1171	WLK1605	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/5/2020
1172	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1173	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1174	WLK1605	Crack < 3/4 inch	Root System		6TH AVE SW - W	Other	8/5/2020
1175	WLK1605	Minor Cracking	Settlement		6TH AVE SW - W	Other	8/5/2020
1176	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1177	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1178	WLK1605	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/5/2020
1179	WLK1605	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/5/2020
1180	WLK1606	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/5/2020
1181	WLK1606	Running Slope > 8.33%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1182	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1183	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1184	WLK1606	No passing space			6TH AVE SW - E	Other	8/5/2020
1185	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1186	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1187	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1188	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1189	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1190	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1191	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1192	WLK1606	Cross Slope > 5%	Root System		6TH AVE SW - E	Other	8/5/2020
1193	WLK1606	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/5/2020
1194	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1195	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1196	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1197	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1198	WLK1606	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/5/2020
1199	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1200	WLK1480	Minor Cracking	Age		X ST SE - S	Other	8/6/2020
1202	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1203	WLK1480	Crack < 3/4 inch	Age		X ST SE - S	Other	8/6/2020
1204	WLK1480	Crack < 3/4 inch	Age		X ST SE - S	Other	8/6/2020
1205	WLK1480	2% < Cross Slope < 3%			X ST SE - S	Other	8/6/2020
1206	WLK1480	Minor Cracking	Age		X ST SE - S	Other	8/6/2020
1208	WLK1480	No passing space			X ST SE - S	Other	8/6/2020
1209	WLK1480	3% < Cross Slope < 5%			X ST SE - S	Other	8/6/2020
1210	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1211	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1212	WLK1480	3% < Cross Slope < 5%			X ST SE - S	Other	8/6/2020
1213	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1214	WLK1480	Minor Cracking	Settlement		X ST SE - S	Other	8/6/2020
1215	WLK1480	Vertical displacement < 3/4 inch			X ST SE - S	Other	8/6/2020
1216	WLK1480	Crack < 3/4 inch	Age		X ST SE - S	Other	8/6/2020
1217	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1218	WLK1480	3% < Cross Slope < 5%			X ST SE - S	Other	8/6/2020
1219	WLK1480	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - S	Other	8/6/2020
1220	WLK1480	No passing space			X ST SE - S	Other	8/6/2020
1221	WLK1481	Crack < 3/4 inch	Root System		ONYX CT SE - N	Other	8/6/2020
1222	WLK1481	Moderate Cracking	Age		ONYX CT SE - N	Other	8/6/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1223	WLK1482	5% < Running Slope < 8.33%	Root System		ONYX CT SE - N	Other	8/6/2020
1224	WLK1482	Vertical displacement > 1-1/4 inch	Root System		ONYX CT SE - N	Other	8/6/2020
1225	WLK1482	Vertical displacement > 1-1/4 inch	Root System		ONYX CT SE - N	Other	8/6/2020
1226	WLK1482	Vertical displacement < 3/4 inch	Root System		ONYX CT SE - N	Other	8/6/2020
1227	WLK1482	No passing space			ONYX CT SE - N	Other	8/6/2020
1228	WLK1482	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ONYX CT SE - N	Other	8/6/2020
1229	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1230	WLK1483	Crack < 3/4 inch	Age		X ST SE - N	Other	8/6/2020
1231	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1232	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1233	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1234	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1235	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1236	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1237	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1238	WLK1483	Crack < 3/4 inch	Age		X ST SE - N	Other	8/6/2020
1239	WLK1483	Cross Slope > 5%	Driveway/Driveway Flare		X ST SE - N	Other	8/6/2020
1240	WLK1423	3% < Cross Slope < 5%	Root System		BONNIEWOOD DR SE - W	Other	8/6/2020
1241	WLK1423	3% < Cross Slope < 5%	Root System		BONNIEWOOD DR SE - W	Other	8/6/2020
1242	WLK1423	3% < Cross Slope < 5%	Root System		BONNIEWOOD DR SE - W	Other	8/6/2020
1243	WLK1423	Crack < 3/4 inch	Settlement		BONNIEWOOD DR SE - W	Other	8/6/2020
1244	WLK1423	Vertical displacement > 1-1/4 inch	Root System		BONNIEWOOD DR SE - W	Other	8/6/2020
1245	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1246	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1247	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1248	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1249	WLK1420	Running Slope > 8.33%	Driveway/Driveway Flare		SCOTT ST SE - N	Other	8/6/2020
1250	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1252	WLK1420	No passing space			SCOTT ST SE - N	Other	8/6/2020
1253	WLK1420	Crack < 3/4 inch	Age		SCOTT ST SE - N	Other	8/6/2020
1254	WLK1420	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - N	Other	8/6/2020
1255	WLK1420	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - N	Other	8/6/2020
1256	WLK1419	Minor Cracking	Settlement		SCOTT ST SE - S	Other	8/6/2020
1257	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1258	WLK1419	3% < Cross Slope < 5%			SCOTT ST SE - S	Other	8/6/2020
1259	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1260	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1261	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1262	WLK1419	Crack < 3/4 inch	Age		SCOTT ST SE - S	Other	8/6/2020
1263	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1264	WLK1419	Cross Slope > 5%	Root System		SCOTT ST SE - S	Other	8/6/2020
1265	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1266	WLK1419	Cross Slope > 5%	Driveway/Driveway Flare		SCOTT ST SE - S	Other	8/6/2020
1267	WLK1419	Crack < 3/4 inch	Age		SCOTT ST SE - S	Other	8/6/2020
1268	WLK1419	Crack < 3/4 inch	Age		SCOTT ST SE - S	Other	8/6/2020
1269	WLK1418	3% < Cross Slope < 5%			BONNIEWOOD DR SE - W	Other	8/6/2020
1270	WLK1418	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - W	Other	8/6/2020
1271	WLK1418	3% < Cross Slope < 5%			BONNIEWOOD DR SE - W	Other	8/6/2020
1272	WLK1417	Cross Slope > 5%	Driveway/Driveway Flare		ISRAEL RD SE - N	Urban Collector	8/6/2020
1273	WLK1417	Minor Cracking	Settlement		ISRAEL RD SE - N	Urban Collector	8/6/2020
1274	WLK1417	3% < Cross Slope < 5%			ISRAEL RD SE - N	Urban Collector	8/6/2020
1275	WLK1416	Crack < 3/4 inch			ISRAEL RD SE - N	Urban Collector	8/6/2020
1276	WLK1416	Crack between 3/4 inch and 1-1/4 inch			ISRAEL RD SE - N	Urban Collector	8/6/2020
1277	WLK1416	Cross Slope > 5%	Driveway/Driveway Flare		ISRAEL RD SE - N	Urban Collector	8/6/2020
1278	WLK1416	Cross Slope > 5%	Root System		ISRAEL RD SE - N	Urban Collector	8/6/2020
1279	WLK1416	Cross Slope > 5%	Driveway/Driveway Flare		ISRAEL RD SE - N	Urban Collector	8/6/2020
1280	WLK1416	Cross Slope > 5%	Driveway/Driveway Flare		ISRAEL RD SE - N	Urban Collector	8/6/2020
1281	WLK1415	Crack < 3/4 inch	Root System		ISRAEL RD SE - S	Urban Collector	8/6/2020
1282	WLK1415	Crack between 3/4 inch and 1-1/4 inch	Root System		ISRAEL RD SE - S	Urban Collector	8/6/2020
1283	WLK1416	Crack between 3/4 inch and 1-1/4 inch	Root System		ISRAEL RD SE - N	Urban Collector	8/6/2020
1284	WLK1416	Vertical displacement is in the vicinity of a sensitive location	Root System		ISRAEL RD SE - N	Urban Collector	8/6/2020
1285	WLK1414	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		NIKOLAS ST SE - W	Other	8/6/2020
1286	WLK1421	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1287	WLK1421	3% < Cross Slope < 5%	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1288	WLK1421	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1289	WLK1421	No passing space			BONNIEWOOD DR SE - E	Other	8/6/2020
1290	WLK1421	Crack < 3/4 inch	Age		BONNIEWOOD DR SE - E	Other	8/6/2020
1291	WLK1421	Running Slope > 8.33%	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1292	WLK1421	Crack < 3/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1293	WLK1421	Crack < 3/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1294	WLK1421	Cross Slope > 5%	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1295	WLK1421	Minor Cracking			BONNIEWOOD DR SE - E	Other	8/6/2020
1296	WLK1421	Running Slope > 8.33%	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1297	WLK1421	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1298	WLK1421	Cross Slope > 5%	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1299	WLK1421	No passing space			BONNIEWOOD DR SE - E	Other	8/6/2020
1300	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1301	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1302	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1303	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1304	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1305	WLK1422	Vertical displacement < 3/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1306	WLK1422	No passing space			BONNIEWOOD DR SE - E	Other	8/6/2020
1307	WLK1422	Crack < 3/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1308	WLK1422	Vertical displacement < 3/4 inch	Root System		BONNIEWOOD DR SE - E	Other	8/6/2020
1309	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1310	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1311	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1312	WLK1422	Cross Slope > 5%	Driveway/Driveway Flare		BONNIEWOOD DR SE - E	Other	8/6/2020
1313	WLK1654	Vertical displacement < 3/4 inch	Root System		CLEANWATER LN SW - E	Other	8/6/2020
1314	WLK1649	Vertical displacement < 3/4 inch	Root System		CLEANWATER LN SW - E	Other	8/6/2020
1315	WLK1650	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1316	WLK1650	Vertical displacement > 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1317	WLK1650	Vertical displacement > 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1318	WLK1653	Vertical displacement > 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1319	WLK1653	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1320	WLK1653	Vertical displacement > 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1321	WLK1653	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1322	WLK1653	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLEANWATER DR SW - W		8/6/2020
1323	WLK1646	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1324	WLK1646	Crack < 3/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1325	WLK1646	5% < Running Slope < 8.33%	Driveway/Driveway Flare		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1326	WLK1646	Vertical displacement > 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1327	WLK1646	5% < Running Slope < 8.33%	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1328	WLK1646	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1329	WLK1646	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1330	WLK1644	Crack < 3/4 inch	Settlement		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1331	WLK1641	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1332	WLK1640	5% < Running Slope < 8.33%	Driveway/Driveway Flare		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1333	WLK1640	Minor Cracking	Settlement		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1334	WLK1637	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1335	WLK1638	2% < Cross Slope < 3%			TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1336	WLK1639	Minor Cracking	Settlement		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1337	WLK1639	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1338	WLK1643	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1339	WLK1643	Cross Slope > 5%	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1340	WLK1645	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1341	WLK1645	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1342	WLK1645	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1343	WLK1645	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1344	WLK1645	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1345	WLK1645	Crack < 3/4 inch	Settlement		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1346	WLK1647	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1347	WLK1647	Crack between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1348	WLK1647	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1349	WLK1647	5% < Running Slope < 8.33%	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1350	WLK1647	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SW - S	Principal Arterial	8/6/2020
1351	WLK1648	Vertical displacement > 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1352	WLK1648	Vertical displacement > 1-1/4 inch	Root System		TUMWATER BLVD SW - N	Principal Arterial	8/6/2020
1353	WLK1413	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SE - N	Minor Arterial	8/6/2020
1354	WLK1413	3% < Cross Slope < 5%	Root System		TUMWATER BLVD SE - N	Minor Arterial	8/6/2020
1355	WLK1413	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - N	Minor Arterial	8/6/2020
1356	WLK1413	Cross Slope > 5%	Root System		TUMWATER BLVD SE - N	Minor Arterial	8/6/2020
1357	WLK1411	2% < Cross Slope < 3%			TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1358	WLK1411	Crack between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1359	WLK1411	5% < Running Slope < 8.33%	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1360	WLK1411	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1361	WLK1411	Running Slope > 8.33%	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1362	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1363	WLK1411	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1364	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1365	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1366	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1367	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1368	WLK1411	Vertical displacement < 3/4 inch	Root System		TUMWATER BLVD SE - S	Minor Arterial	8/6/2020
1369	WLK1413	200' < Passing Space < 400'			TUMWATER BLVD SE - N	Minor Arterial	8/6/2020
1370	WLK1409	No passing space			72ND AVE SE - N	Other	8/6/2020
1371	WLK1409	Cross Slope > 5%	Driveway/Driveway Flare		72ND AVE SE - N	Other	8/6/2020
1372	WLK1410	Cross Slope > 5%	Driveway/Driveway Flare		72ND AVE SE - N	Other	8/6/2020
1373	WLK1410	Cross Slope > 5%	Driveway/Driveway Flare		72ND AVE SE - N	Other	8/6/2020
1374	WLK1325	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1375	WLK1324	Running Slope > 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1376	WLK1324	Crack < 3/4 inch	Age		RIVER DR SE - W	Other	8/7/2020
1377	WLK1324	2% < Cross Slope < 3%	Root System		RIVER DR SE - W	Other	8/7/2020
1378	WLK1324	Minor Cracking	Root System		RIVER DR SE - W	Other	8/7/2020
1379	WLK1324	Crack < 3/4 inch	Age		RIVER DR SE - W	Other	8/7/2020
1380	WLK1324	3% < Cross Slope < 5%	Root System		RIVER DR SE - W	Other	8/7/2020
1381	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1382	WLK1324	5% < Running Slope < 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1383	WLK1324	Running Slope > 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1384	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1385	WLK1324	Severe Cracking	Root System		RIVER DR SE - W	Other	8/7/2020
1386	WLK1324	Running Slope > 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1387	WLK1324	5% < Running Slope < 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1388	WLK1324	Cross Slope > 5%	Root System		RIVER DR SE - W	Other	8/7/2020
1389	WLK1324	Running Slope > 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1390	WLK1324	5% < Running Slope < 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1391	WLK1324	Crack < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1392	WLK1324	5% < Running Slope < 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1393	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1394	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1395	WLK1324	Crack < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1396	WLK1324	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1397	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1398	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1399	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1400	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1401	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1402	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1403	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1404	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1405	WLK1324	5% < Running Slope < 8.33%	Root System		RIVER DR SE - W	Other	8/7/2020
1406	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1407	WLK1324	Vertical displacement < 3/4 inch	Root System		RIVER DR SE - W	Other	8/7/2020
1408	WLK1324	No passing space			RIVER DR SE - W	Other	8/7/2020
1409	WLK1323	Vertical displacement < 3/4 inch			RIVER DR SE - E	Other	8/7/2020
1410	WLK1323	Crack < 3/4 inch	Age		RIVER DR SE - E	Other	8/7/2020
1411	WLK1325	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1412	WLK1325	Crack < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1413	WLK1325	Crack < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1414	WLK1325	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1415	WLK1333	No passing space			79TH AVE SE - S	Other	8/7/2020
1416	WLK1333	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1417	WLK1334	3% < Cross Slope < 5%	Settlement		79TH AVE SE - S	Other	8/7/2020
1418	WLK1335	No passing space			79TH AVE SE - S	Other	8/7/2020
1419	WLK1336	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1420	WLK1345	3% < Cross Slope < 5%	Root System		BELMONTE DR SE - E	Other	8/7/2020
1421	WLK1340	2% < Cross Slope < 3%	Root System		BELMONTE DR SE - W	Other	8/7/2020
1422	WLK1341	Vertical displacement < 3/4 inch	Root System		BELMONTE DR SE - W	Other	8/7/2020
1423	WLK1343	Cross Slope > 5%	Driveway/Driveway Flare		BELMONTE DR SE - E	Other	8/7/2020
1424	WLK1341	2% < Cross Slope < 3%	Root System		BELMONTE DR SE - W	Other	8/7/2020
1425	WLK1345	2% < Cross Slope < 3%	Root System		BELMONTE DR SE - E	Other	8/7/2020
1426	WLK1347	Cross Slope > 5%	Driveway/Driveway Flare		BELMONTE DR SE - E	Other	8/7/2020
1427	WLK1349	3% < Cross Slope < 5%	Root System		79TH AVE SE - S	Other	8/7/2020
1428	WLK1350	No passing space			79TH AVE SE - S	Other	8/7/2020
1429	WLK1350	2% < Cross Slope < 3%	Root System		79TH AVE SE - S	Other	8/7/2020
1430	WLK1350	Crack < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1431	WLK1357	Minor Cracking	Age		79TH AVE SE - S	Other	8/7/2020
1432	WLK1356	No passing space			79TH AVE SE - S	Other	8/7/2020
1433	WLK1356	Crack < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1434	WLK1356	Minor Cracking	Age		79TH AVE SE - S	Other	8/7/2020
1435	WLK1356	Minor Cracking	Settlement		79TH AVE SE - S	Other	8/7/2020
1436	WLK1356	2% < Cross Slope < 3%			79TH AVE SE - S	Other	8/7/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1437	WLK1356	Minor Cracking	Age		79TH AVE SE - S		8/7/2020
1438	WLK1356	Minor Cracking	Age		79TH AVE SE - S		8/7/2020
1439	WLK1356	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - S		8/7/2020
1440	WLK1356	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		79TH AVE SE - S		8/7/2020
1441	WLK1356	Minor Cracking	Age		79TH AVE SE - S		8/7/2020
1442	WLK1356	Minor Cracking	Age		79TH AVE SE - S		8/7/2020
1443	WLK1356	Moderate Cracking	Age		79TH AVE SE - S		8/7/2020
1444	WLK1359	Crack between 3/4 inch and 1-1/4 inch	Settlement		79TH AVE SE - N		8/7/2020
1445	WLK1359	Crack between 3/4 inch and 1-1/4 inch	Settlement		79TH AVE SE - N		8/7/2020
1446	WLK1359	Minor Cracking	Settlement		79TH AVE SE - N		8/7/2020
1447	WLK1359	No passing space			79TH AVE SE - N		8/7/2020
1448	WLK1359	Minor Cracking	Age		79TH AVE SE - N		8/7/2020
1449	WLK1359	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - N		8/7/2020
1450	WLK1359	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - N		8/7/2020
1451	WLK1350	No passing space			79TH AVE SE - S	Other	8/7/2020
1452	WLK1377	3% < Cross Slope < 5%			ARAB DR SE - N	Other	8/7/2020
1453	WLK1332	No passing space			79TH AVE SE - N	Other	8/7/2020
1454	WLK1331	No passing space			79TH AVE SE - N		8/7/2020
1455	WLK1328	No passing space			79TH AVE SE - N	Other	8/7/2020
1456	WLK1327	Cross Slope > 5%	Driveway/Driveway Flare		79TH AVE SE - N	Other	8/7/2020
1457	WLK1327	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		79TH AVE SE - N	Other	8/7/2020
1458	WLK1327	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		79TH AVE SE - N	Other	8/7/2020
1459	WLK1326	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1460	WLK1326	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1461	WLK1325	Crack < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1462	WLK1325	Vertical displacement < 3/4 inch	Root System		79TH AVE SE - S	Other	8/7/2020
1463	WLK1325	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1464	WLK1325	3% < Cross Slope < 5%	Root System		79TH AVE SE - S	Other	8/7/2020
1465	WLK1325	5% < Running Slope < 8.33%	Root System		79TH AVE SE - S	Other	8/7/2020
1466	WLK1360	Vertical displacement < 3/4 inch	Root System		RIVERVIEW CT SE - W		8/7/2020
1467	WLK1202	No passing space			TILLEY CT		8/7/2020
1468	WLK1203	No passing space			TILLEY CT		8/7/2020
1469	WLK1204	3% < Cross Slope < 5%			88TH AVE SE - S	Urban Collector	8/7/2020
1470	WLK1204	2% < Cross Slope < 3%			88TH AVE SE - S	Urban Collector	8/7/2020
1471	WLK1204	Cross Slope > 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1472	WLK1204	No passing space			88TH AVE SE - S	Urban Collector	8/7/2020
1473	WLK1204	Cross Slope > 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1474	WLK1204	2% < Cross Slope < 3%	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1475	WLK1204	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1476	WLK1204	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1477	WLK1204	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1478	WLK1204	Cross Slope > 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1479	WLK1204	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1480	WLK1204	Cross Slope > 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1481	WLK1204	Running Slope > 8.33%	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1482	WLK1204	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1483	WLK1204	2% < Cross Slope < 3%			88TH AVE SE - S	Urban Collector	8/7/2020
1484	WLK1210	No passing space			88TH AVE SE - S	Urban Collector	8/7/2020
1485	WLK1210	Crack < 3/4 inch	Settlement		88TH AVE SE - S	Urban Collector	8/7/2020
1486	WLK1215	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S	Urban Collector	8/7/2020
1487	WLK1209	Vertical displacement > 1-1/4 inch	Root System		88TH AVE SE - N	Urban Collector	8/7/2020
1488	WLK1209	2% < Cross Slope < 3%	Root System		88TH AVE SE - N	Urban Collector	8/7/2020
1489	WLK1209	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - N	Urban Collector	8/7/2020
1490	WLK1209	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - N	Urban Collector	8/7/2020
1491	WLK1060	Minor Cracking	Age				8/7/2020
1492	WLK1060	2% < Cross Slope < 3%					8/7/2020
1493	WLK1060	No passing space					8/7/2020
1494	WLK1060	Cross Slope > 5%	Driveway/Driveway Flare				8/7/2020
1495	WLK1060	3% < Cross Slope < 5%					8/7/2020
1496	WLK1200	3% < Cross Slope < 5%			88TH AVE SE - N	Urban Collector	8/7/2020
1497	WLK1200	2% < Cross Slope < 3%			88TH AVE SE - N	Urban Collector	8/7/2020
1498	WLK1201	Minor Cracking			88TH AVE SE - S	Urban Collector	8/7/2020
1499	WLK1201	3% < Cross Slope < 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1500	WLK1201	Cross Slope > 5%	Driveway/Driveway Flare		88TH AVE SE - S	Urban Collector	8/7/2020
1501	WLK1200	2% < Cross Slope < 3%			88TH AVE SE - N	Urban Collector	8/7/2020
1502	WLK1398	Vertical displacement < 3/4 inch			ARAB DR SE - N	Other	8/7/2020
1503	WLK1398	Crack < 3/4 inch			ARAB DR SE - N	Other	8/7/2020
1504	WLK1397	2% < Cross Slope < 3%	Root System		ARAB DR SE - N	Other	8/7/2020
1505	WLK1397	Minor Cracking	Age		ARAB DR SE - N	Other	8/7/2020
1506	WLK1397	Crack < 3/4 inch			ARAB DR SE - N	Other	8/7/2020
1507	WLK1397	No passing space			ARAB DR SE - N	Other	8/7/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1508	WLK1397	2% < Cross Slope < 3%	Root System		ARAB DR SE - N	Other	8/7/2020
1509	WLK1397	3% < Cross Slope < 5%	Root System		ARAB DR SE - N	Other	8/7/2020
1510	WLK1397	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1511	WLK1397	Crack < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1512	WLK1397	2% < Cross Slope < 3%	Settlement		ARAB DR SE - N	Other	8/7/2020
1513	WLK1397	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1514	WLK1397	Crack < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1515	WLK1397	Vertical displacement > 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1516	WLK1397	Cross Slope > 5%	Root System		ARAB DR SE - N	Other	8/7/2020
1517	WLK1397	3% < Cross Slope < 5%	Root System		ARAB DR SE - N	Other	8/7/2020
1518	WLK1397	3% < Cross Slope < 5%	Root System		ARAB DR SE - N	Other	8/7/2020
1519	WLK1397	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/7/2020
1520	WLK1397	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1521	WLK1397	No passing space			ARAB DR SE - N	Other	8/7/2020
1522	WLK1397	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1523	WLK1397	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1524	WLK1397	Cross Slope > 5%	Root System		ARAB DR SE - N	Other	8/7/2020
1525	WLK1397	Crack < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1526	WLK1399	No passing space			ARAB DR SE - N	Other	8/7/2020
1527	WLK1399	Minor Cracking	Age		ARAB DR SE - N	Other	8/7/2020
1528	WLK1399	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/7/2020
1529	WLK1399	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/7/2020
1530	WLK1399	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/7/2020
1531	WLK1399	Moderate Cracking	Settlement		ARAB DR SE - N	Other	8/7/2020
1532	WLK1398	2% < Cross Slope < 3%			ARAB DR SE - N	Other	8/7/2020
1533	WLK1398	Crack < 3/4 inch	Age		ARAB DR SE - N	Other	8/7/2020
1534	WLK1398	2% < Cross Slope < 3%	Age		ARAB DR SE - N	Other	8/7/2020
1535	WLK1398	Vertical displacement < 3/4 inch	Settlement		ARAB DR SE - N	Other	8/7/2020
1536	WLK961	3% < Cross Slope < 5%			WICKIE PL SE - W	Other	8/7/2020
1537	WLK961	Minor Cracking			WICKIE PL SE - W	Other	8/7/2020
1538	WLK961	Minor Cracking	Age		WICKIE PL SE - W	Other	8/7/2020
1539	WLK961	Minor Cracking	Age		WICKIE PL SE - W	Other	8/7/2020
1540	WLK961	Crack < 3/4 inch	Age		WICKIE PL SE - W	Other	8/7/2020
1541	WLK961	Crack < 3/4 inch	Settlement		WICKIE PL SE - W	Other	8/7/2020
1542	WLK961	Crack < 3/4 inch	Age		WICKIE PL SE - W	Other	8/7/2020
1543	WLK959	Vertical displacement < 3/4 inch	Root System		PALOMINO DR SE - N	Other	8/7/2020
1544	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1545	WLK959	2% < Cross Slope < 3%			PALOMINO DR SE - N	Other	8/7/2020
1546	WLK959	Minor Cracking	Age		PALOMINO DR SE - N	Other	8/7/2020
1547	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1548	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1549	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1550	WLK959	Crack < 3/4 inch	Age		PALOMINO DR SE - N	Other	8/7/2020
1551	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1552	WLK959	Minor Cracking	Age		PALOMINO DR SE - N	Other	8/7/2020
1553	WLK959	Crack < 3/4 inch	Root System		PALOMINO DR SE - N	Other	8/7/2020
1554	WLK959	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1555	WLK953	Crack < 3/4 inch	Age		PALOMINO DR SE - N	Other	8/7/2020
1556	WLK953	2% < Cross Slope < 3%			PALOMINO DR SE - N	Other	8/7/2020
1557	WLK953	3% < Cross Slope < 5%			PALOMINO DR SE - N	Other	8/7/2020
1558	WLK953	Minor Cracking	Age		PALOMINO DR SE - N	Other	8/7/2020
1559	WLK950	Moderate Cracking	Age		HARVEST DR SE - N	Other	8/7/2020
1560	WLK941	Minor Cracking	Age		YELM HWY SE - N	Major Arterial	8/7/2020
1561	WLK949	No passing space			HARVEST DR SE - N	Other	8/7/2020
1562	WLK948	Cross Slope > 5%	Root System		HARVEST DR SE - N	Other	8/7/2020
1563	WLK948	3% < Cross Slope < 5%	Root System		HARVEST DR SE - N	Other	8/7/2020
1564	WLK948	Minor Cracking			HARVEST DR SE - N	Other	8/7/2020
1565	WLK948	Vertical displacement < 3/4 inch	Root System		HARVEST DR SE - N	Other	8/7/2020
1566	WLK958	No passing space			SURREY TRCE SE - N	Other	8/7/2020
1567	WLK957	Minor Cracking	Age		SURREY TRCE SE - N	Other	8/7/2020
1568	WLK956	No passing space			CORRAL LN SE - E	Other	8/7/2020
1569	WLK956	Cross Slope > 5%	Root System		CORRAL LN SE - E	Other	8/7/2020
1570	WLK956	Minor Cracking	Root System		CORRAL LN SE - E	Other	8/7/2020
1571	WLK956	Crack between 3/4 inch and 1-1/4 inch	Settlement		CORRAL LN SE - E	Other	8/7/2020
1572	WLK955	Vertical displacement < 3/4 inch	Root System		HARVEST DR SE - S	Other	8/7/2020
1573	WLK955	Crack between 3/4 inch and 1-1/4 inch	Root System		HARVEST DR SE - S	Other	8/7/2020
1574	WLK955	Minor Cracking	Settlement		HARVEST DR SE - S	Other	8/7/2020
1575	WLK953	Minor Cracking	Age		PALOMINO DR SE - N	Other	8/7/2020
1576	WLK954	3% < Cross Slope < 5%			PALOMINO DR SE - S	Other	8/7/2020
1577	WLK954	Crack < 3/4 inch	Age		PALOMINO DR SE - S	Other	8/7/2020
1578	WLK954	Minor Cracking	Settlement		PALOMINO DR SE - S	Other	8/7/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1579	WLK954	2% < Cross Slope < 3%			PALOMINO DR SE - S	Other	8/7/2020
1580	WLK960	3% < Cross Slope < 5%			PALOMINO DR SE - S	Other	8/7/2020
1581	WLK960	Vertical displacement < 3/4 inch			PALOMINO DR SE - S	Other	8/7/2020
1582	WLK960	Cross Slope > 5%	Settlement		PALOMINO DR SE - S	Other	8/7/2020
1583	WLK960	2% < Cross Slope < 3%	Age		PALOMINO DR SE - S	Other	8/7/2020
1584	WLK962	Crack < 3/4 inch	Age		PALOMINO DR SE - S	Other	8/7/2020
1585	WLK962	Vertical displacement < 3/4 inch	Settlement		PALOMINO DR SE - S	Other	8/7/2020
1586	WLK962	Vertical displacement < 3/4 inch	Root System		PALOMINO DR SE - S	Other	8/7/2020
1587	WLK962	Minor Cracking	Age		PALOMINO DR SE - S	Other	8/7/2020
1588	WLK973	No passing space			JOSEPH ST SE - E	Other	8/7/2020
1589	WLK962	Cross Slope > 5%	Driveway/Driveway Flare		PALOMINO DR SE - S	Other	8/7/2020
1590	WLK973	Cross Slope > 5%	Driveway/Driveway Flare		JOSEPH ST SE - E	Other	8/7/2020
1591	WLK973	Cross Slope > 5%	Driveway/Driveway Flare		JOSEPH ST SE - E	Other	8/7/2020
1592	WLK973	Minor Cracking	Settlement		JOSEPH ST SE - E	Other	8/7/2020
1593	WLK972	Minor Cracking			JOSEPH ST SE - E	Other	8/7/2020
1594	WLK970	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		52ND AVE SE - S	Other	8/7/2020
1595	WLK970	Crack < 3/4 inch	Root System		52ND AVE SE - N	Other	8/7/2020
1596	WLK970	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		52ND AVE SE - N	Other	8/7/2020
1597	WLK970	Vertical displacement < 3/4 inch	Root System		52ND AVE SE - N	Other	8/7/2020
1598	WLK969	Vertical displacement < 3/4 inch	Root System		52ND AVE SE - S	Other	8/7/2020
1599	WLK969	Crack < 3/4 inch	Root System		52ND AVE SE - S	Other	8/7/2020
1600	WLK968	Minor Cracking			JOSEPH ST SE - W	Other	8/7/2020
1601	WLK968	Minor Cracking	Root System		JOSEPH ST SE - W	Other	8/7/2020
1602	WLK968	Cross Slope > 5%	Driveway/Driveway Flare		JOSEPH ST SE - W	Other	8/7/2020
1603	WLK968	Cross Slope > 5%	Driveway/Driveway Flare		JOSEPH ST SE - W	Other	8/7/2020
1604	WLK968	Cross Slope > 5%	Driveway/Driveway Flare		JOSEPH ST SE - W	Other	8/7/2020
1605	WLK974	No passing space			53RD AVE SE - N	Other	8/7/2020
1606	WLK975	Minor Cracking	Age		ARLINGTON CT SE - E	Other	8/7/2020
1607	WLK975	3% < Cross Slope < 5%			ARLINGTON CT SE - E	Other	8/7/2020
1608	WLK975	Minor Cracking	Age		ARLINGTON CT SE - E	Other	8/7/2020
1609	WLK976	Crack < 3/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1610	WLK976	No passing space			53RD AVE SE - N	Other	8/7/2020
1611	WLK976	Vertical displacement < 3/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1612	WLK976	Vertical displacement > 1-1/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1613	WLK976	Vertical displacement < 3/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1614	WLK976	Vertical displacement < 3/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1615	WLK976	Vertical displacement < 3/4 inch	Root System		53RD AVE SE - N	Other	8/7/2020
1616	WLK977	No passing space			53RD AVE SE - S	Other	8/7/2020
1617	WLK983	No passing space			53RD AVE SE - S	Other	8/7/2020
1618	WLK983	2% < Cross Slope < 3%			53RD AVE SE - S	Other	8/7/2020
1619	WLK984	Vertical displacement < 3/4 inch	Root System		53RD AVE SE - S	Other	8/7/2020
1620	WLK967	No passing space			53RD AVE SE - N	Other	8/7/2020
1621	WLK1395	2% < Cross Slope < 3%	Root System		TRAILS END DR SE - E	Other	8/11/2020
1622	WLK1392	Crack > 1-1/4 inch			TRAILS END DR SE - E	Other	8/11/2020
1623	WLK1392	Vertical displacement > 1-1/4 inch			TRAILS END DR SE - E	Other	8/11/2020
1624	WLK1392	Vertical displacement between 3/4 inch and 1-1/4 inch			TRAILS END DR SE - E	Other	8/11/2020
1626	WLK1393	Vertical displacement between 3/4 inch and 1-1/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1627	WLK1393	Vertical displacement > 1-1/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1628	WLK1393	Vertical displacement between 3/4 inch and 1-1/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1629	WLK1394	Vertical displacement < 3/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1630	WLK1394	2% < Cross Slope < 3%			TRAILS END DR SE - W	Other	8/11/2020
1631	WLK1394	Vertical displacement between 3/4 inch and 1-1/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1632	WLK1394	Vertical displacement < 3/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1633	WLK1394	2% < Cross Slope < 3%			TRAILS END DR SE - W	Other	8/11/2020
1634	WLK1394	Crack < 3/4 inch	Root System		TRAILS END DR SE - W	Other	8/11/2020
1635	WLK1394	3% < Cross Slope < 5%			TRAILS END DR SE - W	Other	8/11/2020
1636	WLK1396	Vertical displacement < 3/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1637	WLK1400	No passing space			TRAILS END DR SE - W	Other	8/11/2020
1638	WLK1400	Minor Cracking			TRAILS END DR SE - W	Other	8/11/2020
1639	WLK1400	Severe Cracking			TRAILS END DR SE - W	Other	8/11/2020
1640	WLK1400	Minor Cracking			TRAILS END DR SE - W	Other	8/11/2020
1641	WLK1400	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TRAILS END DR SE - W	Other	8/11/2020
1642	WLK1400	Cross Slope > 5%			TRAILS END DR SE - W	Other	8/11/2020
1643	WLK1400	Vertical displacement < 3/4 inch			TRAILS END DR SE - W	Other	8/11/2020
1644	WLK1400	Vertical displacement > 1-1/4 inch	Root System		TRAILS END DR SE - W	Other	8/11/2020
1645	WLK1400	Moderate Cracking	Settlement		TRAILS END DR SE - W	Other	8/11/2020
1646	WLK1400	Moderate Cracking	Settlement		TRAILS END DR SE - W	Other	8/11/2020
1647	WLK1400	Minor Cracking	Settlement		TRAILS END DR SE - W	Other	8/11/2020
1648	WLK1400	Crack < 3/4 inch	Settlement		TRAILS END DR SE - W	Other	8/11/2020
1649	WLK1400	Vertical displacement < 3/4 inch	Settlement		TRAILS END DR SE - W	Other	8/11/2020
1650	WLK1391	No passing space			ARAB DR SE - N	Other	8/11/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1651	WLK1391	Vertical displacement > 1-1/4 inch	Settlement		ARAB DR SE - N	Other	8/11/2020
1652	WLK1391	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1653	WLK1388	Minor Cracking	Root System		ARAB DR SE - N	Other	8/11/2020
1654	WLK1388	3% < Cross Slope < 5%	Root System		ARAB DR SE - N	Other	8/11/2020
1655	WLK1388	Vertical displacement < 3/4 inch			ARAB DR SE - N	Other	8/11/2020
1656	WLK1388	3% < Cross Slope < 5%	Driveway/Driveway Flare		ARAB DR SE - N	Other	8/11/2020
1657	WLK1388	Crack < 3/4 inch	Settlement		ARAB DR SE - N	Other	8/11/2020
1658	WLK1388	3% < Cross Slope < 5%	Root System		ARAB DR SE - N	Other	8/11/2020
1659	WLK1388	Cross Slope > 5%	Root System		ARAB DR SE - N	Other	8/11/2020
1660	WLK1388	No passing space			ARAB DR SE - N	Other	8/11/2020
1661	WLK1387	Cross Slope > 5%			GELDING DR SE - W	Other	8/11/2020
1662	WLK1387	3% < Cross Slope < 5%			GELDING DR SE - W	Other	8/11/2020
1663	WLK1387	Minor Cracking	Settlement		GELDING DR SE - W	Other	8/11/2020
1664	WLK1387	Crack < 3/4 inch	Settlement		GELDING DR SE - W	Other	8/11/2020
1665	WLK1387	Crack < 3/4 inch	Root System		GELDING DR SE - W	Other	8/11/2020
1666	WLK1386	Minor Cracking	Settlement		GELDING DR SE - E	Other	8/11/2020
1667	WLK1386	Minor Cracking	Settlement		GELDING DR SE - E	Other	8/11/2020
1668	WLK1389	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1669	WLK1389	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1670	WLK1389	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1671	WLK1389	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1672	WLK1389	Severe Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1673	WLK1390	No passing space			ARAB DR SE - N	Other	8/11/2020
1674	WLK1390	Cross Slope > 5%			ARAB DR SE - N	Other	8/11/2020
1675	WLK1385	Cross Slope > 5%			ARAB DR SE - N	Other	8/11/2020
1676	WLK1385	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1677	WLK1385	2% < Cross Slope < 3%			ARAB DR SE - N	Other	8/11/2020
1678	WLK1385	2% < Cross Slope < 3%			ARAB DR SE - N	Other	8/11/2020
1679	WLK1385	Crack < 3/4 inch			ARAB DR SE - N	Other	8/11/2020
1680	WLK1384	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1681	WLK1384	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1682	WLK1383	2% < Cross Slope < 3%			ARAB DR SE - N	Other	8/11/2020
1683	WLK1382	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1684	WLK1382	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1685	WLK1381	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1686	WLK1381	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1687	WLK1381	Minor Cracking	Age		ARAB DR SE - N	Other	8/11/2020
1688	WLK1381	Minor Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1689	WLK1379	Minor Cracking			ARAB DR SE - N	Other	8/11/2020
1690	WLK1377	Moderate Cracking	Age		ARAB DR SE - N	Other	8/11/2020
1691	WLK1377	Minor Cracking	Age		ARAB DR SE - N	Other	8/11/2020
1692	WLK1377	Minor Cracking	Age		ARAB DR SE - N	Other	8/11/2020
1693	WLK1377	Moderate Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1694	WLK1377	Moderate Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1695	WLK1377	No passing space			ARAB DR SE - N	Other	8/11/2020
1696	WLK1377	Vertical displacement < 3/4 inch			ARAB DR SE - N	Other	8/11/2020
1697	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1698	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1699	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1700	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1701	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1702	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1703	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1704	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1705	WLK1377	Vertical displacement > 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1706	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1707	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1708	WLK1377	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1709	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1710	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1711	WLK1377	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1712	WLK1376	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1713	WLK1376	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1714	WLK1376	Vertical displacement > 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1715	WLK1376	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1716	WLK1376	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1717	WLK1376	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1718	WLK1376	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1719	WLK1376	Vertical displacement < 3/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1720	WLK1376	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020
1721	WLK1376	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ARAB DR SE - N	Other	8/11/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1722	WLK1376	Crack < 3/4 inch	Age		ARAB DR SE - N	Other	8/11/2020
1723	WLK1376	Crack < 3/4 inch	Age		ARAB DR SE - N	Other	8/11/2020
1724	WLK1376	Crack < 3/4 inch	Age		ARAB DR SE - N	Other	8/11/2020
1725	WLK1376	Severe Cracking	Settlement		ARAB DR SE - N	Other	8/11/2020
1726	WLK1376	Crack > 1-1/4 inch	Settlement		ARAB DR SE - N	Other	8/11/2020
1727	WLK1355	Minor Cracking	Age		RIVERVIEW DR SE - S	Other	8/11/2020
1728	WLK1355	Vertical displacement < 3/4 inch			RIVERVIEW DR SE - S	Other	8/11/2020
1729	WLK1355	Moderate Cracking	Settlement		RIVERVIEW DR SE - S	Other	8/11/2020
1730	WLK1354	No passing space			RIVERVIEW DR SE - S	Other	8/11/2020
1731	WLK1353	Minor Cracking	Age		80TH AVE SE - E	Other	8/11/2020
1732	WLK1353	Crack < 3/4 inch	Settlement		80TH AVE SE - E	Other	8/11/2020
1733	WLK1353	Minor Cracking	Settlement		80TH AVE SE - E	Other	8/11/2020
1734	WLK1353	Minor Cracking	Settlement		80TH AVE SE - E	Other	8/11/2020
1735	WLK1353	Vertical displacement < 3/4 inch			80TH AVE SE - E	Other	8/11/2020
1736	WLK1353	Minor Cracking			80TH AVE SE - E	Other	8/11/2020
1737	WLK1353	Crack < 3/4 inch			80TH AVE SE - E	Other	8/11/2020
1738	WLK1353	No passing space			80TH AVE SE - E	Other	8/11/2020
1739	WLK1353	Crack < 3/4 inch			80TH AVE SE - E	Other	8/11/2020
1740	WLK1353	3% < Cross Slope < 5%			80TH AVE SE - E	Other	8/11/2020
1741	WLK1353	Minor Cracking	Settlement		80TH AVE SE - E	Other	8/11/2020
1742	WLK1353	Crack < 3/4 inch			80TH AVE SE - E	Other	8/11/2020
1743	WLK1353	Minor Cracking	Settlement		80TH AVE SE - E	Other	8/11/2020
1744	WLK1353	Minor Cracking	Age		80TH AVE SE - E	Other	8/11/2020
1745	WLK1351	Minor Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1746	WLK1351	Minor Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1747	WLK1351	Crack < 3/4 inch	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1748	WLK1351	Minor Cracking	Age		DESCHUTES CT SE - E	Other	8/11/2020
1749	WLK1351	Crack > 1-1/4 inch	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1750	WLK1351	Minor Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1751	WLK1351	Moderate Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1752	WLK1351	Vertical displacement > 1-1/4 inch	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1753	WLK1351	Crack < 3/4 inch	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1754	WLK1351	Minor Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1755	WLK1351	Vertical displacement > 1-1/4 inch	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1756	WLK1351	Minor Cracking	Settlement		DESCHUTES CT SE - E	Other	8/11/2020
1757	WLK1351	Crack < 3/4 inch	Age		DESCHUTES CT SE - E	Other	8/11/2020
1759	WLK1352	Crack < 3/4 inch	Age		80TH AVE SE - E	Other	8/11/2020
1760	WLK979	2% < Cross Slope < 3%			53RD LOOP SE - S	Other	8/11/2020
1761	WLK979	Minor Cracking			53RD LOOP SE - S	Other	8/11/2020
1762	WLK979	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1763	WLK979	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1764	WLK982	Moderate Cracking			53RD LOOP SE - S	Other	8/11/2020
1765	WLK979	Moderate Cracking	Settlement		53RD LOOP SE - S	Other	8/11/2020
1766	WLK979	Hole < 3/4 inch	Age		53RD LOOP SE - S	Other	8/11/2020
1767	WLK979	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1768	WLK979	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1769	WLK979	Crack < 3/4 inch	Settlement		53RD LOOP SE - S	Other	8/11/2020
1770	WLK981	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1771	WLK982	Crack < 3/4 inch	Settlement		53RD LOOP SE - S	Other	8/11/2020
1772	WLK982	Crack < 3/4 inch	Settlement		53RD LOOP SE - S	Other	8/11/2020
1773	WLK982	Crack < 3/4 inch			53RD LOOP SE - S	Other	8/11/2020
1774	WLK982	Crack < 3/4 inch	Settlement		53RD LOOP SE - S	Other	8/11/2020
1775	WLK982	Crack < 3/4 inch	Settlement		53RD LOOP SE - S	Other	8/11/2020
1776	WLK964	Cross Slope > 5%	Driveway/Driveway Flare		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1777	WLK965	Cross Slope > 5%	Driveway/Driveway Flare		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1778	WLK965	3% < Cross Slope < 5%	Driveway/Driveway Flare		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1779	WLK985	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1780	WLK985	Vertical displacement > 1-1/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1781	WLK985	Crack < 3/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1782	WLK985	Vertical displacement > 1-1/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1783	WLK985	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1784	WLK985	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1785	WLK985	Running Slope > 8.33%	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1786	WLK985	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1787	WLK985	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - E	Minor Arterial	8/11/2020
1788	WLK988	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		58TH AVE SE - S	Other	8/11/2020
1789	WLK987	Crack < 3/4 inch	Settlement		PIONEER PARK DW SE - S	Other	8/11/2020
1790	WLK987	Crack < 3/4 inch	Root System		PIONEER PARK DW SE - S	Other	8/11/2020
1791	WLK987	Vertical displacement > 1-1/4 inch	Root System		PIONEER PARK DW SE - S	Other	8/11/2020
1792	WLK987	Vertical displacement > 1-1/4 inch	Root System		PIONEER PARK DW SE - S	Other	8/11/2020
1793	WLK986	Crack < 3/4 inch	Settlement		HENDERSON BLVD SE - N	Other	8/11/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1794	WLK986	Crack between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1795	WLK986	Vertical displacement > 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1796	WLK986	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		HENDERSON BLVD SE - N	Other	8/11/2020
1797	WLK986	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1798	WLK986	Vertical displacement > 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1799	WLK986	Crack < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1800	WLK986	Cross Slope > 5%	Driveway/Driveway Flare		HENDERSON BLVD SE - N	Other	8/11/2020
1801	WLK986	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1802	WLK986	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1803	WLK966	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1804	WLK966	Crack < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1805	WLK966	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1806	WLK966	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1807	WLK966	Vertical displacement < 3/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1808	WLK966	Vertical displacement > 1-1/4 inch	Root System		HENDERSON BLVD SE - N	Other	8/11/2020
1809	WLK315	No passing space			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1810	WLK315	Crack < 3/4 inch			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1811	WLK315	Crack < 3/4 inch			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1812	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1813	WLK315	Crack < 3/4 inch			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1814	WLK315	Crack < 3/4 inch			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1815	WLK315	Crack < 3/4 inch			LAKE PARK DR SW - W	Urban Collector	8/11/2020
1816	WLK315	Crack < 3/4 inch	Settlement		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1817	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1818	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1819	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1820	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1821	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1822	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1823	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1824	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1825	WLK315	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - W	Urban Collector	8/11/2020
1826	WLK316	2% < Cross Slope < 3%			LAKE PARK DR SW - E	Urban Collector	8/11/2020
1827	WLK316	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1828	WLK316	Crack < 3/4 inch	Settlement		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1829	WLK316	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1830	WLK316	Crack < 3/4 inch			LAKE PARK DR SW - E	Urban Collector	8/11/2020
1831	WLK316	Cross Slope > 5%	Driveway/Driveway Flare		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1832	WLK316	Crack < 3/4 inch	Settlement		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1833	WLK316	Vertical displacement < 3/4 inch	Settlement		LAKE PARK DR SW - E	Urban Collector	8/11/2020
1834	WLK947	5% < Running Slope < 8.33%	Driveway/Driveway Flare		YELM HWY SE - S	Major Arterial	8/18/2020
1835	WLK947	Minor Cracking	Settlement		YELM HWY SE - S	Major Arterial	8/18/2020
1836	WLK945	Crack < 3/4 inch			YELM HWY SE - N	Major Arterial	8/18/2020
1837	WLK943	Cross Slope > 5%	Driveway/Driveway Flare		YELM HWY SE - N	Major Arterial	8/18/2020
1838	WLK943	3% < Cross Slope < 5%			YELM HWY SE - N	Major Arterial	8/18/2020
1839	WLK942	Cross Slope > 5%	Driveway/Driveway Flare		YELM HWY SE - S	Major Arterial	8/18/2020
1840	WLK941	Crack < 3/4 inch	Root System		YELM HWY SE - N	Major Arterial	8/18/2020
1841	WLK941	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		YELM HWY SE - N	Major Arterial	8/18/2020
1842	WLK941	Cross Slope > 5%	Driveway/Driveway Flare		YELM HWY SE - N	Major Arterial	8/18/2020
1843	WLK941	Cross Slope > 5%	Driveway/Driveway Flare		YELM HWY SE - N	Major Arterial	8/18/2020
1844	WLK941	Cross Slope > 5%	Driveway/Driveway Flare		YELM HWY SE - N	Major Arterial	8/18/2020
1845	WLK935	2% < Cross Slope < 3%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1846	WLK935	Hole < 3/4 inch			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1847	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1848	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1849	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1850	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1851	WLK935	2% < Cross Slope < 3%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1852	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1853	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1854	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1855	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1856	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1857	WLK935	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1858	WLK934	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1859	WLK925	Cross Slope > 5%	Driveway/Driveway Flare	13.5%	CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1860	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1861	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1862	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1863	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1864	WLK925	3% < Cross Slope < 5%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1865	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1866	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1867	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1868	WLK925	Crack < 3/4 inch	Settlement		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1869	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1870	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1871	WLK925	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1872	WLK851	3% < Cross Slope < 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1873	WLK848	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1874	WLK848	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1875	WLK848	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1876	WLK844	Vertical displacement < 3/4 inch	Age		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1877	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1878	WLK844	2% < Cross Slope < 3%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1879	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1880	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1881	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1882	WLK844	2% < Cross Slope < 3%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1883	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1884	WLK844	3% < Cross Slope < 5%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1885	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1886	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1887	WLK845	3% < Cross Slope < 5%			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1888	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1889	WLK844	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1890	WLK844	3% < Cross Slope < 5%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1891	WLK834	Vertical displacement < 3/4 inch	Root System		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1892	WLK833	Crack < 3/4 inch	Age		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1893	WLK833	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1894	WLK833	Minor Cracking	Age		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1895	WLK833	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1896	WLK833	Crack between 3/4 inch and 1-1/4 inch	Age		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1897	WLK833	Crack < 3/4 inch	Age		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1898	WLK833	2% < Cross Slope < 3%			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1899	WLK833	Crack < 3/4 inch			CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1900	WLK833	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - E	Minor Arterial	8/18/2020
1901	WLK831	5% < Running Slope < 8.33%			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1902	WLK831	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1903	WLK831	Moderate Cracking			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1904	WLK831	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1905	WLK831	Vertical displacement < 3/4 inch	Settlement		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1906	WLK831	Minor Cracking	Settlement		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1907	WLK831	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1908	WLK831	Moderate Cracking	Settlement		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1909	WLK831	Vertical displacement > 1-1/4 inch	Settlement		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1910	WLK831	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1911	WLK775	Minor Cracking			CUSTER WAY SW - N	Minor Arterial	8/18/2020
1912	WLK775	3% < Cross Slope < 5%			CUSTER WAY SW - N	Minor Arterial	8/18/2020
1916	WLK845	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1917	WLK845	Crack < 3/4 inch			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1918	WLK924	3% < Cross Slope < 5%			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1919	WLK924	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1920	WLK937	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1921	WLK937	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1922	WLK937	3% < Cross Slope < 5%	Root System		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1923	WLK937	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1924	WLK937	Minor Cracking	Root System		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1925	WLK937	Cross Slope > 5%	Root System	10.5%	CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1926	WLK937	Vertical displacement < 3/4 inch	Root System		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1927	WLK937	Cross Slope > 5%	Root System		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1928	WLK937	Vertical displacement < 3/4 inch			CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1929	WLK937	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1930	WLK937	Cross Slope > 5%	Driveway/Driveway Flare		CLEVELAND AVE SE - W	Urban Collector	8/18/2020
1931	WLK942	Hole < 3/4 inch			YELM HWY SE - S	Major Arterial	8/18/2020
1932	WLK942	Minor Cracking	Settlement		YELM HWY SE - S	Major Arterial	8/18/2020
1933	WLK782	3% < Cross Slope < 5%			NORTH ST SE - N	Minor Arterial	8/18/2020
1934	WLK782	Vertical displacement < 3/4 inch			NORTH ST SE - N	Minor Arterial	8/18/2020
1935	WLK785	Minor Cracking			NORTH ST SE - N	Minor Arterial	8/18/2020
1936	WLK786	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020
1937	WLK786	Crack < 3/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020
1938	WLK789	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
1939	WLK789	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020
1940	WLK791	Vertical displacement > 1-1/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1941	WLK791	No passing space			NORTH ST SE - S	Minor Arterial	8/18/2020
1942	WLK791	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1943	WLK791	3% < Cross Slope < 5%			NORTH ST SE - S	Minor Arterial	8/18/2020
1944	WLK791	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1945	WLK791	3% < Cross Slope < 5%			NORTH ST SE - S	Minor Arterial	8/18/2020
1946	WLK790	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1947	WLK787	5% < Running Slope < 8.33%	Driveway/Driveway Flare		NORTH ST SE - S	Minor Arterial	8/18/2020
1948	WLK784	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1949	WLK783	Minor Spalling			NORTH ST SE - S	Minor Arterial	8/18/2020
1950	WLK783	Crack < 3/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1951	WLK783	2% < Cross Slope < 3%	Driveway/Driveway Flare		NORTH ST SE - S	Minor Arterial	8/18/2020
1952	WLK779	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - S	Minor Arterial	8/18/2020
1953	WLK776	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020
1954	WLK777	2% < Cross Slope < 3%			NORTH ST SE - S	Minor Arterial	8/18/2020
1955	WLK777	2% < Cross Slope < 3%			NORTH ST SE - S	Minor Arterial	8/18/2020
1956	WLK776	Cross Slope > 5%	Driveway/Driveway Flare		NORTH ST SE - N	Minor Arterial	8/18/2020
1957	WLK776	2% < Cross Slope < 3%			NORTH ST SE - N	Minor Arterial	8/18/2020
1958	WLK776	Vertical displacement < 3/4 inch	Root System		NORTH ST SE - N	Minor Arterial	8/18/2020
1959	WLK776	Minor Spalling			NORTH ST SE - N	Minor Arterial	8/18/2020
1960	WLK776	5% < Running Slope < 8.33%	Driveway/Driveway Flare		NORTH ST SE - N	Minor Arterial	8/18/2020
1961	WLK778	Crack between 3/4 inch and 1-1/4 inch	Settlement		NORTH ST SE - N	Minor Arterial	8/18/2020
1962	WLK781	Vertical displacement < 3/4 inch	Settlement		NORTH ST SE - N	Minor Arterial	8/18/2020
1963	WLK781	Crack < 3/4 inch			NORTH ST SE - N	Minor Arterial	8/18/2020
1964	WLK781	Vertical displacement < 3/4 inch			NORTH ST SE - N	Minor Arterial	8/18/2020
1965	WLK781	Vertical displacement < 3/4 inch			NORTH ST SE - N	Minor Arterial	8/18/2020
1966	WLK798	Cross Slope > 5%	Root System		HOADLY ST SE - W	Other	8/18/2020
1967	WLK798	Crack < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1968	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1969	WLK798	Crack < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1970	WLK798	2% < Cross Slope < 3%			HOADLY ST SE - W	Other	8/18/2020
1971	WLK798	Vertical displacement < 3/4 inch			HOADLY ST SE - W	Other	8/18/2020
1972	WLK798	Crack < 3/4 inch			HOADLY ST SE - W	Other	8/18/2020
1973	WLK798	Crack < 3/4 inch			HOADLY ST SE - W	Other	8/18/2020
1974	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1975	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1976	WLK798	3% < Cross Slope < 5%			HOADLY ST SE - W	Other	8/18/2020
1977	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1978	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1979	WLK798	Crack < 3/4 inch			HOADLY ST SE - W	Other	8/18/2020
1980	WLK798	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1981	WLK798	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1982	WLK799	Crack < 3/4 inch			HOADLY ST SE - W	Other	8/18/2020
1983	WLK799	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1984	WLK799	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1985	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020
1986	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020
1987	WLK799	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Other	8/18/2020
1988	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020
1989	WLK799	Minor Cracking	Age		HOADLY ST SE - W	Other	8/18/2020
1990	WLK799	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1991	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020
1992	WLK799	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1993	WLK799	Vertical displacement > 1-1/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1994	WLK799	No passing space			HOADLY ST SE - W	Other	8/18/2020
1995	WLK799	Minor Cracking			HOADLY ST SE - W	Other	8/18/2020
1996	WLK799	Crack < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1997	WLK799	Crack < 3/4 inch	Root System		HOADLY ST SE - W	Other	8/18/2020
1998	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020
1999	WLK799	Minor Cracking	Age		HOADLY ST SE - W	Other	8/18/2020
2000	WLK799	Vertical displacement > 1-1/4 inch			HOADLY ST SE - W	Other	8/18/2020
2001	WLK797	Vertical displacement < 3/4 inch			HOADLY ST SE - E	Other	8/18/2020
2002	WLK797	No passing space			HOADLY ST SE - E	Other	8/18/2020
2003	WLK797	Crack < 3/4 inch			HOADLY ST SE - E	Other	8/18/2020
2004	WLK797	Vertical displacement > 1-1/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2005	WLK797	Minor Cracking			HOADLY ST SE - E	Other	8/18/2020
2006	WLK797	Crack < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2007	WLK797	Crack < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2008	WLK797	Vertical displacement < 3/4 inch			HOADLY ST SE - E	Other	8/18/2020
2009	WLK799	Crack < 3/4 inch	Age		HOADLY ST SE - W	Other	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2010	WLK797	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Other	8/18/2020
2011	WLK797	Vertical displacement > 1-1/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2012	WLK797	Vertical displacement < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2013	WLK797	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Other	8/18/2020
2014	WLK797	Vertical displacement < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2015	WLK796	Crack < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2016	WLK796	Crack < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2017	WLK796	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2018	WLK796	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2019	WLK796	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2020	WLK796	Crack < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2021	WLK796	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2022	WLK796	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2023	WLK796	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Other	8/18/2020
2024	WLK796	No passing space			HOADLY ST SE - E	Other	8/18/2020
2025	WLK796	Vertical displacement < 3/4 inch	Age		HOADLY ST SE - E	Other	8/18/2020
2026	WLK796	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Other	8/18/2020
2027	WLK796	Vertical displacement > 1-1/4 inch	Root System		HOADLY ST SE - E	Other	8/18/2020
2028	WLK796	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Other	8/18/2020
2029	WLK871	No passing space			HOADLY ST SE - E	Urban Collector	8/18/2020
2030	WLK871	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2031	WLK898	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2032	WLK898	3% < Cross Slope < 5%			HOADLY ST SE - E	Urban Collector	8/18/2020
2033	WLK898	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2034	WLK898	Crack < 3/4 inch	Age		HOADLY ST SE - E	Urban Collector	8/18/2020
2035	WLK898	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2036	WLK897	No passing space			HOADLY ST SE - E	Urban Collector	8/18/2020
2037	WLK897	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2038	WLK897	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2039	WLK897	Crack < 3/4 inch	Age		HOADLY ST SE - E	Urban Collector	8/18/2020
2040	WLK903	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2041	WLK903	Crack < 3/4 inch	Age		HOADLY ST SE - E	Urban Collector	8/18/2020
2042	WLK903	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2043	WLK903	Crack < 3/4 inch	Age		HOADLY ST SE - E	Urban Collector	8/18/2020
2044	WLK903	3% < Cross Slope < 5%			HOADLY ST SE - E	Urban Collector	8/18/2020
2045	WLK904	5% < Running Slope < 8.33%	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2046	WLK904	Crack between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2047	WLK904	Moderate Cracking			HOADLY LOOP SE - N	Urban Collector	8/18/2020
2048	WLK904	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2049	WLK904	Crack < 3/4 inch	Age		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2050	WLK904	Crack < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2051	WLK904	Crack between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2052	WLK904	Crack < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2053	WLK904	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2054	WLK904	3% < Cross Slope < 5%	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2055	WLK904	Crack < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2056	WLK904	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2057	WLK904	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2058	WLK904	Running Slope > 8.33%	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2059	WLK905	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2060	WLK905	Crack < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2061	WLK905	3% < Cross Slope < 5%	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2062	WLK905	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2063	WLK905	Crack < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2064	WLK905	Vertical displacement < 3/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2065	WLK905	Crack between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2066	WLK905	3% < Cross Slope < 5%			HOADLY LOOP SE - N	Urban Collector	8/18/2020
2067	WLK905	Minor Cracking			HOADLY LOOP SE - N	Urban Collector	8/18/2020
2068	WLK907	3% < Cross Slope < 5%			HOADLY LOOP SE - E	Other	8/18/2020
2069	WLK907	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2070	WLK907	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2071	WLK907	Minor Cracking	Age		HOADLY LOOP SE - E	Other	8/18/2020
2072	WLK907	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2073	WLK907	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2074	WLK906	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2075	WLK906	Vertical displacement > 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2076	WLK906	Cross Slope > 5%	Root System	11.4%	HOADLY LOOP SE - E	Other	8/18/2020
2077	WLK906	Vertical displacement > 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2078	WLK906	Crack between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2079	WLK906	Vertical displacement > 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2080	WLK906	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2081	WLK906	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2082	WLK906	Crack < 3/4 inch	Age		HOADLY LOOP SE - E	Other	8/18/2020
2083	WLK906	Crack < 3/4 inch	Settlement		HOADLY LOOP SE - E	Other	8/18/2020
2084	WLK906	3% < Cross Slope < 5%			HOADLY LOOP SE - E	Other	8/18/2020
2085	WLK906	Moderate Cracking	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2086	WLK906	3% < Cross Slope < 5%	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2087	WLK906	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY LOOP SE - E	Other	8/18/2020
2088	WLK905	Crack < 3/4 inch	Age		HOADLY LOOP SE - N	Urban Collector	8/18/2020
2089	WLK905	3% < Cross Slope < 5%			HOADLY LOOP SE - N	Urban Collector	8/18/2020
2090	WLK908	No passing space			HOADLY ST SE - E	Urban Collector	8/18/2020
2091	WLK913	3% < Cross Slope < 5%			HOADLY ST SE - E	Urban Collector	8/18/2020
2092	WLK913	5% < Running Slope < 8.33%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2093	WLK913	5% < Running Slope < 8.33%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2094	WLK913	Crack < 3/4 inch	Age		HOADLY ST SE - E	Urban Collector	8/18/2020
2095	WLK913	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2096	WLK913	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY ST SE - E	Urban Collector	8/18/2020
2097	WLK913	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2098	WLK913	No passing space			HOADLY ST SE - E	Urban Collector	8/18/2020
2099	WLK914	Cross Slope > 5%			BATES ST SE - N	Other	8/18/2020
2100	WLK914	Crack between 3/4 inch and 1-1/4 inch	Age		BATES ST SE - N	Other	8/18/2020
2101	WLK914	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	8/18/2020
2102	WLK914	Crack < 3/4 inch	Age		BATES ST SE - N	Other	8/18/2020
2103	WLK914	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	8/18/2020
2104	WLK914	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	8/18/2020
2105	WLK915	Minor Cracking	Settlement		BATES ST SE - N	Other	8/18/2020
2106	WLK915	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	8/18/2020
2107	WLK915	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	8/18/2020
2108	WLK916	Vertical displacement < 3/4 inch			HOADLY ST SE - E	Urban Collector	8/18/2020
2109	WLK916	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2110	WLK916	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2111	WLK916	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2112	WLK916	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2113	WLK917	3% < Cross Slope < 5%			HOADLY ST SE - W	Urban Collector	8/18/2020
2114	WLK917	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2115	WLK917	Vertical displacement < 3/4 inch	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2116	WLK917	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2117	WLK917	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2118	WLK917	Crack > 1-1/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2119	WLK917	Vertical displacement between 3/4 inch and 1-1/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2120	WLK917	Cross Slope > 5%	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2121	WLK917	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2122	WLK917	Crack < 3/4 inch	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2123	WLK918	No passing space			MCDONALD ST SE - N	Other	8/18/2020
2124	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2125	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2126	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2127	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2128	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2129	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2130	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2131	WLK918	Crack < 3/4 inch			MCDONALD ST SE - N	Other	8/18/2020
2132	WLK918	Crack < 3/4 inch	Age		MCDONALD ST SE - N	Other	8/18/2020
2133	WLK918	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - N	Other	8/18/2020
2134	WLK918	Crack < 3/4 inch			MCDONALD ST SE - N	Other	8/18/2020
2135	WLK918	Crack between 3/4 inch and 1-1/4 inch			MCDONALD ST SE - N	Other	8/18/2020
2136	WLK919	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - S	Other	8/18/2020
2137	WLK919	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - S	Other	8/18/2020
2138	WLK919	Vertical displacement < 3/4 inch	Root System		MCDONALD ST SE - S	Other	8/18/2020
2139	WLK919	3% < Cross Slope < 5%	Root System		MCDONALD ST SE - S	Other	8/18/2020
2140	WLK919	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MCDONALD ST SE - S	Other	8/18/2020
2141	WLK919	Moderate Cracking			MCDONALD ST SE - S	Other	8/18/2020
2142	WLK919	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - S	Other	8/18/2020
2143	WLK919	Crack < 3/4 inch			MCDONALD ST SE - S	Other	8/18/2020
2144	WLK919	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - S	Other	8/18/2020
2145	WLK919	Crack between 3/4 inch and 1-1/4 inch			MCDONALD ST SE - S	Other	8/18/2020
2146	WLK919	Cross Slope > 5%	Driveway/Driveway Flare		MCDONALD ST SE - S	Other	8/18/2020
2147	WLK919	2% < Cross Slope < 3%			MCDONALD ST SE - S	Other	8/18/2020
2148	WLK919	No passing space			MCDONALD ST SE - S	Other	8/18/2020
2149	WLK912	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2150	WLK912	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2151	WLK911	3% < Cross Slope < 5%	Root System		MALCOM ST SE - S	Other	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2152	WLK911	2% < Cross Slope < 3%			MALCOM ST SE - S	Other	8/18/2020
2153	WLK911	Cross Slope > 5%	Driveway/Driveway Flare		MALCOM ST SE - S	Other	8/18/2020
2154	WLK911	3% < Cross Slope < 5%			MALCOM ST SE - S	Other	8/18/2020
2155	WLK911	Cross Slope > 5%	Driveway/Driveway Flare		MALCOM ST SE - S	Other	8/18/2020
2156	WLK911	Minor Cracking			MALCOM ST SE - S	Other	8/18/2020
2157	WLK911	Minor Cracking			MALCOM ST SE - S	Other	8/18/2020
2158	WLK911	Cross Slope > 5%	Driveway/Driveway Flare		MALCOM ST SE - S	Other	8/18/2020
2159	WLK910	No passing space			MALCOM ST SE - S	Other	8/18/2020
2160	WLK910	Cross Slope > 5%	Driveway/Driveway Flare		MALCOM ST SE - S	Other	8/18/2020
2161	WLK910	3% < Cross Slope < 5%			MALCOM ST SE - S	Other	8/18/2020
2162	WLK910	Crack < 3/4 inch			MALCOM ST SE - S	Other	8/18/2020
2163	WLK910	Crack < 3/4 inch			MALCOM ST SE - S	Other	8/18/2020
2164	WLK910	Cross Slope > 5%	Driveway/Driveway Flare		MALCOM ST SE - S	Other	8/18/2020
2165	WLK910	3% < Cross Slope < 5%			MALCOM ST SE - S	Other	8/18/2020
2166	WLK909	Cross Slope > 5%	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2167	WLK909	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2168	WLK909	Cross Slope > 5%	Settlement		HOADLY ST SE - W	Urban Collector	8/18/2020
2169	WLK909	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2170	WLK902	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2171	WLK902	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2172	WLK902	Crack < 3/4 inch	Age		HOADLY ST SE - W	Urban Collector	8/18/2020
2173	WLK902	Crack < 3/4 inch	Age		HOADLY ST SE - W	Urban Collector	8/18/2020
2174	WLK902	Cross Slope > 5%	Root System		HOADLY ST SE - W	Urban Collector	8/18/2020
2175	WLK902	Crack < 3/4 inch	Settlement		HOADLY ST SE - W	Urban Collector	8/18/2020
2176	WLK902	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2177	WLK902	3% < Cross Slope < 5%			HOADLY ST SE - W	Urban Collector	8/18/2020
2178	WLK902	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2179	WLK900	No passing space			CALVARY CT SE - S	Other	8/18/2020
2180	WLK900	2% < Cross Slope < 3%			CALVARY CT SE - S	Other	8/18/2020
2181	WLK899	Crack < 3/4 inch	Age		HOADLY ST SE - W	Urban Collector	8/18/2020
2182	WLK899	Crack between 3/4 inch and 1-1/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2183	WLK899	Vertical displacement > 1-1/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2184	WLK899	Vertical displacement < 3/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2185	WLK899	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2186	WLK899	3% < Cross Slope < 5%			HOADLY ST SE - W	Urban Collector	8/18/2020
2187	WLK856	No passing space			BARCLIFT LN SE - N	Other	8/18/2020
2188	WLK856	Cross Slope > 5%	Driveway/Driveway Flare		BARCLIFT LN SE - N	Other	8/18/2020
2189	WLK856	3% < Cross Slope < 5%	Driveway/Driveway Flare		BARCLIFT LN SE - N	Other	8/18/2020
2190	WLK857	No passing space			BARCLIFT LN SE - S	Urban Collector	8/18/2020
2191	WLK857	3% < Cross Slope < 5%	Driveway/Driveway Flare		BARCLIFT LN SE - S	Urban Collector	8/18/2020
2192	WLK857	3% < Cross Slope < 5%	Driveway/Driveway Flare		BARCLIFT LN SE - S	Urban Collector	8/18/2020
2193	WLK1684	Minor Cracking	Settlement		HOADLY ST SE - W	Urban Collector	8/18/2020
2194	WLK1684	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2195	WLK1684	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2196	WLK870	2% < Cross Slope < 3%			HOADLY ST SE - W	Urban Collector	8/18/2020
2197	WLK870	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2198	WLK870	Crack < 3/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2199	WLK870	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2200	WLK870	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2201	WLK870	Running Slope > 8.33%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2202	WLK870	Crack < 3/4 inch			HOADLY ST SE - W	Urban Collector	8/18/2020
2203	WLK870	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - W	Urban Collector	8/18/2020
2204	WLK871	Cross Slope > 5%	Driveway/Driveway Flare		HOADLY ST SE - E	Urban Collector	8/18/2020
2205	WLK871	Crack between 3/4 inch and 1-1/4 inch			HOADLY ST SE - E	Urban Collector	8/18/2020
2206	WLK871	Crack between 3/4 inch and 1-1/4 inch			HOADLY ST SE - E	Urban Collector	8/18/2020
2207	WLK871	Crack > 1-1/4 inch			HOADLY ST SE - E	Urban Collector	8/18/2020
2208	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2209	WLK920	Vertical displacement < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2210	WLK920	Vertical displacement < 3/4 inch	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2211	WLK920	Vertical displacement < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2212	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2213	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2214	WLK920	Crack < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2215	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2216	WLK920	Crack between 3/4 inch and 1-1/4 inch			LORNE ST SE - E	Other	8/18/2020
2217	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2218	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2219	WLK920	Vertical displacement < 3/4 inch	Settlement		LORNE ST SE - E	Other	8/18/2020
2220	WLK920	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2221	WLK920	Vertical displacement < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2222	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2223	WLK921	Minor Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2224	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2225	WLK921	Running Slope > 8.33%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2226	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2227	WLK921	Crack < 3/4 inch	Age		LORNE ST SE - W	Other	8/18/2020
2228	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2229	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2230	WLK921	Crack < 3/4 inch	Settlement		LORNE ST SE - W	Other	8/18/2020
2231	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2232	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2233	WLK921	Crack < 3/4 inch	Settlement		LORNE ST SE - W	Other	8/18/2020
2234	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2235	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2236	WLK921	No passing space			LORNE ST SE - W	Other	8/18/2020
2237	WLK921	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2238	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2239	WLK922	Minor Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2240	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2241	WLK922	Vertical displacement < 3/4 inch	Settlement		LORNE ST SE - W	Other	8/18/2020
2242	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2243	WLK922	Crack < 3/4 inch			LORNE ST SE - W	Other	8/18/2020
2244	WLK922	Crack < 3/4 inch			LORNE ST SE - W	Other	8/18/2020
2245	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2246	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2247	WLK922	Crack < 3/4 inch			LORNE ST SE - W	Other	8/18/2020
2248	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2249	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2250	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2251	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2252	WLK922	Minor Cracking			LORNE ST SE - W	Other	8/18/2020
2253	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2254	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2255	WLK922	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - W	Other	8/18/2020
2256	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2257	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2258	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2259	WLK922	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2260	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2261	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2262	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2263	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2264	WLK923	Crack < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2265	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2266	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2267	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2268	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2269	WLK923	Crack < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2270	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2271	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2272	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2273	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2274	WLK923	Crack < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2275	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2276	WLK923	Running Slope > 8.33%	Driveway/Driveway Flare	19.2%	LORNE ST SE - E	Other	8/18/2020
2277	WLK923	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2278	WLK923	Cross Slope > 5%			LORNE ST SE - E	Other	8/18/2020
2279	WLK803	No passing space			LORNE ST SE - W	Other	8/18/2020
2280	WLK803	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2281	WLK803	No passing space			LORNE ST SE - W	Other	8/18/2020
2282	WLK803	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2283	WLK803	Running Slope > 8.33%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2284	WLK803	Minor Cracking			LORNE ST SE - W	Other	8/18/2020
2285	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2286	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2287	WLK803	3% < Cross Slope < 5%	Root System		LORNE ST SE - W	Other	8/18/2020
2288	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2289	WLK803	Vertical displacement between 3/4 inch and 1-1/4 inch	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2290	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2291	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2292	WLK803	No passing space			LORNE ST SE - W	Other	8/18/2020
2293	WLK803	Moderate Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2294	WLK803	Cross Slope > 5%	Root System		LORNE ST SE - W	Other	8/18/2020
2295	WLK803	Vertical displacement < 3/4 inch	Root System		LORNE ST SE - W	Other	8/18/2020
2296	WLK803	Minor Cracking	Settlement		LORNE ST SE - W	Other	8/18/2020
2297	WLK803	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2298	WLK803	Vertical displacement < 3/4 inch	Root System		LORNE ST SE - W	Other	8/18/2020
2299	WLK803	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2300	WLK803	Severe Cracking	Root System		LORNE ST SE - W	Other	8/18/2020
2301	WLK803	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - W	Other	8/18/2020
2302	WLK802	Vertical displacement < 3/4 inch	Root System		LORNE ST SE - E	Other	8/18/2020
2303	WLK802	Severe Cracking	Settlement		LORNE ST SE - E	Other	8/18/2020
2304	WLK802	No passing space			LORNE ST SE - E	Other	8/18/2020
2305	WLK802	Severe Cracking	Root System		LORNE ST SE - E	Other	8/18/2020
2306	WLK802	Severe Cracking	Root System		LORNE ST SE - E	Other	8/18/2020
2307	WLK802	Severe Cracking			LORNE ST SE - E	Other	8/18/2020
2308	WLK802	Moderate Cracking	Root System		LORNE ST SE - E	Other	8/18/2020
2309	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2310	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2311	WLK802	Vertical displacement < 3/4 inch	Root System		LORNE ST SE - E	Other	8/18/2020
2312	WLK802	Vertical displacement < 3/4 inch			LORNE ST SE - E	Other	8/18/2020
2313	WLK802	Vertical displacement < 3/4 inch	Settlement		LORNE ST SE - E	Other	8/18/2020
2314	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2315	WLK802	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		LORNE ST SE - E	Other	8/18/2020
2316	WLK802	Crack < 3/4 inch	Root System		LORNE ST SE - E	Other	8/18/2020
2317	WLK802	Minor Cracking	Settlement		LORNE ST SE - E	Other	8/18/2020
2318	WLK802	Vertical displacement < 3/4 inch	Settlement		LORNE ST SE - E	Other	8/18/2020
2319	WLK802	Crack between 3/4 inch and 1-1/4 inch	Settlement		LORNE ST SE - E	Other	8/18/2020
2320	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2321	WLK802	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2322	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2323	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2324	WLK802	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2325	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2326	WLK802	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2327	WLK802	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2328	WLK802	Crack between 3/4 inch and 1-1/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2329	WLK802	Crack < 3/4 inch	Age		LORNE ST SE - E	Other	8/18/2020
2330	WLK802	Moderate Cracking	Age		LORNE ST SE - E	Other	8/18/2020
2331	WLK802	Moderate Cracking	Settlement		LORNE ST SE - E	Other	8/18/2020
2332	WLK802	Cross Slope > 5%	Driveway/Driveway Flare		LORNE ST SE - E	Other	8/18/2020
2333	WLK802	Minor Cracking			LORNE ST SE - E	Other	8/18/2020
2334	WLK939	No passing space			HARTMAN ST SE - S	Other	8/19/2020
2335	WLK939	3% < Cross Slope < 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2336	WLK939	Crack > 1-1/4 inch			HARTMAN ST SE - S	Other	8/19/2020
2337	WLK939	Crack < 3/4 inch			HARTMAN ST SE - S	Other	8/19/2020
2338	WLK939	3% < Cross Slope < 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2339	WLK939	Minor Cracking	Age		HARTMAN ST SE - S	Other	8/19/2020
2340	WLK939	Crack < 3/4 inch	Age		HARTMAN ST SE - S	Other	8/19/2020
2341	WLK939	3% < Cross Slope < 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2342	WLK939	Severe Cracking	Settlement		HARTMAN ST SE - S	Other	8/19/2020
2343	WLK939	Crack between 3/4 inch and 1-1/4 inch	Age		HARTMAN ST SE - S	Other	8/19/2020
2344	WLK939	Crack < 3/4 inch	Age		HARTMAN ST SE - S	Other	8/19/2020
2345	WLK939	Cross Slope > 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2346	WLK939	Vertical displacement < 3/4 inch	Settlement		HARTMAN ST SE - S	Other	8/19/2020
2347	WLK939	Crack between 3/4 inch and 1-1/4 inch			HARTMAN ST SE - S	Other	8/19/2020
2348	WLK939	Cross Slope > 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2349	WLK939	3% < Cross Slope < 5%			HARTMAN ST SE - S	Other	8/19/2020
2350	WLK939	3% < Cross Slope < 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2351	WLK939	Cross Slope > 5%	Driveway/Driveway Flare		HARTMAN ST SE - S	Other	8/19/2020
2352	WLK938	Cross Slope > 5%	Driveway/Driveway Flare		BRECH ST SE - W	Other	8/19/2020
2353	WLK938	Cross Slope > 5%	Driveway/Driveway Flare		BRECH ST SE - W	Other	8/19/2020
2354	WLK929	3% < Cross Slope < 5%			47TH AVE SE - S	Other	8/19/2020
2355	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2356	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2357	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2358	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2359	WLK929	Crack < 3/4 inch	Settlement		47TH AVE SE - S	Other	8/19/2020
2360	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2361	WLK929	Crack < 3/4 inch	Settlement		47TH AVE SE - S	Other	8/19/2020
2362	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2363	WLK928	Minor Cracking	Settlement		47TH AVE SE - S	Other	8/19/2020
2364	WLK928	Minor Cracking	Settlement		47TH AVE SE - S	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2365	WLK928	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2366	WLK928	5% < Running Slope < 8.33%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2367	WLK928	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2368	WLK928	Severe Cracking			47TH AVE SE - S	Other	8/19/2020
2369	WLK928	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2370	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2371	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2372	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2373	WLK929	Cross Slope > 5%	Driveway/Driveway Flare		47TH AVE SE - S	Other	8/19/2020
2374	WLK864	No passing space			SOUTH ST SE - N	Urban Collector	8/19/2020
2375	WLK864	Running Slope > 8.33%	Driveway/Driveway Flare		SOUTH ST SE - N	Urban Collector	8/19/2020
2376	WLK864	5% < Running Slope < 8.33%	Driveway/Driveway Flare		SOUTH ST SE - N	Urban Collector	8/19/2020
2377	WLK864	Crack < 3/4 inch	Age		SOUTH ST SE - N	Urban Collector	8/19/2020
2378	WLK867	No passing space			SOUTH ST SE - N	Urban Collector	8/19/2020
2379	WLK867	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - N	Urban Collector	8/19/2020
2380	WLK872	Cross Slope > 5%	Root System		SOUTH ST SE - N	Other	8/19/2020
2381	WLK872	Cross Slope > 5%	Root System		SOUTH ST SE - N	Other	8/19/2020
2382	WLK872	Crack < 3/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2383	WLK873	No passing space			CATHY CT SE - E	Other	8/19/2020
2384	WLK873	Crack between 3/4 inch and 1-1/4 inch	Age		CATHY CT SE - E	Other	8/19/2020
2385	WLK873	Cross Slope > 5%	Driveway/Driveway Flare		CATHY CT SE - E	Other	8/19/2020
2386	WLK873	Cross Slope > 5%	Driveway/Driveway Flare		CATHY CT SE - E	Other	8/19/2020
2387	WLK873	Cross Slope > 5%	Driveway/Driveway Flare		CATHY CT SE - E	Other	8/19/2020
2388	WLK874	Cross Slope > 5%	Driveway/Driveway Flare		CATHY CT SE - E	Other	8/19/2020
2389	WLK874	Crack < 3/4 inch	Age		CATHY CT SE - E	Other	8/19/2020
2390	WLK875	3% < Cross Slope < 5%			SOUTH ST SE - N	Other	8/19/2020
2391	WLK875	Crack < 3/4 inch	Age		SOUTH ST SE - N	Other	8/19/2020
2392	WLK875	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - N	Other	8/19/2020
2393	WLK875	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2394	WLK875	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2395	WLK875	Vertical displacement < 3/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2396	WLK875	Crack < 3/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2397	WLK875	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - N	Other	8/19/2020
2398	WLK875	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2399	WLK875	Vertical displacement < 3/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2400	WLK876	Cross Slope > 5%	Driveway/Driveway Flare		LOETE CT SE - E	Other	8/19/2020
2401	WLK876	Cross Slope > 5%	Driveway/Driveway Flare		LOETE CT SE - E	Other	8/19/2020
2402	WLK876	Crack > 1-1/4 inch	Settlement		LOETE CT SE - E	Other	8/19/2020
2403	WLK877	Cross Slope > 5%	Driveway/Driveway Flare		LOETE CT SE - E	Other	8/19/2020
2404	WLK877	3% < Cross Slope < 5%			LOETE CT SE - E	Other	8/19/2020
2405	WLK877	Minor Cracking			LOETE CT SE - E	Other	8/19/2020
2406	WLK878	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - N	Other	8/19/2020
2407	WLK878	Crack < 3/4 inch	Age		SOUTH ST SE - N	Other	8/19/2020
2408	WLK878	Crack < 3/4 inch	Settlement		SOUTH ST SE - N	Other	8/19/2020
2409	WLK878	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOUTH ST SE - N	Other	8/19/2020
2410	WLK878	No passing space			SOUTH ST SE - N	Other	8/19/2020
2411	WLK878	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - N	Other	8/19/2020
2412	WLK878	2% < Cross Slope < 3%	Root System		SOUTH ST SE - N	Other	8/19/2020
2413	WLK878	Minor Spalling	Age		SOUTH ST SE - N	Other	8/19/2020
2414	WLK881	3% < Cross Slope < 5%	Root System		SOUTH ST SE - W	Other	8/19/2020
2415	WLK882	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2416	WLK882	Moderate Cracking	Settlement		PIFER RD SE - W	Other	8/19/2020
2417	WLK882	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2418	WLK880	No passing space			SOUTH ST SE - S	Urban Collector	8/19/2020
2419	WLK880	3% < Cross Slope < 5%			SOUTH ST SE - S	Urban Collector	8/19/2020
2420	WLK880	Running Slope > 8.33%	Driveway/Driveway Flare		SOUTH ST SE - S	Urban Collector	8/19/2020
2421	WLK879	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - S	Urban Collector	8/19/2020
2422	WLK879	Crack < 3/4 inch	Age		SOUTH ST SE - S	Urban Collector	8/19/2020
2423	WLK879	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - S	Urban Collector	8/19/2020
2424	WLK866	No passing space			SOUTH ST SE - S	Urban Collector	8/19/2020
2425	WLK866	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - S	Urban Collector	8/19/2020
2426	WLK866	No passing space			SOUTH ST SE - S	Urban Collector	8/19/2020
2427	WLK866	Cross Slope > 5%	Driveway/Driveway Flare		SOUTH ST SE - S	Urban Collector	8/19/2020
2428	WLK852	No passing space			LLOYD ST SE - W	Other	8/19/2020
2429	WLK852	3% < Cross Slope < 5%	Root System		LLOYD ST SE - W	Other	8/19/2020
2430	WLK852	Vertical displacement < 3/4 inch	Root System		LLOYD ST SE - W	Other	8/19/2020
2431	WLK852	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - W	Other	8/19/2020
2432	WLK850	No passing space			PRIMROSE LN SE - S	Other	8/19/2020
2433	WLK850	3% < Cross Slope < 5%			PRIMROSE LN SE - S	Other	8/19/2020
2434	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2435	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2436	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2437	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2438	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2439	WLK850	Crack < 3/4 inch	Age		PRIMROSE LN SE - S	Other	8/19/2020
2440	WLK850	Crack < 3/4 inch	Age		PRIMROSE LN SE - S	Other	8/19/2020
2441	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2442	WLK850	No passing space			PRIMROSE LN SE - S	Other	8/19/2020
2443	WLK850	Running Slope > 8.33%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2444	WLK850	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - S	Other	8/19/2020
2445	WLK850	Crack < 3/4 inch			PRIMROSE LN SE - S	Other	8/19/2020
2446	WLK849	Crack between 3/4 inch and 1-1/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2447	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2448	WLK849	Crack < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2449	WLK849	Crack < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2450	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2451	WLK849	Crack > 1-1/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2452	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2453	WLK849	No passing space			PRIMROSE LN SE - N	Other	8/19/2020
2454	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2455	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2456	WLK849	Crack between 3/4 inch and 1-1/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2457	WLK849	Cross Slope > 5%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2458	WLK849	3% < Cross Slope < 5%			PRIMROSE LN SE - N	Other	8/19/2020
2459	WLK849	Crack < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2460	WLK849	Running Slope > 8.33%	Driveway/Driveway Flare		PRIMROSE LN SE - N	Other	8/19/2020
2461	WLK849	Vertical displacement < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2462	WLK849	Crack < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2463	WLK849	Crack < 3/4 inch	Age		PRIMROSE LN SE - N	Other	8/19/2020
2464	WLK849	Crack between 3/4 inch and 1-1/4 inch	Root System		PRIMROSE LN SE - N	Other	8/19/2020
2465	WLK845	No passing space			CLEVELAND AVE SE - W	Urban Collector	8/19/2020
2466	WLK853	Crack < 3/4 inch	Root System		LLOYD ST SE - W	Other	8/19/2020
2467	WLK853	Vertical displacement > 1-1/4 inch	Root System		LLOYD ST SE - W	Other	8/19/2020
2468	WLK853	Crack < 3/4 inch	Root System		LLOYD ST SE - W	Other	8/19/2020
2469	WLK853	Running Slope > 8.33%	Driveway/Driveway Flare		LLOYD ST SE - W	Other	8/19/2020
2470	WLK854	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - W	Other	8/19/2020
2471	WLK854	Crack < 3/4 inch	Age		LLOYD ST SE - W	Other	8/19/2020
2472	WLK847	Crack < 3/4 inch	Settlement		ENSLEY LN SE - S	Other	8/19/2020
2473	WLK847	No passing space			ENSLEY LN SE - S	Other	8/19/2020
2474	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2475	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2476	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2477	WLK847	Vertical displacement < 3/4 inch	Root System		ENSLEY LN SE - S	Other	8/19/2020
2478	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2479	WLK847	Vertical displacement < 3/4 inch	Settlement		ENSLEY LN SE - S	Other	8/19/2020
2480	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2481	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2482	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2483	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2484	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2485	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2486	WLK847	Vertical displacement < 3/4 inch			ENSLEY LN SE - S	Other	8/19/2020
2487	WLK847	No passing space			ENSLEY LN SE - S	Other	8/19/2020
2488	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2489	WLK847	Crack > 1-1/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2490	WLK847	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - S	Other	8/19/2020
2491	WLK847	Crack < 3/4 inch	Age		ENSLEY LN SE - S	Other	8/19/2020
2492	WLK846	Crack < 3/4 inch	Age		ENSLEY LN SE - N	Other	8/19/2020
2493	WLK846	Crack < 3/4 inch	Age		ENSLEY LN SE - N	Other	8/19/2020
2494	WLK846	Cross Slope > 5%			ENSLEY LN SE - N	Other	8/19/2020
2495	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2496	WLK846	Running Slope > 8.33%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2497	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2498	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2499	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2500	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2501	WLK846	Cross Slope > 5%	Driveway/Driveway Flare		ENSLEY LN SE - N	Other	8/19/2020
2502	WLK855	No passing space			LLOYD ST SE - W	Other	8/19/2020
2503	WLK855	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - W	Other	8/19/2020
2504	WLK861	No passing space			LLOYD ST SE - E	Other	8/19/2020
2505	WLK861	Crack < 3/4 inch	Age		LLOYD ST SE - E	Other	8/19/2020
2506	WLK861	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - E	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2507	WLK860	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - E	Other	8/19/2020
2508	WLK860	Cross Slope > 5%	Driveway/Driveway Flare		LLOYD ST SE - E	Other	8/19/2020
2509	WLK860	Running Slope > 8.33%	Driveway/Driveway Flare		LLOYD ST SE - E	Other	8/19/2020
2510	WLK860	Vertical displacement < 3/4 inch	Age		LLOYD ST SE - E	Other	8/19/2020
2511	WLK869	No passing space			ARMSTRONG AVE SE - E	Other	8/19/2020
2512	WLK869	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2513	WLK869	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2514	WLK869	No passing space			ARMSTRONG AVE SE - E	Other	8/19/2020
2515	WLK869	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2516	WLK868	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2517	WLK868	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2518	WLK868	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - E	Other	8/19/2020
2519	WLK868	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		ARMSTRONG AVE SE - E	Other	8/19/2020
2520	WLK863	Crack < 3/4 inch	Root System		ARMSTRONG AVE SE - W	Other	8/19/2020
2521	WLK863	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2522	WLK863	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2523	WLK863	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2524	WLK863	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2525	WLK863	Crack < 3/4 inch	Root System		ARMSTRONG AVE SE - W	Other	8/19/2020
2526	WLK862	2% < Cross Slope < 3%			KELSEY ST SE - S	Other	8/19/2020
2527	WLK862	Crack < 3/4 inch	Age		KELSEY ST SE - S	Other	8/19/2020
2528	WLK862	Crack < 3/4 inch	Age		KELSEY ST SE - S	Other	8/19/2020
2529	WLK862	Cross Slope > 5%	Driveway/Driveway Flare		KELSEY ST SE - S	Other	8/19/2020
2530	WLK862	Crack < 3/4 inch	Settlement		KELSEY ST SE - S	Other	8/19/2020
2531	WLK862	Cross Slope > 5%	Driveway/Driveway Flare		KELSEY ST SE - S	Other	8/19/2020
2532	WLK862	Crack < 3/4 inch	Age		KELSEY ST SE - S	Other	8/19/2020
2533	WLK862	No passing space			KELSEY ST SE - S	Other	8/19/2020
2534	WLK859	No passing space			KELSEY ST SE - N	Other	8/19/2020
2535	WLK859	Crack < 3/4 inch	Age		KELSEY ST SE - N	Other	8/19/2020
2536	WLK859	Crack < 3/4 inch	Age		KELSEY ST SE - N	Other	8/19/2020
2537	WLK859	Crack < 3/4 inch	Age		KELSEY ST SE - N	Other	8/19/2020
2538	WLK859	Crack between 3/4 inch and 1-1/4 inch	Age		KELSEY ST SE - N	Other	8/19/2020
2539	WLK859	Cross Slope > 5%	Driveway/Driveway Flare		KELSEY ST SE - N	Other	8/19/2020
2540	WLK858	Crack < 3/4 inch	Age		ARMSTRONG AVE SE - W	Other	8/19/2020
2541	WLK858	2% < Cross Slope < 3%	Root System		ARMSTRONG AVE SE - W	Other	8/19/2020
2542	WLK858	No passing space			ARMSTRONG AVE SE - W	Other	8/19/2020
2543	WLK858	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2544	WLK858	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2545	WLK858	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2546	WLK858	Cross Slope > 5%	Driveway/Driveway Flare		ARMSTRONG AVE SE - W	Other	8/19/2020
2547	WLK889	No passing space			HAWTHORNE ST SE - E	Other	8/19/2020
2548	WLK889	Crack < 3/4 inch	Age		HAWTHORNE ST SE - E	Other	8/19/2020
2549	WLK890	Crack < 3/4 inch	Age		40TH AVE SE - N	Other	8/19/2020
2550	WLK890	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - N	Other	8/19/2020
2551	WLK890	Vertical displacement < 3/4 inch			40TH AVE SE - N	Other	8/19/2020
2552	WLK890	Crack < 3/4 inch	Age		40TH AVE SE - N	Other	8/19/2020
2553	WLK890	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - N	Other	8/19/2020
2554	WLK890	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - N	Other	8/19/2020
2555	WLK890	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - N	Other	8/19/2020
2556	WLK890	Crack < 3/4 inch	Age		40TH AVE SE - N	Other	8/19/2020
2557	WLK890	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - N	Other	8/19/2020
2558	WLK891	Crack < 3/4 inch	Age		PIFER RD SE - W	Other	8/19/2020
2559	WLK891	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2560	WLK891	No passing space			PIFER RD SE - W	Other	8/19/2020
2561	WLK891	3% < Cross Slope < 5%			PIFER RD SE - W	Other	8/19/2020
2562	WLK891	No passing space			PIFER RD SE - W	Other	8/19/2020
2563	WLK891	Minor Cracking	Settlement		PIFER RD SE - W	Other	8/19/2020
2564	WLK891	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2565	WLK891	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2566	WLK891	Minor Cracking	Settlement		PIFER RD SE - W	Other	8/19/2020
2567	WLK891	Cross Slope > 5%			PIFER RD SE - W	Other	8/19/2020
2568	WLK891	Cross Slope > 5%	Driveway/Driveway Flare		PIFER RD SE - W	Other	8/19/2020
2569	WLK892	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2570	WLK892	3% < Cross Slope < 5%			MIDDLE ST SE - S	Other	8/19/2020
2571	WLK892	Vertical displacement < 3/4 inch	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2572	WLK892	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2573	WLK892	Crack < 3/4 inch	Root System		MIDDLE ST SE - S	Other	8/19/2020
2574	WLK892	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2575	WLK892	Vertical displacement < 3/4 inch	Root System		MIDDLE ST SE - S	Other	8/19/2020
2576	WLK892	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2577	WLK892	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2578	WLK886	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE ST SE - E	Other	8/19/2020
2579	WLK886	Crack < 3/4 inch	Age		HAWTHORNE ST SE - E	Other	8/19/2020
2580	WLK886	No passing space			HAWTHORNE ST SE - E	Other	8/19/2020
2581	WLK886	Crack between 3/4 inch and 1-1/4 inch	Root System		HAWTHORNE ST SE - E	Other	8/19/2020
2582	WLK887	Running Slope > 8.33%	Driveway/Driveway Flare		39TH CT SE - N	Other	8/19/2020
2583	WLK887	Crack < 3/4 inch	Age		39TH CT SE - N	Other	8/19/2020
2584	WLK887	3% < Cross Slope < 5%	Driveway/Driveway Flare		39TH CT SE - N	Other	8/19/2020
2585	WLK887	3% < Cross Slope < 5%	Driveway/Driveway Flare		39TH CT SE - N	Other	8/19/2020
2586	WLK887	5% < Running Slope < 8.33%	Driveway/Driveway Flare		39TH CT SE - N	Other	8/19/2020
2587	WLK887	Running Slope > 8.33%	Driveway/Driveway Flare		39TH CT SE - N	Other	8/19/2020
2588	WLK888	Running Slope > 8.33%	Driveway/Driveway Flare		39TH CT SE - S	Other	8/19/2020
2589	WLK888	Cross Slope > 5%	Driveway/Driveway Flare		39TH CT SE - S	Other	8/19/2020
2590	WLK888	Crack < 3/4 inch	Age		39TH CT SE - S	Other	8/19/2020
2591	WLK888	Running Slope > 8.33%	Driveway/Driveway Flare		39TH CT SE - S	Other	8/19/2020
2592	WLK888	Crack between 3/4 inch and 1-1/4 inch	Age		39TH CT SE - S	Other	8/19/2020
2593	WLK888	Crack between 3/4 inch and 1-1/4 inch	Age		39TH CT SE - S	Other	8/19/2020
2594	WLK888	Crack < 3/4 inch	Age		39TH CT SE - S	Other	8/19/2020
2595	WLK889	Crack < 3/4 inch	Age		HAWTHORNE ST SE - E	Other	8/19/2020
2596	WLK884	No passing space			HAWTHORNE ST SE - W	Other	8/19/2020
2597	WLK884	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2598	WLK884	Crack < 3/4 inch	Settlement		HAWTHORNE ST SE - W	Other	8/19/2020
2599	WLK884	Vertical displacement < 3/4 inch	Root System		HAWTHORNE ST SE - W	Other	8/19/2020
2600	WLK884	Crack < 3/4 inch	Settlement		HAWTHORNE ST SE - W	Other	8/19/2020
2601	WLK884	Running Slope > 8.33%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2602	WLK884	Running Slope > 8.33%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2603	WLK883	3% < Cross Slope < 5%			40TH AVE SE - S	Other	8/19/2020
2604	WLK883	Crack < 3/4 inch	Age		40TH AVE SE - S	Other	8/19/2020
2605	WLK883	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2606	WLK883	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2607	WLK883	Crack < 3/4 inch	Age		40TH AVE SE - S	Other	8/19/2020
2608	WLK883	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2609	WLK883	Running Slope > 8.33%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2610	WLK883	Crack < 3/4 inch	Age		40TH AVE SE - S	Other	8/19/2020
2611	WLK883	Crack < 3/4 inch	Age		40TH AVE SE - S	Other	8/19/2020
2612	WLK883	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2613	WLK883	Cross Slope > 5%	Driveway/Driveway Flare		40TH AVE SE - S	Other	8/19/2020
2614	WLK883	No passing space			40TH AVE SE - S	Other	8/19/2020
2615	WLK882	Crack < 3/4 inch	Root System		PIFER RD SE - W	Other	8/19/2020
2616	WLK882	Crack < 3/4 inch	Age		PIFER RD SE - W	Other	8/19/2020
2617	WLK884	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2618	WLK884	Running Slope > 8.33%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2619	WLK884	No passing space			HAWTHORNE ST SE - W	Other	8/19/2020
2620	WLK885	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2621	WLK885	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2622	WLK885	Crack < 3/4 inch	Age		HAWTHORNE ST SE - W	Other	8/19/2020
2623	WLK885	Running Slope > 8.33%	Driveway/Driveway Flare		HAWTHORNE ST SE - W	Other	8/19/2020
2624	WLK893	No passing space			MIDDLE ST SE - S	Other	8/19/2020
2625	WLK893	Crack < 3/4 inch	Age		MIDDLE ST SE - S	Other	8/19/2020
2626	WLK893	Crack < 3/4 inch	Age		MIDDLE ST SE - S	Other	8/19/2020
2627	WLK894	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - S	Other	8/19/2020
2628	WLK894	Cross Slope > 5%	Root System		MIDDLE ST SE - S	Other	8/19/2020
2629	WLK894	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MIDDLE ST SE - S	Other	8/19/2020
2630	WLK896	No passing space			MIDDLE ST SE - N	Other	8/19/2020
2631	WLK896	3% < Cross Slope < 5%			MIDDLE ST SE - N	Other	8/19/2020
2632	WLK896	Crack < 3/4 inch	Age		MIDDLE ST SE - N	Other	8/19/2020
2633	WLK896	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2634	WLK896	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2635	WLK896	Crack < 3/4 inch	Age		MIDDLE ST SE - N	Other	8/19/2020
2636	WLK896	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2637	WLK896	Crack < 3/4 inch	Age		MIDDLE ST SE - N	Other	8/19/2020
2638	WLK896	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2639	WLK895	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2640	WLK895	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2641	WLK895	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2642	WLK895	Moderate Cracking	Settlement		MIDDLE ST SE - N	Other	8/19/2020
2643	WLK895	Cross Slope > 5%	Driveway/Driveway Flare		MIDDLE ST SE - N	Other	8/19/2020
2644	WLK793	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2645	WLK793	No passing space			HAWTHORNE PL SE - W	Other	8/19/2020
2646	WLK793	Minor Cracking	Settlement		HAWTHORNE PL SE - W	Other	8/19/2020
2647	WLK793	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2648	WLK793	Severe Cracking	Settlement		HAWTHORNE PL SE - W	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2649	WLK793	Minor Cracking	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2650	WLK793	Vertical displacement between 3/4 inch and 1-1/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2651	WLK793	Crack between 3/4 inch and 1-1/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2652	WLK793	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2653	WLK793	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2654	WLK793	Vertical displacement < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2655	WLK793	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2656	WLK793	Vertical displacement < 3/4 inch	Root System		HAWTHORNE PL SE - W	Other	8/19/2020
2657	WLK792	Vertical displacement < 3/4 inch	Root System		HAWTHORNE PL SE - E	Other	8/19/2020
2658	WLK792	Vertical displacement < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2659	WLK792	Minor Cracking	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2660	WLK792	No passing space			HAWTHORNE PL SE - E	Other	8/19/2020
2661	WLK792	Minor Cracking	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2662	WLK792	Crack between 3/4 inch and 1-1/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2663	WLK792	Crack < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2664	WLK792	Vertical displacement < 3/4 inch	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2665	WLK1687	No passing space			HAWTHORNE PL SE - E	Other	8/19/2020
2666	WLK1687	3% < Cross Slope < 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2667	WLK1687	Crack < 3/4 inch	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2668	WLK1687	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2669	WLK1687	Cross Slope > 5%			HAWTHORNE PL SE - E	Other	8/19/2020
2670	WLK1687	3% < Cross Slope < 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2671	WLK1687	Crack < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2672	WLK1687	Crack < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2673	WLK1687	Crack < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2674	WLK1687	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2675	WLK1687	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2676	WLK1687	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2677	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2678	WLK1686	No passing space			HAWTHORNE PL SE - W	Other	8/19/2020
2679	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2680	WLK1686	Vertical displacement > 1-1/4 inch	Root System		HAWTHORNE PL SE - W	Other	8/19/2020
2681	WLK1686	Vertical displacement > 1-1/4 inch	Root System		HAWTHORNE PL SE - W	Other	8/19/2020
2682	WLK1686	Vertical displacement < 3/4 inch	Root System		HAWTHORNE PL SE - W	Other	8/19/2020
2683	WLK1686	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2684	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2685	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2686	WLK1686	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2687	WLK1686	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2688	WLK1686	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2689	WLK1686	Crack between 3/4 inch and 1-1/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2690	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2691	WLK1686	Crack < 3/4 inch	Age		HAWTHORNE PL SE - W	Other	8/19/2020
2692	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2693	WLK1686	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - W	Other	8/19/2020
2704	WLK795	Minor Cracking	Age		PEAR ST SE - E	Other	8/19/2020
2705	WLK794	Cross Slope > 5%	Driveway/Driveway Flare		QUINCE ST SE - E	Other	8/19/2020
2706	WLK794	Minor Cracking	Age		QUINCE ST SE - E	Other	8/19/2020
2707	WLK794	Vertical displacement > 1-1/4 inch	Settlement		QUINCE ST SE - E	Other	8/19/2020
2708	WLK794	3% < Cross Slope < 5%			QUINCE ST SE - E	Other	8/19/2020
2709	WLK794	Cross Slope > 5%	Driveway/Driveway Flare		QUINCE ST SE - E	Other	8/19/2020
2710	WLK1685	Moderate Cracking	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2711	WLK1685	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2712	WLK1685	Crack < 3/4 inch	Age		HAWTHORNE PL SE - E	Other	8/19/2020
2713	WLK1685	Crack < 3/4 inch	Settlement		HAWTHORNE PL SE - E	Other	8/19/2020
2714	WLK1685	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2715	WLK1685	No passing space			HAWTHORNE PL SE - E	Other	8/19/2020
2716	WLK1685	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2717	WLK1685	Cross Slope > 5%	Driveway/Driveway Flare		HAWTHORNE PL SE - E	Other	8/19/2020
2718	WLK1685	3% < Cross Slope < 5%			HAWTHORNE PL SE - E	Other	8/19/2020
2719	WLK991	2% < Cross Slope < 3%			WRANGLER DR SE - W	Other	8/19/2020
2720	WLK991	2% < Cross Slope < 3%			WRANGLER DR SE - W	Other	8/19/2020
2721	WLK992	3% < Cross Slope < 5%			WRANGLER DR SE - W	Other	8/19/2020
2722	WLK992	3% < Cross Slope < 5%			WRANGLER DR SE - W	Other	8/19/2020
2723	WLK993	3% < Cross Slope < 5%			64TH WAY SE - S	Other	8/19/2020
2724	WLK994	3% < Cross Slope < 5%			64TH WAY SE - N	Other	8/19/2020
2725	WLK994	2% < Cross Slope < 3%			64TH WAY SE - N	Other	8/19/2020
2726	WLK994	3% < Cross Slope < 5%			64TH WAY SE - N	Other	8/19/2020
2727	WLK995	3% < Cross Slope < 5%			64TH WAY SE - N	Other	8/19/2020
2728	WLK996	3% < Cross Slope < 5%			64TH WAY SE - N	Other	8/19/2020
2729	WLK998	2% < Cross Slope < 3%			65TH CT SE	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2730	WLK998	3% < Cross Slope < 5%			65TH CT SE	Other	8/19/2020
2731	WLK1000	Vertical displacement < 3/4 inch	Root System		WRANGLER DR SE - E	Other	8/19/2020
2732	WLK1002	Vertical displacement < 3/4 inch	Root System		65TH AVE SE - N	Other	8/19/2020
2733	WLK1003	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		65TH AVE SE - S	Other	8/19/2020
2734	WLK1003	Vertical displacement > 1-1/4 inch	Root System		65TH AVE SE - S	Other	8/19/2020
2735	WLK1003	2% < Cross Slope < 3%	Driveway/Driveway Flare		65TH AVE SE - S	Other	8/19/2020
2736	WLK990	5% < Running Slope < 8.33%	Driveway/Driveway Flare		65TH AVE SE - S	Other	8/19/2020
2737	WLK990	5% < Running Slope < 8.33%	Driveway/Driveway Flare		65TH AVE SE - S	Other	8/19/2020
2738	WLK990	5% < Running Slope < 8.33%	Driveway/Driveway Flare		65TH AVE SE - S	Other	8/19/2020
2739	WLK989	5% < Running Slope < 8.33%	Driveway/Driveway Flare		65TH AVE SE - S	Other	8/19/2020
2740	WLK989	Minor Cracking	Settlement		65TH AVE SE - S	Other	8/19/2020
2741	WLK1004	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2742	WLK1022	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2743	WLK1022	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2744	WLK1022	Crack < 3/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2745	WLK1022	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2746	WLK1022	Running Slope > 8.33%	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2747	WLK1022	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2748	WLK1022	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2749	WLK1019	Vertical displacement < 3/4 inch	Root System		RIVERDALE DR SE - E	Other	8/19/2020
2750	WLK1035	Vertical displacement > 1-1/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2751	WLK1035	Vertical displacement > 1-1/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2752	WLK1035	Vertical displacement < 3/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2753	WLK1033	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		69TH AVE SE - S	Other	8/19/2020
2754	WLK1033	3% < Cross Slope < 5%			69TH AVE SE - S	Other	8/19/2020
2755	WLK1032	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2756	WLK1025	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2757	WLK1025	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2758	WLK1025	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2759	WLK1025	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2760	WLK1025	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2761	WLK1025	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2762	WLK1025	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2763	WLK1024	Vertical displacement > 1-1/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2764	WLK1024	Vertical displacement > 1-1/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2765	WLK1024	Crack < 3/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2766	WLK1024	Running Slope > 8.33%	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2767	WLK1024	Crack < 3/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2768	WLK1023	Vertical displacement < 3/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2769	WLK1023	Vertical displacement < 3/4 inch	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2770	WLK1023	Cross Slope > 5%	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2771	WLK1023	Moderate Cracking	Root System		RIVERDALE DR SE - S	Other	8/19/2020
2772	WLK1027	Vertical displacement > 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2773	WLK1027	Vertical displacement > 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2774	WLK1027	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2775	WLK1026	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2776	WLK1026	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2777	WLK1026	Vertical displacement > 1-1/4 inch	Root System		ZENDA DR SE - E	Other	8/19/2020
2778	WLK1028	Vertical displacement < 3/4 inch	Root System		ZENDA DR SE - W	Other	8/19/2020
2779	WLK1012	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2780	WLK1012	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2781	WLK1007	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2782	WLK1006	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2783	WLK1006	Vertical displacement > 1-1/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2784	WLK1006	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2785	WLK1006	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2786	WLK1006	Crack < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2787	WLK1006	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2788	WLK1006	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2789	WLK1006	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2790	WLK1006	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - W	Other	8/19/2020
2791	WLK1005	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2792	WLK1005	Vertical displacement > 1-1/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2793	WLK1005	Vertical displacement > 1-1/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2794	WLK1005	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2795	WLK1008	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2796	WLK1008	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2797	WLK1008	Minor Cracking	Root System		DESPERADO DR SE - E	Other	8/19/2020
2798	WLK1008	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2799	WLK1008	Vertical displacement < 3/4 inch	Root System		DESPERADO DR SE - E	Other	8/19/2020
2800	WLK1009	Minor Cracking	Root System		69TH CT SE - N	Other	8/19/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2801	WLK1010	Vertical displacement < 3/4 inch	Root System		69TH CT SE - N	Other	8/19/2020
2802	WLK1038	Vertical displacement < 3/4 inch	Root System		MUNN LAKE DR SE - E	Other	8/19/2020
2803	WLK1038	Vertical displacement < 3/4 inch	Root System		MUNN LAKE DR SE - E	Other	8/19/2020
2804	WLK1038	Vertical displacement < 3/4 inch	Root System		MUNN LAKE DR SE - E	Other	8/19/2020
2805	WLK1032	Vertical displacement < 3/4 inch	Root System		69TH AVE SE - N	Other	8/19/2020
2806	WLK1030	Vertical displacement < 3/4 inch	Root System		MUNN LAKE DR SE - E	Other	8/19/2020
2807	WLK1029	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MUNN LAKE DR SE - W		8/19/2020
2808	WLK1039	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MUNN LAKE DR SE - W		8/19/2020
2809	WLK1039	Running Slope > 8.33%	Root System		MUNN LAKE DR SE - W		8/19/2020
2810	WLK1039	Crack between 3/4 inch and 1-1/4 inch	Root System		MUNN LAKE DR SE - W		8/19/2020
2811	WLK1043	Vertical displacement < 3/4 inch	Root System		ALTA VISTA DR SE - W	Other	8/19/2020
2812	WLK1050	Vertical displacement < 3/4 inch	Root System		ALTA VISTA DR SE - E		8/19/2020
2813	WLK1050	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ALTA VISTA DR SE - E		8/19/2020
2814	WLK1050	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ALTA VISTA DR SE - E		8/19/2020
2815	WLK1050	Vertical displacement > 1-1/4 inch	Root System		ALTA VISTA DR SE - E		8/19/2020
2816	WLK1054	Vertical displacement < 3/4 inch	Root System		PLEASURE DR SE - N	Other	8/19/2020
2817	WLK1054	Vertical displacement < 3/4 inch	Root System		PLEASURE DR SE - N	Other	8/19/2020
2818	WLK1054	Vertical displacement < 3/4 inch	Root System		PLEASURE DR SE - N	Other	8/19/2020
2819	WLK1054	Vertical displacement < 3/4 inch	Root System		PLEASURE DR SE - N	Other	8/19/2020
2820	WLK1053	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TAHOE DR SE - W		8/19/2020
2821	WLK1053	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TAHOE DR SE - W		8/19/2020
2822	WLK1055	Vertical displacement < 3/4 inch	Root System				8/19/2020
2823	WLK1055	Vertical displacement < 3/4 inch	Root System				8/19/2020
2824	WLK1055	Vertical displacement < 3/4 inch	Root System				8/19/2020
2825	WLK1055	Vertical displacement < 3/4 inch	Root System				8/19/2020
2826	WLK98	5% < Running Slope < 8.33%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	8/20/2020
2828	WLK59	3% < Cross Slope < 5%			TROSPER RD SW - S	Principal Arterial	8/20/2020
2829	WLK59	3% < Cross Slope < 5%			TROSPER RD SW - S	Principal Arterial	8/20/2020
2830	WLK60	Crack < 3/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2831	WLK1143	Crack < 3/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2832	WLK1143	Crack < 3/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2833	WLK1143	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Principal Arterial	8/20/2020
2834	WLK1143	Crack < 3/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2835	WLK1143	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Principal Arterial	8/20/2020
2836	WLK1143	Crack < 3/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2837	WLK1143	Crack between 3/4 inch and 1-1/4 inch	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2838	WLK1143	Minor Cracking	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2839	WLK1143	Minor Cracking	Age		TROSPER RD SW - S	Principal Arterial	8/20/2020
2840	WLK1142	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Principal Arterial	8/20/2020
2841	WLK1142	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Principal Arterial	8/20/2020
2842	WLK61	Crack < 3/4 inch	Age		TROSPER RD SW - N	Principal Arterial	8/20/2020
2843	WLK62	3% < Cross Slope < 5%			TROSPER RD SW - N	Principal Arterial	8/20/2020
2844	WLK62	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - N	Principal Arterial	8/20/2020
2845	WLK62	5% < Running Slope < 8.33%	Driveway/Driveway Flare		TROSPER RD SW - N	Principal Arterial	8/20/2020
2846	WLK62	Crack < 3/4 inch	Age		TROSPER RD SW - N	Principal Arterial	8/20/2020
2847	WLK305	Hole between 3/4 inch and 1-1/4 inch			TROSPER RD SW - N	Minor Arterial	8/20/2020
2848	WLK310	Running Slope > 8.33%	Driveway/Driveway Flare			Other	8/20/2020
2849	WLK310	Running Slope > 8.33%	Driveway/Driveway Flare			Other	8/20/2020
2850	WLK310	Vertical displacement is in the vicinity of a sensitive location				Other	8/20/2020
2851	WLK310	Crack < 3/4 inch	Age			Other	8/20/2020
2852	WLK310	Vertical displacement is in the vicinity of a sensitive location				Other	8/20/2020
2859	WLK310	No passing space				Other	8/20/2020
2860	WLK309	Crack > 1-1/4 inch	Age		MILLER ST SW - S	Other	8/20/2020
2861	WLK259	3% < Cross Slope < 5%			TROSPER RD SW - N	Minor Arterial	8/20/2020
2862	WLK259	3% < Cross Slope < 5%			TROSPER RD SW - N	Minor Arterial	8/20/2020
2863	WLK259	Crack < 3/4 inch	Settlement		TROSPER RD SW - N	Minor Arterial	8/20/2020
2864	WLK258	3% < Cross Slope < 5%			TROSPER RD SW - N	Minor Arterial	8/20/2020
2865	WLK257	Cross Slope > 5%			TROSPER RD SW - N	Minor Arterial	8/20/2020
2866	WLK257	3% < Cross Slope < 5%			TROSPER RD SW - N	Minor Arterial	8/20/2020
2867	WLK107	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	8/20/2020
2868	WLK107	2% < Cross Slope < 3%			TROSPER RD SW - S	Minor Arterial	8/20/2020
2869	WLK116	2% < Cross Slope < 3%			TROSPER RD SW - S	Minor Arterial	8/20/2020
2870	WLK116	Cross Slope > 5%	Driveway/Driveway Flare		TROSPER RD SW - S	Minor Arterial	8/20/2020
2871	WLK119	3% < Cross Slope < 5%			TROSPER RD SW - S	Minor Arterial	8/20/2020
2872	WLK119	3% < Cross Slope < 5%			TROSPER RD SW - S	Minor Arterial	8/20/2020
2873	WLK119	2% < Cross Slope < 3%			TROSPER RD SW - S	Minor Arterial	8/20/2020
2874	WLK118	3% < Cross Slope < 5%			TROSPER LAKE ST SW - W	Other	8/20/2020
2875	WLK118	No passing space			TROSPER LAKE ST SW - W	Other	8/20/2020
2876	WLK118	Crack < 3/4 inch	Age		TROSPER LAKE ST SW - W	Other	8/20/2020
2877	WLK118	2% < Cross Slope < 3%			TROSPER LAKE ST SW - W	Other	8/20/2020
2878	WLK111	No passing space			56TH AVE SW - S	Other	8/20/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2879	WLK110	3% < Cross Slope < 5%			56TH AVE SW - S	Other	8/20/2020
2880	WLK110	Vertical displacement < 3/4 inch	Root System		56TH AVE SW - S	Other	8/20/2020
2881	WLK114	Crack < 3/4 inch	Age		56TH AVE SW - N	Other	8/20/2020
2882	WLK114	Vertical displacement < 3/4 inch			56TH AVE SW - N	Other	8/20/2020
2883	WLK114	Crack < 3/4 inch	Root System		56TH AVE SW - N	Other	8/20/2020
2884	WLK117	No passing space			TROSPER LAKE ST SW - E	Other	8/20/2020
2885	WLK117	3% < Cross Slope < 5%			TROSPER LAKE ST SW - E	Other	8/20/2020
2886	WLK117	Crack < 3/4 inch	Root System		TROSPER LAKE ST SW - E	Other	8/20/2020
2887	WLK117	Crack < 3/4 inch	Root System		TROSPER LAKE ST SW - E	Other	8/20/2020
2888	WLK117	Cross Slope > 5%			TROSPER LAKE ST SW - E	Other	8/20/2020
2889	WLK117	3% < Cross Slope < 5%			TROSPER LAKE ST SW - E	Other	8/20/2020
2890	WLK63	3% < Cross Slope < 5%			2ND AVE SW - E	Minor Arterial	8/20/2020
2891	WLK63	3% < Cross Slope < 5%			2ND AVE SW - E	Minor Arterial	8/20/2020
2892	WLK63	Crack < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2893	WLK63	Crack < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2894	WLK63	Crack < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2895	WLK63	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2896	WLK63	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2897	WLK63	Vertical displacement > 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2898	WLK63	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2899	WLK63	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2900	WLK64	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2901	WLK63	Vertical displacement < 3/4 inch			2ND AVE SW - E	Minor Arterial	8/20/2020
2902	WLK63	3% < Cross Slope < 5%			2ND AVE SW - E	Minor Arterial	8/20/2020
2903	WLK63	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2904	WLK63	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2905	WLK63	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2906	WLK69	Minor Cracking	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2907	WLK69	Cross Slope > 5%	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2908	WLK69	5% < Running Slope < 8.33%	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2909	WLK69	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2910	WLK69	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
2911	WLK69	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2912	WLK69	2% < Cross Slope < 3%			2ND AVE SW - E	Minor Arterial	8/20/2020
2913	WLK69	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2914	WLK69	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2915	WLK69	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2916	WLK74	Vertical displacement > 1-1/4 inch		plants in sidewalk	I ST SW - N	Other	8/20/2020
2917	WLK72	Vertical displacement < 3/4 inch			2ND AVE SW - E	Minor Arterial	8/20/2020
2918	WLK73	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2919	WLK78	Crack < 3/4 inch	Age		2ND AVE SW - E	Minor Arterial	8/20/2020
2920	WLK78	2% < Cross Slope < 3%			2ND AVE SW - E	Minor Arterial	8/20/2020
2921	WLK78	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - E	Minor Arterial	8/20/2020
2922	WLK79	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
2923	WLK79	Minor Cracking	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
2924	WLK79	Crack between 3/4 inch and 1-1/4 inch	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
2925	WLK79	Minor Cracking	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
2926	WLK80	Crack between 3/4 inch and 1-1/4 inch	Settlement		LINWOOD AVE SW - N	Urban Collector	8/20/2020
2927	WLK80	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
2928	WLK81	Minor Cracking	Settlement		2ND AVE SW - E	Minor Arterial	8/20/2020
2929	WLK93	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2930	WLK93	No passing space			2ND AVE SW - W	Minor Arterial	8/20/2020
2931	WLK93	Crack between 3/4 inch and 1-1/4 inch	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2932	WLK93	Cross Slope > 5%			2ND AVE SW - W	Minor Arterial	8/20/2020
2933	WLK93	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2934	WLK93	Minor Cracking			2ND AVE SW - W	Minor Arterial	8/20/2020
2935	WLK93	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2936	WLK91	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2937	WLK91	Crack > 1-1/4 inch	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2938	WLK91	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2939	WLK91	3% < Cross Slope < 5%			2ND AVE SW - W	Minor Arterial	8/20/2020
2940	WLK91	Minor Cracking			2ND AVE SW - W	Minor Arterial	8/20/2020
2941	WLK90	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2942	WLK90	Minor Cracking	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2943	WLK90	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2944	WLK90	Crack < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2945	WLK90	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2946	WLK90	Minor Cracking	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2947	WLK90	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2948	WLK90	Crack < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
2949	WLK90	Crack < 3/4 inch			2ND AVE SW - W	Minor Arterial	8/20/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
2950	WLK90	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2951	WLK418	Vertical displacement < 3/4 inch			B ST SW - S	Other	8/20/2020
2952	WLK89	Vertical displacement between 3/4 inch and 1-1/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2953	WLK89	Minor Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2954	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2955	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2956	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2957	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2958	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2959	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2960	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2961	WLK89	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2962	WLK402	No passing space			C ST SW - S	Other	8/20/2020
2963	WLK402	Cross Slope > 5%			C ST SW - S	Other	8/20/2020
2964	WLK401	No passing space			D ST SW - S	Other	8/20/2020
2965	WLK87	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2966	WLK87	Vertical displacement between 3/4 inch and 1-1/4 inch	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2967	WLK385	Severe Cracking	Settlement		E ST SW - S	Other	8/20/2020
2968	WLK86	Minor Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2969	WLK86	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2970	WLK86	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2971	WLK86	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2972	WLK86	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2973	WLK86	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2974	WLK85	No passing space			2ND AVE SW - W	Minor Arterial	8/20/2020
2975	WLK85	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2976	WLK85	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2977	WLK85	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2978	WLK85	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2979	WLK85	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2980	WLK85	3% < Cross Slope < 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2981	WLK85	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2982	WLK84	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2983	WLK84	3% < Cross Slope < 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
2984	WLK84	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2985	WLK84	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2986	WLK84	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2987	WLK84	Moderate Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2988	WLK84	Vertical displacement < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2989	WLK84	Moderate Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2990	WLK83	Minor Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2991	WLK83	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2992	WLK83	Crack < 3/4 inch	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
2993	WLK83	2% < Cross Slope < 3%			2ND AVE SW - W	Minor Arterial	8/20/2020
2994	WLK83	No passing space			2ND AVE SW - W	Minor Arterial	8/20/2020
2995	WLK83	Moderate Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2996	WLK83	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2997	WLK83	Vertical displacement < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2998	WLK83	Vertical displacement < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
2999	WLK83	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3000	WLK83	Severe Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3001	WLK71	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3002	WLK71	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3003	WLK71	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3004	WLK71	2% < Cross Slope < 3%			2ND AVE SW - W	Minor Arterial	8/20/2020
3005	WLK71	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3006	WLK70	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3007	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3008	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3009	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3010	WLK68	Crack between 3/4 inch and 1-1/4 inch	Root System			Other	8/20/2020
3011	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3012	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3013	WLK68	Cross Slope > 5%	Driveway/Driveway Flare			Other	8/20/2020
3014	WLK68	3% < Cross Slope < 5%				Other	8/20/2020
3015	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3016	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3017	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3018	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3019	WLK64	Vertical displacement < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
3020	WLK64	Crack < 3/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3021	WLK64	Crack between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - W	Minor Arterial	8/20/2020
3022	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3023	WLK64	Minor Cracking	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
3024	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3025	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3026	WLK64	Crack < 3/4 inch	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
3027	WLK64	3% < Cross Slope < 5%			2ND AVE SW - W	Minor Arterial	8/20/2020
3028	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3029	WLK64	Crack < 3/4 inch	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3030	WLK64	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		2ND AVE SW - W	Minor Arterial	8/20/2020
3031	WLK64	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3032	WLK64	Minor Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3033	WLK64	Severe Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3034	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3035	WLK64	Severe Cracking	Age		2ND AVE SW - W	Minor Arterial	8/20/2020
3036	WLK64	Minor Cracking			2ND AVE SW - W	Minor Arterial	8/20/2020
3037	WLK64	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/20/2020
3038	WLK63	Minor Cracking			2ND AVE SW - E	Minor Arterial	8/20/2020
3039	WLK63	Crack between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
3040	WLK63	Crack between 3/4 inch and 1-1/4 inch	Age		2ND AVE SW - E	Minor Arterial	8/20/2020
3041	WLK63	Crack between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
3042	WLK63	Crack between 3/4 inch and 1-1/4 inch	Root System		2ND AVE SW - E	Minor Arterial	8/20/2020
3043	WLK65	No passing space			2ND AVE SW - W	Other	8/20/2020
3044	WLK65	Crack < 3/4 inch	Root System		2ND AVE SW - W	Other	8/20/2020
3045	WLK65	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Other	8/20/2020
3046	WLK65	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Other	8/20/2020
3047	WLK65	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Other	8/20/2020
3048	WLK65	Crack < 3/4 inch	Settlement		2ND AVE SW - W	Other	8/20/2020
3049	WLK66	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Other	8/20/2020
3050	WLK66	Crack < 3/4 inch	Age		2ND AVE SW - W	Other	8/20/2020
3051	WLK66	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Other	8/20/2020
3052	WLK67	Cross Slope > 5%	Driveway/Driveway Flare		LITTLE ST SW - N	Other	8/20/2020
3053	WLK67	Crack < 3/4 inch	Age		LITTLE ST SW - N	Other	8/20/2020
3054	WLK67	Crack < 3/4 inch	Age		LITTLE ST SW - N	Other	8/20/2020
3055	WLK67	Crack < 3/4 inch	Age		LITTLE ST SW - N	Other	8/20/2020
3056	WLK67	Cross Slope > 5%	Driveway/Driveway Flare		LITTLE ST SW - N	Other	8/20/2020
3057	WLK67	No passing space			LITTLE ST SW - N	Other	8/20/2020
3058	WLK67	Crack < 3/4 inch	Settlement		LITTLE ST SW - N	Other	8/20/2020
3059	WLK334	2% < Cross Slope < 3%			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3060	WLK334	Minor Cracking			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3061	WLK335	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3062	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3063	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3064	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3065	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3066	WLK327	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3067	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3068	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3069	WLK327	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3070	WLK327	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3071	WLK327	3% < Cross Slope < 5%			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3072	WLK328	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3073	WLK328	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3074	WLK328	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3075	WLK328	Crack between 3/4 inch and 1-1/4 inch	Settlement		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3076	WLK328	3% < Cross Slope < 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3077	WLK328	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3078	WLK328	Vertical displacement < 3/4 inch			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3079	WLK328	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3080	WLK329	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3081	WLK330	Vertical displacement > 1-1/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3082	WLK330	Vertical displacement > 1-1/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3083	WLK331	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3084	WLK331	Vertical displacement < 3/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3085	WLK331	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3086	WLK331	Vertical displacement > 1-1/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3087	WLK331	Vertical displacement > 1-1/4 inch	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3088	WLK317	3% < Cross Slope < 5%			LINWOOD AVE SW - S	Urban Collector	8/20/2020
3089	WLK317	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3090	WLK317	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3091	WLK317	No passing space			LINWOOD AVE SW - S	Urban Collector	8/20/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3092	WLK317	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3093	WLK317	Crack > 1-1/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3094	WLK317	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3095	WLK318	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3096	WLK318	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3097	WLK318	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3098	WLK318	Crack > 1-1/4 inch	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3099	WLK318	Cross Slope > 5%	Root System		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3100	WLK318	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3101	WLK318	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3102	WLK318	Vertical displacement < 3/4 inch	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3103	WLK318	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3104	WLK321	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3105	WLK321	3% < Cross Slope < 5%			LINWOOD AVE SW - S	Urban Collector	8/20/2020
3106	WLK321	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3107	WLK321	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3108	WLK321	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3109	WLK322	Moderate Cracking	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3110	WLK322	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3111	WLK322	No passing space			LINWOOD AVE SW - S	Urban Collector	8/20/2020
3112	WLK322	Minor Cracking	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3113	WLK322	Vertical displacement < 3/4 inch	Root System		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3114	WLK322	Vertical displacement < 3/4 inch	Root System		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3115	WLK322	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3116	WLK322	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3117	WLK322	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3118	WLK324	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3119	WLK324	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3120	WLK324	Vertical displacement < 3/4 inch	Root System		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3121	WLK324	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3122	WLK324	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3123	WLK324	Crack < 3/4 inch	Age		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3124	WLK324	Minor Cracking	Settlement		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3125	WLK324	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - S	Urban Collector	8/20/2020
3126	WLK326	3% < Cross Slope < 5%	Root System		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3127	WLK340	3% < Cross Slope < 5%	Root System		5TH AVE SW - E	Other	8/20/2020
3128	WLK372	3% < Cross Slope < 5%			7TH AVE SW - E	Urban Collector	8/20/2020
3129	WLK372	3% < Cross Slope < 5%			7TH AVE SW - E	Urban Collector	8/20/2020
3130	WLK371	Crack < 3/4 inch	Age		H ST SW - N	Other	8/20/2020
3131	WLK329	2% < Cross Slope < 3%			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3132	WLK329	Running Slope > 8.33%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3133	WLK329	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3134	WLK329	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3135	WLK329	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3136	WLK329	3% < Cross Slope < 5%			LINWOOD AVE SW - N	Urban Collector	8/20/2020
3137	WLK329	Minor Cracking	Settlement		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3138	WLK329	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3139	WLK329	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3140	WLK329	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3141	WLK329	Cross Slope > 5%	Driveway/Driveway Flare		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3142	WLK329	Crack < 3/4 inch	Age		LINWOOD AVE SW - N	Urban Collector	8/20/2020
3143	WLK347	Vertical displacement < 3/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/20/2020
3144	WLK347	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3145	WLK347	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/20/2020
3146	WLK347	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3147	WLK347	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3148	WLK347	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/20/2020
3149	WLK347	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3150	WLK347	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3151	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3152	WLK348	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/20/2020
3153	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3154	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3155	WLK348	Vertical displacement < 3/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/20/2020
3156	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3157	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3158	WLK348	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3159	WLK373	Minor Cracking			7TH AVE SW - W	Urban Collector	8/20/2020
3160	WLK373	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/20/2020
3161	WLK592	Vertical displacement < 3/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/20/2020
3162	WLK593	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/20/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3163	WLK593	Vertical displacement < 3/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/20/2020
3164	WLK593	2% < Cross Slope < 3%			7TH AVE SW - W	Urban Collector	8/20/2020
3165	WLK593	Crack < 3/4 inch	Settlement		7TH AVE SW - W	Urban Collector	8/20/2020
3166	WLK593	Crack < 3/4 inch	Settlement		7TH AVE SW - W	Urban Collector	8/20/2020
3167	WLK592	Vertical displacement < 3/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/20/2020
3168	WLK591	Cross Slope > 5%	Driveway/Driveway Flare		BARNES BLVD SW - W	Urban Collector	8/20/2020
3169	WLK591	Minor Cracking	Age		BARNES BLVD SW - W	Urban Collector	8/20/2020
3170	WLK591	Crack < 3/4 inch	Age		BARNES BLVD SW - W	Urban Collector	8/20/2020
3171	WLK590	Crack < 3/4 inch	Age		BARNES BLVD SW - W	Urban Collector	8/20/2020
3172	WLK590	Minor Cracking	Root System		BARNES BLVD SW - W	Urban Collector	8/20/2020
3173	WLK590	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - W	Urban Collector	8/20/2020
3174	WLK590	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - W	Urban Collector	8/20/2020
3175	WLK590	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - W	Urban Collector	8/20/2020
3176	WLK590	Crack < 3/4 inch	Settlement		BARNES BLVD SW - W	Urban Collector	8/20/2020
3177	WLK590	Cross Slope > 5%	Driveway/Driveway Flare		BARNES BLVD SW - W	Urban Collector	8/20/2020
3178	WLK590	Minor Cracking			BARNES BLVD SW - W	Urban Collector	8/20/2020
3179	WLK590	Minor Cracking	Settlement		BARNES BLVD SW - W	Urban Collector	8/20/2020
3180	WLK590	Minor Cracking	Settlement		BARNES BLVD SW - W	Urban Collector	8/20/2020
3181	WLK590	Minor Cracking	Settlement		BARNES BLVD SW - W	Urban Collector	8/20/2020
3182	WLK590	Cross Slope > 5%	Driveway/Driveway Flare		BARNES BLVD SW - W	Urban Collector	8/20/2020
3183	WLK590	Minor Cracking	Settlement		BARNES BLVD SW - W	Urban Collector	8/20/2020
3184	WLK590	Crack between 3/4 inch and 1-1/4 inch	Root System		BARNES BLVD SW - W	Urban Collector	8/20/2020
3185	WLK594	Crack between 3/4 inch and 1-1/4 inch	Root System		G ST SW - S	Other	8/20/2020
3186	WLK594	Minor Spalling			G ST SW - S	Other	8/20/2020
3187	WLK604	Vertical displacement < 3/4 inch	Root System		G ST SW - E	Other	8/20/2020
3188	WLK605	Crack < 3/4 inch	Root System		G ST SW - W	Other	8/20/2020
3189	WLK606	Minor Cracking			G ST SW - N	Other	8/20/2020
3190	WLK606	Minor Cracking			G ST SW - N	Other	8/20/2020
3191	WLK611	Crack < 3/4 inch	Root System		G ST SW - N	Other	8/20/2020
3192	WLK611	Vertical displacement < 3/4 inch	Root System		G ST SW - N	Other	8/20/2020
3193	WLK374	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/20/2020
3194	WLK364	No passing space			G ST SW - S	Other	8/20/2020
3195	WLK364	Cross Slope > 5%	Driveway/Driveway Flare		G ST SW - S	Other	8/20/2020
3196	WLK364	Crack < 3/4 inch	Age		G ST SW - S	Other	8/20/2020
3197	WLK364	Crack < 3/4 inch	Age		G ST SW - S	Other	8/20/2020
3198	WLK364	Crack between 3/4 inch and 1-1/4 inch	Age		G ST SW - S	Other	8/20/2020
3199	WLK380	Cross Slope > 5%	Driveway/Driveway Flare		G ST SW - N	Other	8/20/2020
3200	WLK596	Crack < 3/4 inch	Root System		8TH AVE SW - E	Other	8/25/2020
3201	WLK596	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		8TH AVE SW - E	Other	8/25/2020
3202	WLK596	3% < Cross Slope < 5%			8TH AVE SW - E	Other	8/25/2020
3203	WLK595	Crack < 3/4 inch	Root System		8TH AVE SW - E	Other	8/25/2020
3204	WLK595	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		8TH AVE SW - E	Other	8/25/2020
3205	WLK597	Vertical displacement < 3/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3206	WLK597	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3207	WLK597	Vertical displacement > 1-1/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3208	WLK597	Vertical displacement < 3/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3209	WLK601	Vertical displacement < 3/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3210	WLK602	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3211	WLK603	Vertical displacement < 3/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3212	WLK603	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		8TH AVE SW - W	Other	8/25/2020
3213	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3214	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3215	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3216	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3217	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3218	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3219	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3220	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3221	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3222	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3223	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3224	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3225	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3226	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3227	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3228	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3229	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3230	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3231	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3232	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020
3233	WLK609	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - E	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3305	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3306	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3307	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3308	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3309	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3310	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3311	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3312	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3313	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3314	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3315	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3316	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3317	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3318	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3319	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3320	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3321	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3322	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3323	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3324	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3325	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3326	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3327	WLK608	Cross Slope > 5%	Driveway/Driveway Flare		EBBETS DR SW - W	Other	8/25/2020
3328	WLK344	No passing space			6TH AVE SW - W	Other	8/25/2020
3329	WLK344	Minor Cracking	Age		6TH AVE SW - W	Other	8/25/2020
3330	WLK344	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/25/2020
3331	WLK351	Crack < 3/4 inch	Settlement		6TH AVE SW - W	Other	8/25/2020
3332	WLK351	Minor Cracking			6TH AVE SW - W	Other	8/25/2020
3333	WLK370	Running Slope > 8.33%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/25/2020
3334	WLK342	No passing space			I ST SW - S	Other	8/25/2020
3335	WLK344	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/25/2020
3336	WLK341	Crack between 3/4 inch and 1-1/4 inch	Root System		5TH AVE SW - W	Other	8/25/2020
3337	WLK341	No passing space			5TH AVE SW - W	Other	8/25/2020
3338	WLK341	Minor Cracking	Age		5TH AVE SW - W	Other	8/25/2020
3339	WLK341	Running Slope > 8.33%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/25/2020
3340	WLK341	Crack < 3/4 inch	Age		5TH AVE SW - W	Other	8/25/2020
3341	WLK354	Vertical displacement between 3/4 inch and 1-1/4 inch		plants in sidewalk cracks	5TH AVE SW - W	Other	8/25/2020
3342	WLK354	Crack < 3/4 inch	Age		5TH AVE SW - W	Other	8/25/2020
3343	WLK354	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/25/2020
3344	WLK354	Vertical displacement > 1-1/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3345	WLK354	Crack < 3/4 inch	Age		5TH AVE SW - W	Other	8/25/2020
3346	WLK354	Vertical displacement > 1-1/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3347	WLK354	Vertical displacement > 1-1/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3348	WLK368	Vertical displacement < 3/4 inch	Root System		5TH AVE SW - W	Other	8/25/2020
3349	WLK368	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/25/2020
3350	WLK392	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/25/2020
3351	WLK392	No passing space			5TH AVE SW - E	Other	8/25/2020
3352	WLK392	Crack < 3/4 inch	Root System		5TH AVE SW - E	Other	8/25/2020
3353	WLK392	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/25/2020
3354	WLK392	Cross Slope > 5%	Age		5TH AVE SW - E	Other	8/25/2020
3355	WLK392	Vertical displacement > 1-1/4 inch	Settlement		5TH AVE SW - E	Other	8/25/2020
3356	WLK375	Vertical displacement > 1-1/4 inch		plants in sidewalk cracks	5TH AVE SW - E	Other	8/25/2020
3357	WLK375	Running Slope > 8.33%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/25/2020
3358	WLK375	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/25/2020
3359	WLK355	No passing space			5TH AVE SW - E	Other	8/25/2020
3360	WLK340	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/25/2020
3361	WLK341	Crack between 3/4 inch and 1-1/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3362	WLK341	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/25/2020
3363	WLK341	Crack < 3/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3364	WLK337	No passing space			4TH AVE SW - E	Other	8/25/2020
3365	WLK358	3% < Cross Slope < 5%			4TH AVE SW - E	Other	8/25/2020
3366	WLK358	Vertical displacement < 3/4 inch			4TH AVE SW - E	Other	8/25/2020
3367	WLK358	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3368	WLK358	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3369	WLK358	3% < Cross Slope < 5%			4TH AVE SW - E	Other	8/25/2020
3370	WLK358	Running Slope > 8.33%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3371	WLK365	No passing space			4TH AVE SW - E	Other	8/25/2020
3372	WLK365	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3373	WLK365	3% < Cross Slope < 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3374	WLK365	Vertical displacement < 3/4 inch			4TH AVE SW - E	Other	8/25/2020
3375	WLK365	Crack < 3/4 inch	Root System		4TH AVE SW - E	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3376	WLK365	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3377	WLK366	Crack between 3/4 inch and 1-1/4 inch	Settlement		4TH AVE SW - W	Other	8/25/2020
3378	WLK366	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3379	WLK366	No passing space			4TH AVE SW - W	Other	8/25/2020
3380	WLK366	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3381	WLK357	Running Slope > 8.33%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3382	WLK357	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3383	WLK338	Vertical displacement < 3/4 inch	Root System		4TH AVE SW - W	Other	8/25/2020
3384	WLK338	Crack < 3/4 inch	Root System		4TH AVE SW - W	Other	8/25/2020
3385	WLK338	Crack < 3/4 inch	Root System		4TH AVE SW - W	Other	8/25/2020
3386	WLK386	Vertical displacement < 3/4 inch	Settlement		4TH AVE SW - E	Other	8/25/2020
3387	WLK386	No passing space			4TH AVE SW - E	Other	8/25/2020
3388	WLK386	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3389	WLK386	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3390	WLK398	Vertical displacement < 3/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3391	WLK398	Crack < 3/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3392	WLK398	Crack > 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3393	WLK398	Crack > 1-1/4 inch	Settlement		4TH AVE SW - E	Other	8/25/2020
3394	WLK413	3% < Cross Slope < 5%			4TH AVE SW - E	Other	8/25/2020
3395	WLK413	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3396	WLK413	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3397	WLK413	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3398	WLK412	No passing space			4TH AVE SW - W	Other	8/25/2020
3399	WLK406	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3400	WLK406	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3401	WLK406	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3402	WLK406	Vertical displacement > 1-1/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3403	WLK406	Vertical displacement < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3404	WLK406	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3405	WLK407	No passing space			D ST SW - N	Other	8/25/2020
3406	WLK393	No passing space			4TH AVE SW - W	Other	8/25/2020
3407	WLK393	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3408	WLK393	5% < Running Slope < 8.33%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3409	WLK393	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3410	WLK393	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3411	WLK393	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3412	WLK393	Minor Cracking	Age		4TH AVE SW - W	Other	8/25/2020
3413	WLK393	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3414	WLK393	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3415	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3416	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3417	WLK390	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3418	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3419	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3420	WLK390	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3421	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3422	WLK390	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3423	WLK377	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/25/2020
3424	WLK386	Vertical displacement < 3/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3425	WLK386	Crack < 3/4 inch	Age		4TH AVE SW - E	Other	8/25/2020
3426	WLK422	No passing space			3RD AVE SW - E	Other	8/25/2020
3427	WLK422	Crack < 3/4 inch	Settlement		3RD AVE SW - E	Other	8/25/2020
3428	WLK422	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3429	WLK422	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3430	WLK422	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3431	WLK422	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3432	WLK422	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3433	WLK425	No passing space			DIVISION ST SW - S	Other	8/25/2020
3434	WLK421	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3435	WLK421	3% < Cross Slope < 5%			3RD AVE SW - W	Other	8/25/2020
3436	WLK421	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3437	WLK421	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3438	WLK421	Crack between 3/4 inch and 1-1/4 inch	Root System		3RD AVE SW - W	Other	8/25/2020
3439	WLK421	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3440	WLK421	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3441	WLK421	Vertical displacement between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3442	WLK421	Vertical displacement < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3443	WLK419	Severe Cracking	Settlement		B ST SW - S	Other	8/25/2020
3444	WLK415	Crack between 3/4 inch and 1-1/4 inch	Settlement		3RD AVE SW - W	Other	8/25/2020
3445	WLK415	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3446	WLK415	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3447	WLK415	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3448	WLK415	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3449	WLK415	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3450	WLK415	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3451	WLK415	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3452	WLK415	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3453	WLK415	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3454	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3455	WLK1657	No passing space			C ST SW - S	Other	8/25/2020
3456	WLK405	Crack between 3/4 inch and 1-1/4 inch	Age				8/25/2020
3457	WLK405	Crack < 3/4 inch	Age				8/25/2020
3458	WLK405	Crack < 3/4 inch	Age				8/25/2020
3459	WLK405	Cross Slope > 5%	Driveway/Driveway Flare				8/25/2020
3460	WLK405	Crack < 3/4 inch	Age				8/25/2020
3461	WLK405	Crack < 3/4 inch	Age				8/25/2020
3462	WLK405	Crack < 3/4 inch	Age				8/25/2020
3463	WLK396	Crack < 3/4 inch	Age				8/25/2020
3464	WLK396	Crack between 3/4 inch and 1-1/4 inch	Root System		3RD AVE SW - W	Other	8/25/2020
3465	WLK396	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3466	WLK396	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3467	WLK396	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3468	WLK396	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3469	WLK396	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3470	WLK396	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3471	WLK396	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3472	WLK388	No passing space			3RD AVE SW - W	Other	8/25/2020
3473	WLK388	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3474	WLK388	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3475	WLK388	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3476	WLK388	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3477	WLK388	Moderate Cracking	Settlement		3RD AVE SW - W	Other	8/25/2020
3478	WLK388	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3479	WLK388	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		3RD AVE SW - W	Other	8/25/2020
3480	WLK388	Minor Cracking	Age		3RD AVE SW - W	Other	8/25/2020
3481	WLK388	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3482	WLK388	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3483	WLK379	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3484	WLK364	Crack between 3/4 inch and 1-1/4 inch	Age		G ST SW - S	Other	8/25/2020
3485	WLK363	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/25/2020
3486	WLK363	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3487	WLK363	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3488	WLK363	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3489	WLK360	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3490	WLK360	Severe Cracking	Age		3RD AVE SW - W	Other	8/25/2020
3491	WLK360	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3492	WLK362	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3493	WLK362	3% < Cross Slope < 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3494	WLK362	Vertical displacement < 3/4 inch			3RD AVE SW - E	Other	8/25/2020
3495	WLK362	Vertical displacement < 3/4 inch			3RD AVE SW - E	Other	8/25/2020
3496	WLK362	3% < Cross Slope < 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3497	WLK381	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3498	WLK379	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/25/2020
3499	WLK381	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3500	WLK381	3% < Cross Slope < 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3501	WLK384	Vertical displacement > 1-1/4 inch	Settlement		3RD AVE SW - E	Other	8/25/2020
3502	WLK384	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3503	WLK384	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3504	WLK384	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3505	WLK384	3% < Cross Slope < 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3506	WLK384	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3507	WLK384	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3508	WLK384	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/25/2020
3509	WLK384	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3510	WLK384	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3511	WLK399	3% < Cross Slope < 5%			3RD AVE SW - E	Other	8/25/2020
3512	WLK399	Crack > 1-1/4 inch			3RD AVE SW - E	Other	8/25/2020
3513	WLK399	Crack < 3/4 inch	Root System		3RD AVE SW - E	Other	8/25/2020
3514	WLK399	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3515	WLK399	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3516	WLK403	Crack < 3/4 inch	Settlement		3RD AVE SW - E	Other	8/25/2020
3517	WLK417	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3518	WLK417	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3519	WLK417	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3520	WLK417	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/25/2020
3521	WLK434	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3522	WLK434	Moderate Cracking	Settlement		DIVISION ST SW - N	Other	8/25/2020
3523	WLK434	Crack between 3/4 inch and 1-1/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3524	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3525	WLK426	Crack between 3/4 inch and 1-1/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3526	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3527	WLK426	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - S	Other	8/25/2020
3528	WLK426	Crack < 3/4 inch	Root System		DIVISION ST SW - S	Other	8/25/2020
3529	WLK426	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - S	Other	8/25/2020
3530	WLK426	Minor Cracking	Age		DIVISION ST SW - S	Other	8/25/2020
3531	WLK426	Moderate Cracking	Settlement		DIVISION ST SW - S	Other	8/25/2020
3532	WLK426	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - S	Other	8/25/2020
3533	WLK426	Moderate Cracking	Settlement		DIVISION ST SW - S	Other	8/25/2020
3534	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3535	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3536	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3537	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3538	WLK426	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3539	WLK426	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - S	Other	8/25/2020
3540	WLK425	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		DIVISION ST SW - S	Other	8/25/2020
3541	WLK425	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - S	Other	8/25/2020
3542	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3543	WLK425	Vertical displacement < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3544	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3545	WLK425	Crack between 3/4 inch and 1-1/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3546	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3547	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3548	WLK425	Vertical displacement < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3549	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3550	WLK425	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3551	WLK424	No passing space			DIVISION ST SW - S	Other	8/25/2020
3552	WLK424	Crack > 1-1/4 inch			DIVISION ST SW - S	Other	8/25/2020
3553	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3554	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3555	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3556	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3557	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3558	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3559	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3560	WLK424	Crack between 3/4 inch and 1-1/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3561	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3562	WLK424	Crack > 1-1/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3563	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3564	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3565	WLK424	Vertical displacement > 1-1/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3566	WLK424	Crack < 3/4 inch	Age		DIVISION ST SW - S	Other	8/25/2020
3567	WLK441	Cross Slope > 5%	Driveway/Driveway Flare		DIVISION ST SW - N	Other	8/25/2020
3568	WLK441	Minor Cracking	Settlement		DIVISION ST SW - N	Other	8/25/2020
3569	WLK441	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3570	WLK441	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3571	WLK441	No passing space			DIVISION ST SW - N	Other	8/25/2020
3572	WLK437	No passing space			DIVISION ST SW - N	Other	8/25/2020
3573	WLK437	No passing space			DIVISION ST SW - N	Other	8/25/2020
3574	WLK437	Vertical displacement < 3/4 inch	Settlement		DIVISION ST SW - N	Other	8/25/2020
3575	WLK437	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3576	WLK437	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3577	WLK436	Vertical displacement < 3/4 inch	Settlement		DIVISION ST SW - N	Other	8/25/2020
3578	WLK434	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3579	WLK434	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3580	WLK434	Crack < 3/4 inch	Age		DIVISION ST SW - N	Other	8/25/2020
3581	WLK420	No passing space			B ST SW - E	Other	8/25/2020
3582	WLK420	No passing space			B ST SW - E	Other	8/25/2020
3583	WLK420	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - E	Other	8/25/2020
3584	WLK420	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - E	Other	8/25/2020
3585	WLK420	Crack < 3/4 inch	Age		B ST SW - E	Other	8/25/2020
3586	WLK420	Crack > 1-1/4 inch			B ST SW - E	Other	8/25/2020
3587	WLK420	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - E	Other	8/25/2020
3588	WLK420	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - E	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3589	WLK420	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - E	Other	8/25/2020
3590	WLK419	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3591	WLK419	3% < Cross Slope < 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3592	WLK419	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3593	WLK419	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3594	WLK419	Running Slope > 8.33%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3595	WLK419	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3596	WLK419	Crack between 3/4 inch and 1-1/4 inch	Settlement		B ST SW - S	Other	8/25/2020
3597	WLK419	Moderate Cracking	Age		B ST SW - S	Other	8/25/2020
3598	WLK419	Crack < 3/4 inch	Age		B ST SW - S	Other	8/25/2020
3599	WLK417	Vertical displacement > 1-1/4 inch		brush on sidewalk	3RD AVE SW - E	Other	8/25/2020
3600	WLK418	Running Slope > 8.33%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3601	WLK418	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3602	WLK418	Cross Slope > 5%	Driveway/Driveway Flare		B ST SW - S	Other	8/25/2020
3603	WLK418	Minor Cracking	Settlement		B ST SW - S	Other	8/25/2020
3604	WLK418	Vertical displacement < 3/4 inch	Root System		B ST SW - S	Other	8/25/2020
3605	WLK418	Crack < 3/4 inch	Age		B ST SW - S	Other	8/25/2020
3606	WLK418	Crack < 3/4 inch	Age		B ST SW - S	Other	8/25/2020
3607	WLK319	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3608	WLK319	No passing space			DAISY LN SW - W	Other	8/25/2020
3609	WLK320	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - E	Other	8/25/2020
3610	WLK320	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		DAISY LN SW - E	Other	8/25/2020
3611	WLK320	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - E	Other	8/25/2020
3612	WLK320	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - E	Other	8/25/2020
3613	WLK320	Crack < 3/4 inch	Root System		DAISY LN SW - E	Other	8/25/2020
3614	WLK319	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3615	WLK319	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3616	WLK319	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3617	WLK319	2% < Cross Slope < 3%			DAISY LN SW - W	Other	8/25/2020
3618	WLK319	Cross Slope > 5%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3619	WLK319	Crack < 3/4 inch	Age		DAISY LN SW - W	Other	8/25/2020
3620	WLK319	Running Slope > 8.33%	Driveway/Driveway Flare		DAISY LN SW - W	Other	8/25/2020
3621	WLK319	2% < Cross Slope < 3%			DAISY LN SW - W	Other	8/25/2020
3622	WLK414	No passing space			C ST SW - N	Other	8/25/2020
3623	WLK414	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3624	WLK414	Minor Cracking	Settlement		C ST SW - N	Other	8/25/2020
3625	WLK414	Severe Cracking	Age		C ST SW - N	Other	8/25/2020
3626	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3627	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3628	WLK414	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3629	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3630	WLK406	Vertical displacement < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3631	WLK411	Crack > 1-1/4 inch			C ST SW - N	Other	8/25/2020
3632	WLK411	No passing space			C ST SW - N	Other	8/25/2020
3633	WLK411	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3634	WLK411	No passing space			C ST SW - N	Other	8/25/2020
3635	WLK411	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3636	WLK410	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3637	WLK410	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3638	WLK410	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3639	WLK410	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3640	WLK409	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3641	WLK409	Vertical displacement > 1-1/4 inch	Root System		C ST SW - S	Other	8/25/2020
3642	WLK409	Vertical displacement > 1-1/4 inch	Root System		C ST SW - S	Other	8/25/2020
3643	WLK409	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3644	WLK409	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3645	WLK409	Minor Cracking	Age		C ST SW - S	Other	8/25/2020
3646	WLK409	No passing space			C ST SW - S	Other	8/25/2020
3647	WLK1657	Vertical displacement between 3/4 inch and 1-1/4 inch		plants in sidewalk cracks	C ST SW - S	Other	8/25/2020
3648	WLK1657	Crack < 3/4 inch	Age		C ST SW - S	Other	8/25/2020
3649	WLK1657	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3650	WLK1657	Severe Cracking	Age		C ST SW - S	Other	8/25/2020
3651	WLK1657	Crack > 1-1/4 inch	Age		C ST SW - S	Other	8/25/2020
3652	WLK1657	No passing space			C ST SW - S	Other	8/25/2020
3653	WLK402	No passing space			C ST SW - S	Other	8/25/2020
3654	WLK402	Crack < 3/4 inch	Age		C ST SW - S	Other	8/25/2020
3655	WLK402	Crack < 3/4 inch	Age		C ST SW - S	Other	8/25/2020
3656	WLK402	Crack between 3/4 inch and 1-1/4 inch	Age		C ST SW - S	Other	8/25/2020
3657	WLK402	Crack < 3/4 inch	Age		C ST SW - S	Other	8/25/2020
3658	WLK402	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3659	WLK402	Minor Cracking	Settlement		C ST SW - S	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3660	WLK402	Minor Cracking	Age		C ST SW - S	Other	8/25/2020
3661	WLK402	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3662	WLK402	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	8/25/2020
3663	WLK89	No passing space			2ND AVE SW - W	Minor Arterial	8/25/2020
3664	WLK416	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3665	WLK416	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3666	WLK416	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3667	WLK416	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - N	Other	8/25/2020
3668	WLK416	Crack > 1-1/4 inch	Settlement		C ST SW - N	Other	8/25/2020
3669	WLK416	Crack between 3/4 inch and 1-1/4 inch	Age		C ST SW - N	Other	8/25/2020
3670	WLK416	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		C ST SW - N	Other	8/25/2020
3671	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3672	WLK414	Crack < 3/4 inch	Age		C ST SW - N	Other	8/25/2020
3673	WLK395	Crack < 3/4 inch	Root System		D ST SW - S	Other	8/25/2020
3674	WLK395	Crack < 3/4 inch	Age		D ST SW - S	Other	8/25/2020
3675	WLK395	No passing space			D ST SW - S	Other	8/25/2020
3676	WLK395	Cross Slope > 5%	Driveway/Driveway Flare		D ST SW - S	Other	8/25/2020
3677	WLK395	Cross Slope > 5%	Driveway/Driveway Flare		D ST SW - S	Other	8/25/2020
3678	WLK401	No passing space			D ST SW - S	Other	8/25/2020
3679	WLK401	3% < Cross Slope < 5%	Driveway/Driveway Flare		D ST SW - S	Other	8/25/2020
3680	WLK405	Vertical displacement between 3/4 inch and 1-1/4 inch					8/25/2020
3681	WLK404	Crack < 3/4 inch	Age		D ST SW - N	Other	8/25/2020
3682	WLK404	Crack < 3/4 inch	Age		D ST SW - N	Other	8/25/2020
3683	WLK404	Crack < 3/4 inch	Age		D ST SW - N	Other	8/25/2020
3684	WLK404	Crack < 3/4 inch	Age		D ST SW - N	Other	8/25/2020
3685	WLK404	Crack between 3/4 inch and 1-1/4 inch	Settlement		D ST SW - N	Other	8/25/2020
3686	WLK404	Cross Slope > 5%	Driveway/Driveway Flare		D ST SW - N	Other	8/25/2020
3687	WLK404	Cross Slope > 5%	Driveway/Driveway Flare		D ST SW - N	Other	8/25/2020
3688	WLK404	Crack between 3/4 inch and 1-1/4 inch	Age		D ST SW - N	Other	8/25/2020
3689	WLK407	Vertical displacement > 1-1/4 inch	Age		D ST SW - N	Other	8/25/2020
3690	WLK395	Crack < 3/4 inch	Age		D ST SW - S	Other	8/25/2020
3691	WLK395	Cross Slope > 5%	Driveway/Driveway Flare		D ST SW - S	Other	8/25/2020
3692	WLK395	Minor Cracking	Age		D ST SW - S	Other	8/25/2020
3693	WLK395	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		D ST SW - S	Other	8/25/2020
3694	WLK389	No passing space			E ST SW - S	Other	8/25/2020
3695	WLK397	Moderate Cracking	Root System		E ST SW - N	Other	8/25/2020
3696	WLK397	Cross Slope > 5%	Driveway/Driveway Flare		E ST SW - N	Other	8/25/2020
3697	WLK397	Crack < 3/4 inch	Age		E ST SW - N	Other	8/25/2020
3698	WLK397	Crack < 3/4 inch	Age		E ST SW - N	Other	8/25/2020
3699	WLK397	Minor Cracking	Settlement		E ST SW - N	Other	8/25/2020
3700	WLK389	No passing space			E ST SW - S	Other	8/25/2020
3701	WLK389	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		E ST SW - S	Other	8/25/2020
3702	WLK389	Cross Slope > 5%	Driveway/Driveway Flare		E ST SW - S	Other	8/25/2020
3703	WLK384	Vertical displacement < 3/4 inch			3RD AVE SW - E	Other	8/25/2020
3704	WLK385	No passing space			E ST SW - S	Other	8/25/2020
3705	WLK385	Cross Slope > 5%	Driveway/Driveway Flare		E ST SW - S	Other	8/25/2020
3706	WLK400	Cross Slope > 5%	Driveway/Driveway Flare		E ST SW - N	Other	8/25/2020
3707	WLK385	Severe Cracking	Root System		E ST SW - S	Other	8/25/2020
3708	WLK385	Running Slope > 8.33%	Driveway/Driveway Flare		E ST SW - S	Other	8/25/2020
3709	WLK385	Severe Cracking	Settlement		E ST SW - S	Other	8/25/2020
3710	WLK385	Cross Slope > 5%	Driveway/Driveway Flare		E ST SW - S	Other	8/25/2020
3711	WLK385	Crack < 3/4 inch	Age		E ST SW - S	Other	8/25/2020
3712	WLK88	Cross Slope > 5%	Driveway/Driveway Flare		2ND AVE SW - W	Minor Arterial	8/25/2020
3713	WLK384	Vertical displacement < 3/4 inch	Root System		3RD AVE SW - E	Other	8/25/2020
3714	WLK400	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		E ST SW - N	Other	8/25/2020
3715	WLK387	No passing space			F ST SW - N	Other	8/25/2020
3716	WLK378	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3717	WLK382	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3718	WLK382	No passing space			F ST SW - N	Other	8/25/2020
3719	WLK382	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3720	WLK382	Running Slope > 8.33%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3721	WLK382	Crack between 3/4 inch and 1-1/4 inch	Age		F ST SW - N	Other	8/25/2020
3722	WLK382	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3723	WLK382	Moderate Cracking	Age		F ST SW - N	Other	8/25/2020
3724	WLK382	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3725	WLK382	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3726	WLK383	No passing space			F ST SW - N	Other	8/25/2020
3727	WLK383	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3728	WLK383	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3729	WLK383	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3730	WLK383	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3731	WLK383	Crack between 3/4 inch and 1-1/4 inch	Age		F ST SW - N	Other	8/25/2020
3732	WLK383	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3733	WLK383	Crack between 3/4 inch and 1-1/4 inch	Age		F ST SW - N	Other	8/25/2020
3734	WLK387	Crack < 3/4 inch	Root System		F ST SW - N	Other	8/25/2020
3735	WLK387	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3736	WLK387	Cross Slope > 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3737	WLK387	3% < Cross Slope < 5%	Driveway/Driveway Flare		F ST SW - N	Other	8/25/2020
3738	WLK376	Crack < 3/4 inch	Age		F ST SW - N		8/25/2020
3739	WLK391	Crack < 3/4 inch	Age		F ST SW - N	Other	8/25/2020
3740	WLK391	Cross Slope > 5%	Age		F ST SW - N	Other	8/25/2020
3741	WLK391	No passing space			F ST SW - N	Other	8/25/2020
3742	WLK350	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		H ST SW - S	Other	8/25/2020
3743	WLK350	Crack < 3/4 inch	Settlement		H ST SW - S	Other	8/25/2020
3744	WLK371	Minor Cracking	Age		H ST SW - N	Other	8/25/2020
3745	WLK371	Vertical displacement < 3/4 inch	Root System		H ST SW - N	Other	8/25/2020
3746	WLK369	Cross Slope > 5%	Driveway/Driveway Flare		H ST SW - N	Other	8/25/2020
3747	WLK369	Vertical displacement < 3/4 inch	Root System		H ST SW - N	Other	8/25/2020
3748	WLK368	Vertical displacement > 1-1/4 inch	Settlement		5TH AVE SW - W	Other	8/25/2020
3749	WLK361	Cross Slope > 5%	Driveway/Driveway Flare		H ST SW - N	Other	8/25/2020
3750	WLK361	Crack < 3/4 inch	Age		H ST SW - N	Other	8/25/2020
3751	WLK361	Cross Slope > 5%	Driveway/Driveway Flare		H ST SW - N	Other	8/25/2020
3752	WLK359	No passing space			I ST SW - N	Other	8/25/2020
3753	WLK356	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3754	WLK356	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3755	WLK356	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3756	WLK342	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3757	WLK353	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3758	WLK353	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3759	WLK352	Minor Cracking			I ST SW - N	Other	8/25/2020
3760	WLK345	Crack < 3/4 inch			I ST SW - S	Other	8/25/2020
3761	WLK345	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3762	WLK345	Vertical displacement > 1-1/4 inch	Age		I ST SW - S	Other	8/25/2020
3763	WLK345	3% < Cross Slope < 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3764	WLK342	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3765	WLK342	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3766	WLK342	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3767	WLK342	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3768	WLK342	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3769	WLK342	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3770	WLK339	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3771	WLK339	Minor Cracking	Age		I ST SW - S	Other	8/25/2020
3772	WLK339	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3773	WLK339	Crack < 3/4 inch	Age		I ST SW - S	Other	8/25/2020
3774	WLK336	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - S	Other	8/25/2020
3775	WLK359	Cross Slope > 5%	Driveway/Driveway Flare		I ST SW - N	Other	8/25/2020
3776	WLK75	No passing space			4TH AVE SW - W	Other	8/25/2020
3777	WLK75	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/25/2020
3778	WLK75	Crack < 3/4 inch			4TH AVE SW - W	Other	8/25/2020
3779	WLK75	Minor Cracking	Age		4TH AVE SW - W	Other	8/25/2020
3780	WLK75	Moderate Cracking	Settlement		4TH AVE SW - W	Other	8/25/2020
3781	WLK75	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/25/2020
3782	WLK75	Cross Slope > 5%	Root System		4TH AVE SW - W	Other	8/25/2020
3785	WLK76	Minor Spalling	Age		K ST SW - S	Other	8/25/2020
3786	WLK545	3% < Cross Slope < 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
3787	WLK545	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
3788	WLK545	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
3789	WLK545	No passing space			7TH AVE SW - E	Other	8/26/2020
3790	WLK545	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
3791	WLK545	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
3792	WLK544	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
3793	WLK544	Crack < 3/4 inch	Age		7TH AVE SW - W	Other	8/26/2020
3794	WLK544	Crack < 3/4 inch	Age		7TH AVE SW - W	Other	8/26/2020
3795	WLK544	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
3796	WLK544	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
3797	WLK544	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
3798	WLK544	Crack between 3/4 inch and 1-1/4 inch	Settlement		7TH AVE SW - W	Other	8/26/2020
3799	WLK544	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
3800	WLK544	No passing space			7TH AVE SW - W	Other	8/26/2020
3801	WLK543	Vertical displacement < 3/4 inch	Settlement		IRVING ST SW - N	Urban Collector	8/26/2020
3802	WLK543	No passing space			IRVING ST SW - N	Urban Collector	8/26/2020
3803	WLK543	Vertical displacement < 3/4 inch	Settlement		IRVING ST SW - N	Urban Collector	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3875	WLK526	Vertical displacement < 3/4 inch	Settlement		IRVING ST SW - S	Urban Collector	8/26/2020
3876	WLK526	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3877	WLK526	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3878	WLK526	Severe Spalling	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3879	WLK526	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3880	WLK526	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3881	WLK526	No passing space			IRVING ST SW - S	Urban Collector	8/26/2020
3882	WLK526	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3883	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3884	WLK525	No passing space			IRVING ST SW - S	Urban Collector	8/26/2020
3885	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3886	WLK525	Crack < 3/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3887	WLK525	Crack < 3/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3888	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3889	WLK525	Crack < 3/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3890	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3891	WLK525	Crack between 3/4 inch and 1-1/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3892	WLK525	Crack < 3/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3893	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3894	WLK525	Crack between 3/4 inch and 1-1/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3895	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3896	WLK525	Vertical displacement < 3/4 inch	Settlement		IRVING ST SW - S	Urban Collector	8/26/2020
3897	WLK525	Crack between 3/4 inch and 1-1/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3898	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3899	WLK525	Crack < 3/4 inch	Age		IRVING ST SW - S	Urban Collector	8/26/2020
3900	WLK525	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Urban Collector	8/26/2020
3901	WLK524	Crack between 3/4 inch and 1-1/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3902	WLK524	Crack between 3/4 inch and 1-1/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3903	WLK524	Minor Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3904	WLK524	Minor Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3905	WLK524	Vertical displacement > 1-1/4 inch	Root System		7TH AVE SW - W	Urban Collector	8/26/2020
3906	WLK524	Moderate Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3907	WLK524	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
3908	WLK524	Severe Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
3909	WLK523	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3910	WLK523	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3911	WLK523	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3912	WLK523	Moderate Cracking	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3913	WLK523	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3914	WLK523	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3915	WLK523	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3916	WLK523	Crack between 3/4 inch and 1-1/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3917	WLK523	3% < Cross Slope < 5%			7TH AVE SW - E	Urban Collector	8/26/2020
3918	WLK523	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3919	WLK523	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3920	WLK522	3% < Cross Slope < 5%			IRVING ST SW - S	Other	8/26/2020
3921	WLK522	Crack between 3/4 inch and 1-1/4 inch	Age		IRVING ST SW - S	Other	8/26/2020
3922	WLK522	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Other	8/26/2020
3923	WLK522	Minor Cracking	Age		IRVING ST SW - S	Other	8/26/2020
3924	WLK522	Crack < 3/4 inch	Age		IRVING ST SW - S	Other	8/26/2020
3925	WLK522	3% < Cross Slope < 5%			IRVING ST SW - S	Other	8/26/2020
3926	WLK522	Moderate Cracking	Age		IRVING ST SW - S	Other	8/26/2020
3927	WLK522	Crack < 3/4 inch	Age		IRVING ST SW - S	Other	8/26/2020
3928	WLK522	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - S	Other	8/26/2020
3929	WLK522	No passing space			IRVING ST SW - S	Other	8/26/2020
3930	WLK520	2% < Cross Slope < 3%			6TH AVE SW - E	Other	8/26/2020
3931	WLK520	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
3932	WLK520	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
3933	WLK520	Vertical displacement < 3/4 inch	Root System		6TH AVE SW - E	Other	8/26/2020
3934	WLK520	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
3935	WLK520	Vertical displacement < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
3936	WLK520	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
3937	WLK513	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3938	WLK510	Running Slope > 8.33%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3939	WLK511	Cross Slope > 5%			6TH AVE SW - W	Other	8/26/2020
3940	WLK511	Crack > 1-1/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
3941	WLK511	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
3942	WLK511	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
3943	WLK511	No passing space			6TH AVE SW - W	Other	8/26/2020
3944	WLK512	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GRANT ST SW - N	Other	8/26/2020
3945	WLK514	Cross Slope > 5%			6TH AVE SW - E	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
3946	WLK514	Crack between 3/4 inch and 1-1/4 inch	Root System		6TH AVE SW - E	Other	8/26/2020
3947	WLK514	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
3948	WLK514	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		6TH AVE SW - E	Other	8/26/2020
3949	WLK519	Vertical displacement < 3/4 inch	Root System		HAYES ST SW - N	Other	8/26/2020
3950	WLK519	Crack < 3/4 inch	Root System		HAYES ST SW - N	Other	8/26/2020
3951	WLK519	Cross Slope > 5%	Root System		HAYES ST SW - N	Other	8/26/2020
3952	WLK519	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		HAYES ST SW - N	Other	8/26/2020
3953	WLK519	Vertical displacement < 3/4 inch	Root System		HAYES ST SW - N	Other	8/26/2020
3954	WLK519	Vertical displacement < 3/4 inch	Root System		HAYES ST SW - N	Other	8/26/2020
3955	WLK509	No passing space			HAYES ST SW - N	Other	8/26/2020
3956	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3957	WLK509	No passing space			HAYES ST SW - N	Other	8/26/2020
3958	WLK509	Crack < 3/4 inch	Age		HAYES ST SW - N	Other	8/26/2020
3959	WLK509	Crack between 3/4 inch and 1-1/4 inch	Age		HAYES ST SW - N	Other	8/26/2020
3960	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3961	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3962	WLK509	Crack between 3/4 inch and 1-1/4 inch	Age		HAYES ST SW - N	Other	8/26/2020
3963	WLK509	Vertical displacement < 3/4 inch	Age		HAYES ST SW - N	Other	8/26/2020
3964	WLK509	Crack < 3/4 inch	Age		HAYES ST SW - N	Other	8/26/2020
3965	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3966	WLK509	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		HAYES ST SW - N	Other	8/26/2020
3967	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3968	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3969	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3970	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3971	WLK509	Minor Cracking	Settlement		HAYES ST SW - N	Other	8/26/2020
3972	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3973	WLK509	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - N	Other	8/26/2020
3974	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3975	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3976	WLK508	No passing space			HAYES ST SW - S	Other	8/26/2020
3977	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3978	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3979	WLK508	Crack < 3/4 inch	Age		HAYES ST SW - S	Other	8/26/2020
3980	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3981	WLK508	No passing space			HAYES ST SW - S	Other	8/26/2020
3982	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3983	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3984	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3985	WLK508	Crack < 3/4 inch	Age		HAYES ST SW - S	Other	8/26/2020
3986	WLK508	Severe Cracking			HAYES ST SW - S	Other	8/26/2020
3987	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3988	WLK508	Cross Slope > 5%			HAYES ST SW - S	Other	8/26/2020
3989	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3990	WLK508	Crack < 3/4 inch	Age		HAYES ST SW - S	Other	8/26/2020
3991	WLK508	Cross Slope > 5%	Driveway/Driveway Flare		HAYES ST SW - S	Other	8/26/2020
3992	WLK508	Crack < 3/4 inch	Age		HAYES ST SW - S	Other	8/26/2020
3993	WLK513	No passing space			7TH AVE SW - E	Urban Collector	8/26/2020
3994	WLK513	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3995	WLK513	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3996	WLK513	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3997	WLK513	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
3998	WLK513	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
3999	WLK507	Crack between 3/4 inch and 1-1/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4000	WLK507	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
4001	WLK507	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4002	WLK507	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
4003	WLK507	Crack < 3/4 inch	Settlement		7TH AVE SW - W	Urban Collector	8/26/2020
4004	WLK507	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
4005	WLK507	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4006	WLK507	Crack < 3/4 inch	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4007	WLK512	No passing space			GRANT ST SW - N	Other	8/26/2020
4008	WLK512	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4009	WLK512	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4010	WLK512	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4011	WLK512	Minor Cracking	Age		GRANT ST SW - N	Other	8/26/2020
4012	WLK512	Vertical displacement < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4013	WLK512	Crack between 3/4 inch and 1-1/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4014	WLK506	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4015	WLK506	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4016	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4017	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4018	WLK506	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4019	WLK506	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4020	WLK506	Moderate Cracking	Age		GRANT ST SW - N	Other	8/26/2020
4021	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4022	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4023	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4024	WLK506	Running Slope > 8.33%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4025	WLK506	Vertical displacement > 1-1/4 inch	Root System		GRANT ST SW - N	Other	8/26/2020
4026	WLK506	Cross Slope > 5%	Root System		GRANT ST SW - N	Other	8/26/2020
4027	WLK506	Vertical displacement > 1-1/4 inch	Root System		GRANT ST SW - N	Other	8/26/2020
4028	WLK506	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4029	WLK506	5% < Running Slope < 8.33%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4030	WLK505	Crack between 3/4 inch and 1-1/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4031	WLK505	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4032	WLK505	Running Slope > 8.33%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4033	WLK504	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4034	WLK504	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4035	WLK541	Cross Slope > 5%	Driveway/Driveway Flare		IRVING ST SW - N	Urban Collector	8/26/2020
4036	WLK504	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4037	WLK504	No passing space			GRANT ST SW - S	Other	8/26/2020
4038	WLK500	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - E	Other	8/26/2020
4039	WLK500	3% < Cross Slope < 5%	Driveway/Driveway Flare		9TH AVE SW - E	Other	8/26/2020
4040	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4041	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4042	WLK501	No passing space			GRANT ST SW - S	Other	8/26/2020
4043	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4044	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4045	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4046	WLK501	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		GRANT ST SW - S	Other	8/26/2020
4047	WLK501	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4048	WLK501	Crack < 3/4 inch	Age		GRANT ST SW - S	Other	8/26/2020
4049	WLK501	No passing space			GRANT ST SW - S	Other	8/26/2020
4050	WLK497	Minor Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4051	WLK497	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
4052	WLK497	3% < Cross Slope < 5%	Driveway/Driveway Flare		7TH AVE SW - W	Urban Collector	8/26/2020
4053	WLK497	Minor Cracking	Age		7TH AVE SW - W	Urban Collector	8/26/2020
4054	WLK496	No passing space			7TH AVE SW - E	Urban Collector	8/26/2020
4055	WLK496	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
4056	WLK496	Running Slope > 8.33%	Driveway/Driveway Flare		7TH AVE SW - E	Urban Collector	8/26/2020
4057	WLK496	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
4058	WLK496	Vertical displacement > 1-1/4 inch	Root System		7TH AVE SW - E	Urban Collector	8/26/2020
4059	WLK496	Crack between 3/4 inch and 1-1/4 inch	Root System		7TH AVE SW - E	Urban Collector	8/26/2020
4060	WLK496	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		7TH AVE SW - E	Urban Collector	8/26/2020
4061	WLK496	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
4062	WLK496	Crack < 3/4 inch	Age		7TH AVE SW - E	Urban Collector	8/26/2020
4063	WLK495	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GRANT ST SW - S	Other	8/26/2020
4064	WLK495	Crack between 3/4 inch and 1-1/4 inch	Root System		GRANT ST SW - S	Other	8/26/2020
4065	WLK495	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4066	WLK495	Crack between 3/4 inch and 1-1/4 inch	Age		GRANT ST SW - S	Other	8/26/2020
4067	WLK495	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4068	WLK495	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - S	Other	8/26/2020
4069	WLK495	Crack between 3/4 inch and 1-1/4 inch	Age		GRANT ST SW - S	Other	8/26/2020
4070	WLK494	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4071	WLK494	Vertical displacement < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4072	WLK494	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4073	WLK494	Crack < 3/4 inch	Root System		6TH AVE SW - W	Other	8/26/2020
4074	WLK494	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		6TH AVE SW - W	Other	8/26/2020
4075	WLK488	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4076	WLK488	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4077	WLK488	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4078	WLK488	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4079	WLK488	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4080	WLK488	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4081	WLK488	Crack between 3/4 inch and 1-1/4 inch	Settlement		6TH AVE SW - E	Other	8/26/2020
4082	WLK490	No passing space			GRANT ST SW - S	Other	8/26/2020
4083	WLK490	Crack < 3/4 inch	Age		GRANT ST SW - S	Other	8/26/2020
4084	WLK490	Crack < 3/4 inch	Age		GRANT ST SW - S	Other	8/26/2020
4085	WLK489	Crack between 3/4 inch and 1-1/4 inch	Age		5TH AVE SW - W	Other	8/26/2020
4086	WLK489	3% < Cross Slope < 5%			5TH AVE SW - W	Other	8/26/2020
4087	WLK489	Minor Cracking	Age		5TH AVE SW - W	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4088	WLK489	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4089	WLK489	Severe Cracking	Age		5TH AVE SW - W	Other	8/26/2020
4090	WLK486	No passing space			5TH AVE SW - E	Other	8/26/2020
4091	WLK518	No passing space			GRANT ST SW - N	Other	8/26/2020
4092	WLK518	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4093	WLK518	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4094	WLK518	Crack < 3/4 inch	Age		GRANT ST SW - N	Other	8/26/2020
4095	WLK517	Running Slope > 8.33%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/26/2020
4096	WLK515	Cross Slope > 5%	Driveway/Driveway Flare		GRANT ST SW - N	Other	8/26/2020
4097	WLK512	Crack < 3/4 inch	Settlement		GRANT ST SW - N	Other	8/26/2020
4098	WLK512	Vertical displacement < 3/4 inch	Settlement		GRANT ST SW - N	Other	8/26/2020
4099	WLK492	No passing space			FERRY ST SW - S	Urban Collector	8/26/2020
4100	WLK492	Crack < 3/4 inch	Settlement		FERRY ST SW - S	Urban Collector	8/26/2020
4101	WLK473	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4102	WLK473	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4103	WLK474	No passing space			6TH AVE SW - E	Other	8/26/2020
4104	WLK474	Crack < 3/4 inch	Settlement		6TH AVE SW - E	Other	8/26/2020
4105	WLK474	2% < Cross Slope < 3%	Root System		6TH AVE SW - E	Other	8/26/2020
4106	WLK474	Vertical displacement < 3/4 inch	Root System		6TH AVE SW - E	Other	8/26/2020
4107	WLK488	2% < Cross Slope < 3%			6TH AVE SW - E	Other	8/26/2020
4108	WLK491	3% < Cross Slope < 5%	Driveway/Driveway Flare		FERRY ST SW - S	Urban Collector	8/26/2020
4109	WLK491	Vertical displacement < 3/4 inch	Settlement		FERRY ST SW - S	Urban Collector	8/26/2020
4110	WLK491	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Urban Collector	8/26/2020
4111	WLK491	No passing space			FERRY ST SW - S	Urban Collector	8/26/2020
4112	WLK491	Moderate Cracking	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4113	WLK476	No passing space			5TH AVE SW - W	Other	8/26/2020
4114	WLK476	Vertical displacement < 3/4 inch			5TH AVE SW - W	Other	8/26/2020
4115	WLK476	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4116	WLK477	No passing space			5TH AVE SW - E	Other	8/26/2020
4117	WLK477	Crack < 3/4 inch	Root System		5TH AVE SW - E	Other	8/26/2020
4118	WLK477	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4119	WLK477	Vertical displacement < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4120	WLK477	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4121	WLK477	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/26/2020
4122	WLK477	No passing space			5TH AVE SW - E	Other	8/26/2020
4123	WLK477	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4124	WLK477	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4125	WLK487	No passing space			FERRY ST SW - S	Urban Collector	8/26/2020
4126	WLK487	Crack < 3/4 inch	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4127	WLK487	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Urban Collector	8/26/2020
4128	WLK487	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Urban Collector	8/26/2020
4129	WLK487	Crack < 3/4 inch	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4130	WLK487	Crack < 3/4 inch	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4131	WLK479	Vertical displacement > 1-1/4 inch	Root System		4TH AVE SW - W	Urban Collector	8/26/2020
4132	WLK479	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		4TH AVE SW - W	Urban Collector	8/26/2020
4133	WLK479	Crack < 3/4 inch	Age		4TH AVE SW - W	Urban Collector	8/26/2020
4134	WLK479	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Urban Collector	8/26/2020
4135	WLK479	No passing space			4TH AVE SW - W	Urban Collector	8/26/2020
4136	WLK479	No passing space			4TH AVE SW - W	Urban Collector	8/26/2020
4137	WLK480	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Urban Collector	8/26/2020
4138	WLK484	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Other	8/26/2020
4139	WLK484	Crack < 3/4 inch	Age		FERRY ST SW - S	Other	8/26/2020
4140	WLK484	Crack between 3/4 inch and 1-1/4 inch	Age		FERRY ST SW - S	Other	8/26/2020
4141	WLK484	Crack between 3/4 inch and 1-1/4 inch	Age		FERRY ST SW - S	Other	8/26/2020
4142	WLK484	No passing space			FERRY ST SW - S	Other	8/26/2020
4143	WLK482	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4144	WLK482	Vertical displacement < 3/4 inch	Settlement		3RD AVE SW - W	Other	8/26/2020
4145	WLK482	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4146	WLK482	Vertical displacement < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4147	WLK482	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		3RD AVE SW - W	Other	8/26/2020
4148	WLK482	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		3RD AVE SW - W	Other	8/26/2020
4149	WLK482	Moderate Cracking	Settlement		3RD AVE SW - W	Other	8/26/2020
4150	WLK482	Severe Cracking	Settlement		3RD AVE SW - W	Other	8/26/2020
4151	WLK482	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/26/2020
4152	WLK482	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4153	WLK482	Vertical displacement < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4154	WLK482	Vertical displacement > 1-1/4 inch			3RD AVE SW - W	Other	8/26/2020
4155	WLK482	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/26/2020
4156	WLK482	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/26/2020
4157	WLK483	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/26/2020
4158	WLK483	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4159	WLK483	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		3RD AVE SW - E	Other	8/26/2020
4160	WLK483	Vertical displacement < 3/4 inch	Root System		3RD AVE SW - E	Other	8/26/2020
4161	WLK483	Vertical displacement < 3/4 inch	Root System		3RD AVE SW - E	Other	8/26/2020
4162	WLK483	Vertical displacement < 3/4 inch	Root System		3RD AVE SW - E	Other	8/26/2020
4163	WLK482	Vertical displacement < 3/4 inch	Root System		3RD AVE SW - W	Other	8/26/2020
4164	WLK482	Running Slope > 8.33%	Driveway/Driveway Flare		3RD AVE SW - W	Other	8/26/2020
4165	WLK482	No passing space			3RD AVE SW - W	Other	8/26/2020
4166	WLK482	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4167	WLK485	No passing space			FERRY ST SW - N	Urban Collector	8/26/2020
4168	WLK485	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Urban Collector	8/26/2020
4169	WLK485	Crack < 3/4 inch	Settlement		FERRY ST SW - N	Urban Collector	8/26/2020
4170	WLK485	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Urban Collector	8/26/2020
4171	WLK493	No passing space			FERRY ST SW - N	Urban Collector	8/26/2020
4172	WLK493	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Urban Collector	8/26/2020
4173	WLK497	Cross Slope > 5%			7TH AVE SW - W	Urban Collector	8/26/2020
4174	WLK498	No passing space			FERRY ST SW - N	Other	8/26/2020
4175	WLK498	3% < Cross Slope < 5%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4176	WLK498	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4177	WLK498	No passing space			FERRY ST SW - N	Other	8/26/2020
4178	WLK498	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4179	WLK498	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4180	WLK498	Running Slope > 8.33%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4181	WLK498	Running Slope > 8.33%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4182	WLK498	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - N	Other	8/26/2020
4183	WLK499	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Other	8/26/2020
4184	WLK499	Crack < 3/4 inch	Age		FERRY ST SW - S	Other	8/26/2020
4185	WLK499	Crack < 3/4 inch	Age		FERRY ST SW - S	Other	8/26/2020
4186	WLK499	Minor Cracking	Age		FERRY ST SW - S	Other	8/26/2020
4187	WLK499	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Other	8/26/2020
4188	WLK499	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Other	8/26/2020
4189	WLK499	Minor Spalling	Age		FERRY ST SW - S	Other	8/26/2020
4190	WLK499	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Other	8/26/2020
4191	WLK499	No passing space			FERRY ST SW - S	Other	8/26/2020
4192	WLK472	Crack < 3/4 inch	Age		7TH AVE SW - W	Other	8/26/2020
4193	WLK472	Crack < 3/4 inch	Age		7TH AVE SW - W	Other	8/26/2020
4194	WLK472	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
4195	WLK492	Crack < 3/4 inch	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4196	WLK492	Cross Slope > 5%	Driveway/Driveway Flare		FERRY ST SW - S	Urban Collector	8/26/2020
4197	WLK492	Moderate Cracking	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4198	WLK492	Crack < 3/4 inch	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4199	WLK492	Moderate Cracking	Age		FERRY ST SW - S	Urban Collector	8/26/2020
4200	WLK470	Crack > 1-1/4 inch	Settlement		EMERSON ST SW - S	Other	8/26/2020
4201	WLK469	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
4202	WLK469	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
4203	WLK469	Crack < 3/4 inch	Settlement		7TH AVE SW - W	Other	8/26/2020
4204	WLK469	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
4205	WLK469	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - W	Other	8/26/2020
4206	WLK468	Crack < 3/4 inch	Age		7TH AVE SW - E	Other	8/26/2020
4207	WLK468	Crack < 3/4 inch	Age		7TH AVE SW - E	Other	8/26/2020
4208	WLK468	Vertical displacement < 3/4 inch	Settlement		7TH AVE SW - E	Other	8/26/2020
4209	WLK468	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
4210	WLK468	Severe Cracking	Age		7TH AVE SW - E	Other	8/26/2020
4211	WLK468	Crack < 3/4 inch	Age		7TH AVE SW - E	Other	8/26/2020
4212	WLK468	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
4213	WLK468	Crack < 3/4 inch	Age		7TH AVE SW - E	Other	8/26/2020
4214	WLK468	Crack < 3/4 inch	Root System		7TH AVE SW - E	Other	8/26/2020
4215	WLK467	No passing space			EMERSON ST SW - S	Other	8/26/2020
4216	WLK467	Crack < 3/4 inch	Age		EMERSON ST SW - S	Other	8/26/2020
4217	WLK467	Severe Cracking	Age		EMERSON ST SW - S	Other	8/26/2020
4218	WLK467	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - S	Other	8/26/2020
4219	WLK481	5% < Running Slope < 8.33%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/26/2020
4220	WLK478	No passing space			EMERSON ST SW - N	Other	8/26/2020
4221	WLK478	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - N	Other	8/26/2020
4222	WLK1658	Crack < 3/4 inch	Age		EMERSON ST SW - S	Other	8/26/2020
4223	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4224	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4225	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4226	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4227	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4228	WLK464	Crack < 3/4 inch	Age		5TH AVE SW - W	Other	8/26/2020
4229	WLK464	Crack < 3/4 inch	Age		5TH AVE SW - W	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4230	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4231	WLK464	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4232	WLK465	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/26/2020
4233	WLK465	No passing space			5TH AVE SW - E	Other	8/26/2020
4234	WLK465	Crack < 3/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4235	WLK467	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - S	Other	8/26/2020
4236	WLK459	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
4237	WLK459	Vertical displacement < 3/4 inch			7TH AVE SW - E	Other	8/26/2020
4238	WLK459	Cross Slope > 5%	Driveway/Driveway Flare		7TH AVE SW - E	Other	8/26/2020
4239	WLK459	No passing space			7TH AVE SW - E	Other	8/26/2020
4240	WLK462	No passing space			6TH AVE SW - E	Other	8/26/2020
4241	WLK461	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4242	WLK462	No passing space			6TH AVE SW - E	Other	8/26/2020
4243	WLK462	2% < Cross Slope < 3%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4244	WLK462	3% < Cross Slope < 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4245	WLK462	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4246	WLK462	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4247	WLK462	Running Slope > 8.33%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4249	WLK1659	No passing space			6TH AVE SW - W	Other	8/26/2020
4250	WLK1659	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4251	WLK1659	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4252	WLK1659	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4253	WLK1659	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4254	WLK1659	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4255	WLK1659	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4256	WLK1659	3% < Cross Slope < 5%			6TH AVE SW - W	Other	8/26/2020
4257	WLK1659	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4258	WLK457	Cross Slope > 5%	Driveway/Driveway Flare		DESOTO ST SW - S	Other	8/26/2020
4259	WLK457	Cross Slope > 5%	Driveway/Driveway Flare		DESOTO ST SW - S	Other	8/26/2020
4260	WLK457	Cross Slope > 5%	Driveway/Driveway Flare		DESOTO ST SW - S	Other	8/26/2020
4261	WLK457	Crack < 3/4 inch	Age		DESOTO ST SW - S	Other	8/26/2020
4262	WLK457	Cross Slope > 5%	Driveway/Driveway Flare		DESOTO ST SW - S	Other	8/26/2020
4263	WLK454	Crack between 3/4 inch and 1-1/4 inch	Settlement		CLARK ST SW - S	Other	8/26/2020
4264	WLK454	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - S	Other	8/26/2020
4265	WLK454	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - S	Other	8/26/2020
4266	WLK452	No passing space			6TH AVE SW - W	Other	8/26/2020
4267	WLK452	Cross Slope > 5%			6TH AVE SW - W	Other	8/26/2020
4268	WLK452	Crack < 3/4 inch	Age		6TH AVE SW - W	Other	8/26/2020
4269	WLK452	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4270	WLK452	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4271	WLK452	3% < Cross Slope < 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4272	WLK452	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4273	WLK450	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4274	WLK450	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4275	WLK450	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4276	WLK450	Crack < 3/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4277	WLK450	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4278	WLK450	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4279	WLK450	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - E	Other	8/26/2020
4280	WLK451	No passing space			CLARK ST SW - S	Other	8/26/2020
4281	WLK451	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - S	Other	8/26/2020
4282	WLK448	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4283	WLK448	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - W	Other	8/26/2020
4284	WLK463	Cross Slope > 5%	Root System		CLARK ST SW - N	Other	8/26/2020
4285	WLK463	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CLARK ST SW - N	Other	8/26/2020
4286	WLK463	Crack < 3/4 inch	Root System		CLARK ST SW - N	Other	8/26/2020
4287	WLK463	Crack < 3/4 inch	Age		CLARK ST SW - N	Other	8/26/2020
4288	WLK463	Running Slope > 8.33%	Driveway/Driveway Flare		CLARK ST SW - N	Other	8/26/2020
4289	WLK460	3% < Cross Slope < 5%			CLARK ST SW - N	Other	8/26/2020
4290	WLK460	Vertical displacement < 3/4 inch	Settlement		CLARK ST SW - N	Other	8/26/2020
4291	WLK460	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - N	Other	8/26/2020
4292	WLK460	3% < Cross Slope < 5%	Driveway/Driveway Flare		CLARK ST SW - N	Other	8/26/2020
4293	WLK455	Cross Slope > 5%	Root System		CLARK ST SW - N	Other	8/26/2020
4294	WLK455	Vertical displacement < 3/4 inch	Root System		CLARK ST SW - N	Other	8/26/2020
4295	WLK455	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - N	Other	8/26/2020
4296	WLK455	Crack between 3/4 inch and 1-1/4 inch	Age		CLARK ST SW - N	Other	8/26/2020
4297	WLK455	Cross Slope > 5%	Driveway/Driveway Flare		CLARK ST SW - N	Other	8/26/2020
4298	WLK455	Vertical displacement > 1-1/4 inch	Settlement		CLARK ST SW - N	Other	8/26/2020
4299	WLK455	Crack between 3/4 inch and 1-1/4 inch	Root System		CLARK ST SW - N	Other	8/26/2020
4300	WLK429	Vertical displacement < 3/4 inch	Root System		6TH AVE SW - E	Other	8/26/2020
4301	WLK429	3% < Cross Slope < 5%	Root System		6TH AVE SW - E	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4302	WLK428	Cross Slope > 5%	Driveway/Driveway Flare		6TH AVE SW - W	Other	8/26/2020
4303	WLK427	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4304	WLK427	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4305	WLK427	No passing space			BATES ST SW - S	Other	8/26/2020
4306	WLK450	Crack between 3/4 inch and 1-1/4 inch	Age		6TH AVE SW - E	Other	8/26/2020
4307	WLK449	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BATES ST SW - N	Other	8/26/2020
4308	WLK449	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - N	Other	8/26/2020
4309	WLK449	No passing space			BATES ST SW - N	Other	8/26/2020
4310	WLK447	5% < Running Slope < 8.33%	Driveway/Driveway Flare		BATES ST SW - N	Other	8/26/2020
4311	WLK445	5% < Running Slope < 8.33%	Driveway/Driveway Flare		BATES ST SW - N	Other	8/26/2020
4312	WLK445	5% < Running Slope < 8.33%	Driveway/Driveway Flare		BATES ST SW - N	Other	8/26/2020
4313	WLK445	Minor Cracking	Age		BATES ST SW - N	Other	8/26/2020
4314	WLK445	Crack < 3/4 inch	Root System		BATES ST SW - N	Other	8/26/2020
4315	WLK445	Crack < 3/4 inch	Age		BATES ST SW - N	Other	8/26/2020
4316	WLK444	No passing space			3RD AVE SW - W	Other	8/26/2020
4317	WLK444	Vertical displacement < 3/4 inch	Settlement		3RD AVE SW - W	Other	8/26/2020
4318	WLK444	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4319	WLK444	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4320	WLK444	Crack > 1-1/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4321	WLK446	Crack > 1-1/4 inch	Age		CLARK ST SW - S	Other	8/26/2020
4322	WLK446	Crack < 3/4 inch	Age		CLARK ST SW - S	Other	8/26/2020
4323	WLK443	Crack < 3/4 inch	Age		3RD AVE SW - E	Other	8/26/2020
4324	WLK443	Minor Cracking	Age		3RD AVE SW - E	Other	8/26/2020
4325	WLK443	Crack < 3/4 inch	Settlement		3RD AVE SW - E	Other	8/26/2020
4326	WLK442	Vertical displacement < 3/4 inch	Root System		BATES ST SW - N	Other	8/26/2020
4327	WLK442	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BATES ST SW - N	Other	8/26/2020
4328	WLK442	Moderate Cracking	Settlement		BATES ST SW - N	Other	8/26/2020
4329	WLK442	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		BATES ST SW - N	Other	8/26/2020
4330	WLK440	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/26/2020
4331	WLK440	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/26/2020
4332	WLK440	Cross Slope > 5%	Driveway/Driveway Flare		3RD AVE SW - E	Other	8/26/2020
4333	WLK440	No passing space			3RD AVE SW - E	Other	8/26/2020
4334	WLK438	Crack between 3/4 inch and 1-1/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4335	WLK438	Crack < 3/4 inch	Age		3RD AVE SW - W	Other	8/26/2020
4336	WLK439	No passing space			BATES ST SW - S	Other	8/26/2020
4337	WLK439	Crack between 3/4 inch and 1-1/4 inch	Age		BATES ST SW - S	Other	8/26/2020
4338	WLK439	Crack < 3/4 inch	Age		BATES ST SW - S	Other	8/26/2020
4339	WLK436	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/26/2020
4340	WLK436	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - E	Other	8/26/2020
4341	WLK436	Crack < 3/4 inch	Settlement		4TH AVE SW - E	Other	8/26/2020
4342	WLK436	Vertical displacement < 3/4 inch	Root System		4TH AVE SW - E	Other	8/26/2020
4343	WLK436	Crack < 3/4 inch	Age		4TH AVE SW - E	Other	8/26/2020
4344	WLK436	Crack between 3/4 inch and 1-1/4 inch	Age		4TH AVE SW - E	Other	8/26/2020
4345	WLK433	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/26/2020
4346	WLK433	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/26/2020
4347	WLK433	Vertical displacement > 1-1/4 inch	Settlement		4TH AVE SW - W	Other	8/26/2020
4348	WLK433	Cross Slope > 5%	Driveway/Driveway Flare		4TH AVE SW - W	Other	8/26/2020
4349	WLK433	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/26/2020
4350	WLK433	Crack < 3/4 inch	Age		4TH AVE SW - W	Other	8/26/2020
4351	WLK432	Crack < 3/4 inch	Age		BATES ST SW - S	Other	8/26/2020
4352	WLK432	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4353	WLK432	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4354	WLK432	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4355	WLK432	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SW - S	Other	8/26/2020
4356	WLK435	Cross Slope > 5%	Driveway/Driveway Flare		5TH AVE SW - E	Other	8/26/2020
4357	WLK435	Crack between 3/4 inch and 1-1/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4358	WLK435	Crack between 3/4 inch and 1-1/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4359	WLK435	Crack > 1-1/4 inch	Age		5TH AVE SW - E	Other	8/26/2020
4360	WLK431	Vertical displacement < 3/4 inch	Root System		5TH AVE SW - W	Other	8/26/2020
4361	WLK431	Vertical displacement < 3/4 inch	Root System		5TH AVE SW - W	Other	8/26/2020
4362	WLK431	Vertical displacement > 1-1/4 inch	Root System		5TH AVE SW - W	Other	8/26/2020
4363	WLK431	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		5TH AVE SW - W	Other	8/26/2020
4364	WLK431	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		5TH AVE SW - W	Other	8/26/2020
4365	WLK547	Crack < 3/4 inch	Age		9TH AVE SW - E	Other	8/26/2020
4366	WLK547	Crack < 3/4 inch	Age		9TH AVE SW - E	Other	8/26/2020
4367	WLK547	No passing space			9TH AVE SW - E	Other	8/26/2020
4368	WLK548	Crack between 3/4 inch and 1-1/4 inch	Settlement		9TH AVE SW - W	Other	8/26/2020
4369	WLK547	Crack < 3/4 inch	Settlement		9TH AVE SW - E	Other	8/26/2020
4370	WLK549	Crack < 3/4 inch	Settlement		ANTHONY CT SW - S	Other	8/26/2020
4371	WLK550	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4372	WLK550	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4373	WLK550	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4374	WLK550	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4375	WLK551	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4376	WLK551	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4377	WLK550	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4378	WLK552	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4379	WLK552	3% < Cross Slope < 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4380	WLK552	3% < Cross Slope < 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4381	WLK552	3% < Cross Slope < 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4382	WLK553	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4383	WLK553	Cross Slope > 5%	Driveway/Driveway Flare		ANTHONY CT SW - W	Other	8/26/2020
4384	WLK554	Crack < 3/4 inch	Settlement		ANTHONY CT SW - N	Other	8/26/2020
4385	WLK555	No passing space			9TH AVE SW - E	Other	8/26/2020
4386	WLK556	Moderate Cracking	Settlement		9TH AVE SW - W	Other	8/26/2020
4387	WLK556	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4388	WLK556	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4389	WLK548	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4390	WLK548	5% < Running Slope < 8.33%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4391	WLK548	Running Slope > 8.33%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4392	WLK548	5% < Running Slope < 8.33%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4393	WLK548	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4394	WLK548	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4395	WLK548	Crack < 3/4 inch	Age		9TH AVE SW - W	Other	8/26/2020
4396	WLK548	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4397	WLK548	Crack < 3/4 inch	Age		9TH AVE SW - W	Other	8/26/2020
4398	WLK548	Cross Slope > 5%	Driveway/Driveway Flare		9TH AVE SW - W	Other	8/26/2020
4399	WLK650	Crack < 3/4 inch	Settlement		VIEWPOINT CT SW - N	Other	8/27/2020
4400	WLK650	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		VIEWPOINT CT SW - N	Other	8/27/2020
4401	WLK649	Minor Cracking	Root System		VIEWPOINT CT SW - N	Other	8/27/2020
4402	WLK649	Crack < 3/4 inch	Root System		VIEWPOINT CT SW - N	Other	8/27/2020
4403	WLK649	Vertical displacement < 3/4 inch	Root System		VIEWPOINT CT SW - N	Other	8/27/2020
4404	WLK655	Crack < 3/4 inch	Root System		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4405	WLK655	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4406	WLK655	Minor Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4407	WLK666	Crack between 3/4 inch and 1-1/4 inch	Settlement		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4408	WLK654	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4409	WLK654	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4410	WLK654	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4411	WLK654	Crack < 3/4 inch	Age		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4412	WLK653	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4413	WLK653	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4414	WLK653	Vertical displacement < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4415	WLK653	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4416	WLK653	Crack between 3/4 inch and 1-1/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4417	WLK652	Crack between 3/4 inch and 1-1/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4418	WLK652	Severe Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4419	WLK652	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4420	WLK652	Crack between 3/4 inch and 1-1/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4421	WLK652	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4422	WLK652	Severe Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4423	WLK652	Crack > 1-1/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4424	WLK652	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4425	WLK652	Moderate Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4426	WLK652	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4427	WLK652	Crack between 3/4 inch and 1-1/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4428	WLK652	Vertical displacement < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4429	WLK651	Moderate Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4430	WLK651	Moderate Cracking	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4431	WLK651	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4432	WLK651	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - E	Urban Collector	8/27/2020
4433	WLK676	3% < Cross Slope < 5%	Settlement		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4434	WLK676	Crack < 3/4 inch	Settlement		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4435	WLK677	No passing space			DELLROSE RD SW - N	Other	8/27/2020
4436	WLK678	No passing space			WOODLAND DR SW - E	Other	8/27/2020
4437	WLK679	Vertical displacement < 3/4 inch	Root System		WOODLAND CT SW - N	Other	8/27/2020
4438	WLK675	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		WOODLAND DR SW - E	Other	8/27/2020
4439	WLK675	Cross Slope > 5%	Root System		WOODLAND DR SW - E	Other	8/27/2020
4440	WLK675	Vertical displacement > 1-1/4 inch	Root System		WOODLAND DR SW - E	Other	8/27/2020
4441	WLK675	Crack < 3/4 inch	Age		WOODLAND DR SW - E	Other	8/27/2020
4442	WLK673	No passing space			WOODLAND DR SW - E	Other	8/27/2020
4443	WLK671	No passing space			WOODLAND DR SW - E	Other	8/27/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4444	WLK672	Cross Slope > 5%	Driveway/Driveway Flare		BROOKSIDE RD SW - N	Other	8/27/2020
4445	WLK672	Crack < 3/4 inch	Age		BROOKSIDE RD SW - N	Other	8/27/2020
4446	WLK672	Cross Slope > 5%	Driveway/Driveway Flare		BROOKSIDE RD SW - N	Other	8/27/2020
4447	WLK672	Cross Slope > 5%	Driveway/Driveway Flare		BROOKSIDE RD SW - N	Other	8/27/2020
4448	WLK672	Vertical displacement < 3/4 inch	Root System		BROOKSIDE RD SW - N	Other	8/27/2020
4449	WLK672	Cross Slope > 5%	Driveway/Driveway Flare		BROOKSIDE RD SW - N	Other	8/27/2020
4450	WLK669	No passing space			CROSBY BLVD SW - W	Urban Collector	8/27/2020
4451	WLK669	Minor Cracking	Settlement		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4452	WLK667	No passing space			SUMMIT CT SW - N	Other	8/27/2020
4453	WLK666	Crack < 3/4 inch	Age		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4454	WLK666	Minor Cracking	Age		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4455	WLK665	Severe Cracking	Settlement		CROSBY BLVD SW - W	Urban Collector	8/27/2020
4456	WLK663	Vertical displacement < 3/4 inch	Root System		GALENTA DR SW - E	Other	8/27/2020
4457	WLK663	Crack < 3/4 inch	Age		GALENTA DR SW - E	Other	8/27/2020
4458	WLK662	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GALENTA DR SW - N	Other	8/27/2020
4459	WLK661	Vertical displacement < 3/4 inch	Root System		GALENTA DR SW - N	Other	8/27/2020
4460	WLK661	Vertical displacement > 1-1/4 inch	Root System		GALENTA DR SW - N	Other	8/27/2020
4461	WLK660	Minor Cracking	Root System		GALENTA DR SW - S	Other	8/27/2020
4462	WLK658	Minor Cracking	Root System		CROSBY BLVD SW - N	Urban Collector	8/27/2020
4463	WLK658	Vertical displacement < 3/4 inch	Root System		CROSBY BLVD SW - N	Urban Collector	8/27/2020
4464	WLK658	Severe Cracking	Settlement		CROSBY BLVD SW - N	Urban Collector	8/27/2020
4465	WLK657	Crack < 3/4 inch	Root System		CROSBY BLVD SW - S	Urban Collector	8/27/2020
4466	WLK657	Vertical displacement < 3/4 inch	Root System		CROSBY BLVD SW - S	Urban Collector	8/27/2020
4467	WLK650	Crack < 3/4 inch	Settlement		VIEWPOINT CT SW - N	Other	8/27/2020
4468	WLK648	Vertical displacement < 3/4 inch	Root System		VISTA LOOP SW - S	Other	8/27/2020
4469	WLK648	Crack < 3/4 inch	Root System		VISTA LOOP SW - S	Other	8/27/2020
4470	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4471	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4472	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4473	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4474	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4475	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4476	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4477	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4478	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4479	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4480	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4481	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4482	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4483	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4484	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4485	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4486	WLK646	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - S	Other	8/27/2020
4487	WLK643	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4488	WLK643	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4489	WLK643	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4490	WLK643	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4491	WLK643	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4492	WLK639	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4493	WLK639	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4494	WLK639	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4495	WLK638	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4496	WLK640	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - W	Other	8/27/2020
4497	WLK640	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - W	Other	8/27/2020
4498	WLK640	Crack < 3/4 inch	Age		VISTA LOOP SW - W	Other	8/27/2020
4499	WLK640	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - W	Other	8/27/2020
4500	WLK641	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - W	Other	8/27/2020
4501	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4502	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4503	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4504	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4505	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4506	WLK644	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4507	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4508	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4509	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4510	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4511	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4512	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4513	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4514	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4515	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4516	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4517	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4518	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4519	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4520	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4521	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4522	WLK645	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4523	WLK647	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4524	WLK647	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4525	WLK647	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4526	WLK582	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4527	WLK582	2% < Cross Slope < 3%			VISTA LOOP SW - E	Other	8/27/2020
4528	WLK581	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - E	Other	8/27/2020
4529	WLK580	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4530	WLK580	3% < Cross Slope < 5%			VISTA LOOP SW - N	Other	8/27/2020
4531	WLK580	Cross Slope > 5%			VISTA LOOP SW - N	Other	8/27/2020
4532	WLK580	Cross Slope > 5%			VISTA LOOP SW - N	Other	8/27/2020
4533	WLK580	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4534	WLK579	Crack < 3/4 inch	Settlement		12TH AVE SW - E	Other	8/27/2020
4535	WLK578	Crack > 1-1/4 inch	Settlement		VISTA LOOP SW - N	Other	8/27/2020
4536	WLK577	3% < Cross Slope < 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4537	WLK576	Cross Slope > 5%	Driveway/Driveway Flare		VISTA LOOP SW - N	Other	8/27/2020
4538	WLK574	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BARNES BLVD SW - N	Urban Collector	8/27/2020
4539	WLK575	3% < Cross Slope < 5%	Root System		BARNES BLVD SW - N	Urban Collector	8/27/2020
4540	WLK575	Crack < 3/4 inch	Age		BARNES BLVD SW - N	Urban Collector	8/27/2020
4541	WLK584	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - N	Urban Collector	8/27/2020
4542	WLK584	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - N	Urban Collector	8/27/2020
4543	WLK584	Running Slope > 8.33%	Driveway/Driveway Flare		BARNES BLVD SW - N	Urban Collector	8/27/2020
4544	WLK588	Running Slope > 8.33%	Driveway/Driveway Flare		BARNES BLVD SW - E	Urban Collector	8/27/2020
4545	WLK588	Vertical displacement < 3/4 inch	Root System		BARNES BLVD SW - E	Urban Collector	8/27/2020
4546	WLK588	Vertical displacement < 3/4 inch	Settlement		BARNES BLVD SW - E	Urban Collector	8/27/2020
4547	WLK589	Vertical displacement < 3/4 inch	Settlement		BARNES BLVD SW - W	Urban Collector	8/27/2020
4548	WLK586	Cross Slope > 5%			BARNES BLVD SW - S	Urban Collector	8/27/2020
4549	WLK631	3% < Cross Slope < 5%			RIDGEVIEW CT SW - N	Other	8/27/2020
4550	WLK636	2% < Cross Slope < 3%			BLUE SKY DR SW - E	Other	8/27/2020
4551	WLK633	3% < Cross Slope < 5%			BLUE SKY DR SW - E	Other	8/27/2020
4552	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4553	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4554	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4555	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4556	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4557	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4558	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4559	WLK616	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - S	Other	8/27/2020
4560	WLK615	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - N	Other	8/27/2020
4561	WLK615	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - N	Other	8/27/2020
4562	WLK615	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - N	Other	8/27/2020
4563	WLK615	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - N	Other	8/27/2020
4564	WLK618	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - N	Other	8/27/2020
4565	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4566	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4567	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4568	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4569	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4570	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4571	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4572	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4573	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4574	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4575	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4576	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4577	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4578	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4579	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4580	WLK620	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4581	WLK624	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4582	WLK624	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4583	WLK624	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4584	WLK625	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4585	WLK625	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4586	WLK625	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4587	WLK625	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4588	WLK625	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4589	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4590	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4591	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4592	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4593	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4594	WLK626	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - E	Other	8/27/2020
4595	WLK621	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4596	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4597	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4598	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4599	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4600	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4601	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4602	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4603	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4604	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4605	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4606	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4607	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4608	WLK619	Cross Slope > 5%	Driveway/Driveway Flare		RIDGEVIEW LOOP SW - W	Other	8/27/2020
4609	WLK527	Vertical displacement < 3/4 inch	Root System		12TH AVE SW - W	Other	8/27/2020
4610	WLK538	3% < Cross Slope < 5%			12TH AVE SW - W	Other	8/27/2020
4611	WLK538	Severe Cracking	Age		12TH AVE SW - W	Other	8/27/2020
4612	WLK538	3% < Cross Slope < 5%			12TH AVE SW - W	Other	8/27/2020
4613	WLK538	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		12TH AVE SW - W	Other	8/27/2020
4614	WLK538	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		12TH AVE SW - W	Other	8/27/2020
4615	WLK538	2% < Cross Slope < 3%	Root System		12TH AVE SW - W	Other	8/27/2020
4616	WLK539	Cross Slope > 5%	Driveway/Driveway Flare		12TH AVE SW - W	Other	8/27/2020
4617	WLK540	Cross Slope > 5%	Driveway/Driveway Flare		12TH AVE SW - W	Other	8/27/2020
4618	WLK540	Crack between 3/4 inch and 1-1/4 inch	Age		12TH AVE SW - W	Other	8/27/2020
4619	WLK529	Vertical displacement < 3/4 inch	Root System		BAY ST SW - N	Other	8/27/2020
4620	WLK529	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BAY ST SW - N	Other	8/27/2020
4621	WLK533	Cross Slope > 5%			BAY ST SW - S	Other	8/27/2020
4622	WLK530	Vertical displacement < 3/4 inch	Root System		BAY ST SW - N	Other	8/27/2020
4623	WLK530	Cross Slope > 5%			BAY ST SW - N	Other	8/27/2020
4624	WLK535	Vertical displacement < 3/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4625	WLK535	No passing space			BAY LOOP SW - E	Other	8/27/2020
4626	WLK535	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4627	WLK535	Vertical displacement > 1-1/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4628	WLK535	Vertical displacement < 3/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4629	WLK535	Vertical displacement > 1-1/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4630	WLK536	No passing space			BAY LOOP SW - N	Other	8/27/2020
4631	WLK536	Severe Cracking	Settlement		BAY LOOP SW - N	Other	8/27/2020
4632	WLK536	Severe Cracking			BAY LOOP SW - N	Other	8/27/2020
4633	WLK537	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4634	WLK537	Vertical displacement > 1-1/4 inch	Root System		BAY LOOP SW - E	Other	8/27/2020
4635	WLK534	Vertical displacement > 1-1/4 inch	Root System		BAY ST SW - S	Other	8/27/2020
4636	WLK534	Vertical displacement < 3/4 inch	Root System		BAY ST SW - S	Other	8/27/2020
4637	WLK534	No passing space			BAY ST SW - S	Other	8/27/2020
4638	WLK306	2% < Cross Slope < 3%			RURAL RD SW - E	Urban Collector	8/27/2020
4639	WLK306	2% < Cross Slope < 3%			RURAL RD SW - E	Urban Collector	8/27/2020
4640	WLK750	Crack < 3/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4641	WLK750	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4642	WLK750	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4643	WLK750	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		32ND AVE SW - N	Other	8/28/2020
4644	WLK750	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4645	WLK750	3% < Cross Slope < 5%	Root System		32ND AVE SW - N	Other	8/28/2020
4646	WLK750	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4647	WLK750	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - N	Other	8/28/2020
4648	WLK751	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - S	Other	8/28/2020
4649	WLK751	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - S	Other	8/28/2020
4650	WLK751	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - S	Other	8/28/2020
4651	WLK751	Vertical displacement < 3/4 inch	Root System		32ND AVE SW - S	Other	8/28/2020
4652	WLK752	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		32ND AVE SW - S	Commercial/Industrial Collector	8/28/2020
4653	WLK753	Vertical displacement > 1-1/4 inch	Root System		32ND AVE SW - S	Commercial/Industrial Collector	8/28/2020
4654	WLK753	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		32ND AVE SW - S	Commercial/Industrial Collector	8/28/2020
4655	WLK754	Crack < 3/4 inch	Settlement		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4656	WLK754	3% < Cross Slope < 5%	Root System		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4657	WLK754	Vertical displacement > 1-1/4 inch	Root System		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4658	WLK754	Vertical displacement > 1-1/4 inch	Root System		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4659	WLK699	3% < Cross Slope < 5%			SAPP RD SW - N	Urban Collector	8/28/2020
4660	WLK766	Cross Slope > 5%			RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4661	WLK766	3% < Cross Slope < 5%			RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4662	WLK759	No passing space			SIMMONS MILL CT SW - E	Other	8/28/2020
4663	WLK759	Crack < 3/4 inch	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4664	WLK759	3% < Cross Slope < 5%	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4665	WLK759	Crack < 3/4 inch	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4666	WLK759	Vertical displacement < 3/4 inch	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4667	WLK759	Crack < 3/4 inch	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4668	WLK758	No passing space			SIMMONS MILL CT SW - E	Other	8/28/2020
4669	WLK758	Crack < 3/4 inch	Root System		SIMMONS MILL CT SW - E	Other	8/28/2020
4670	WLK761	Vertical displacement < 3/4 inch	Root System		CHAPPAREL DR SW - S	Other	8/28/2020
4671	WLK760	Vertical displacement < 3/4 inch	Root System		SIMMONS MILL CT SW - W	Other	8/28/2020
4672	WLK760	Vertical displacement < 3/4 inch	Root System		SIMMONS MILL CT SW - W	Other	8/28/2020
4673	WLK760	Vertical displacement < 3/4 inch	Root System		SIMMONS MILL CT SW - W	Other	8/28/2020
4674	WLK762	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4675	WLK763	Crack < 3/4 inch	Settlement		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4676	WLK755	Crack between 3/4 inch and 1-1/4 inch	Root System		RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4677	WLK755	Crack < 3/4 inch	Root System		RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4678	WLK755	Cross Slope > 5%	Driveway/Driveway Flare		RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4679	WLK755	Vertical displacement < 3/4 inch	Root System		RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4680	WLK748	2% < Cross Slope < 3%			RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4681	WLK748	3% < Cross Slope < 5%	Driveway/Driveway Flare		RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4682	WLK748	3% < Cross Slope < 5%			RW JOHNSON BLVD SW - W	Commercial/Industrial Collector	8/28/2020
4683	WLK729	3% < Cross Slope < 5%			RW JOHNSON BLVD SW - E	Commercial/Industrial Collector	8/28/2020
4684	WLK728	Cross Slope > 5%	Driveway/Driveway Flare		RW JOHNSON BLVD SW - E	Other	8/28/2020
4685	WLK1061	3% < Cross Slope < 5%	Driveway/Driveway Flare				8/28/2020
4686	WLK1061	2% < Cross Slope < 3%					8/28/2020
4687	WLK1061	2% < Cross Slope < 3%	Driveway/Driveway Flare				8/28/2020
4688	WLK730	2% < Cross Slope < 3%	Driveway/Driveway Flare				8/28/2020
4689	WLK730	No passing space			27TH AVE SW - N	Other	8/28/2020
4690	WLK735	Hole > 1-1/4 inch	Settlement		27TH AVE SW - N	Other	8/28/2020
4691	WLK736	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		27TH AVE SW - S	Other	8/28/2020
4692	WLK736	Vertical displacement < 3/4 inch	Settlement		27TH AVE SW - S	Other	8/28/2020
4693	WLK736	Crack < 3/4 inch	Root System		27TH AVE SW - S	Other	8/28/2020
4694	WLK736	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		27TH AVE SW - S	Other	8/28/2020
4695	WLK734	3% < Cross Slope < 5%			FIRLAND ST SW - W	Other	8/28/2020
4696	WLK734	3% < Cross Slope < 5%			FIRLAND ST SW - W	Other	8/28/2020
4697	WLK734	No passing space			FIRLAND ST SW - W	Other	8/28/2020
4698	WLK732	No passing space			DOUGLAS ST SW - W	Other	8/28/2020
4699	WLK731	2% < Cross Slope < 3%			DOUGLAS ST SW - W	Other	8/28/2020
4700	WLK731	3% < Cross Slope < 5%			DOUGLAS ST SW - W	Other	8/28/2020
4701	WLK731	Crack < 3/4 inch	Age		DOUGLAS ST SW - W	Other	8/28/2020
4702	WLK738	No passing space			FIRLAND ST SW - W	Other	8/28/2020
4703	WLK741	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		29TH AVE SW - N	Other	8/28/2020
4704	WLK741	No passing space			29TH AVE SW - N	Other	8/28/2020
4705	WLK741	No passing space			29TH AVE SW - N	Other	8/28/2020
4706	WLK746	3% < Cross Slope < 5%	Root System		29TH AVE SW - S	Other	8/28/2020
4707	WLK747	Vertical displacement < 3/4 inch	Root System		29TH AVE SW - S	Other	8/28/2020
4708	WLK746	Vertical displacement > 1-1/4 inch		meter box	29TH AVE SW - S	Other	8/28/2020
4709	WLK743	No passing space			29TH AVE SW - N	Other	8/28/2020
4710	WLK742	No passing space			29TH AVE SW - N	Other	8/28/2020
4711	WLK740	No passing space			NOBLE ST SW - E	Other	8/28/2020
4712	WLK740	No passing space			NOBLE ST SW - E	Other	8/28/2020
4713	WLK740	Crack < 3/4 inch	Root System		NOBLE ST SW - E	Other	8/28/2020
4714	WLK739	No passing space			28TH AVE SW - S	Other	8/28/2020
4715	WLK737	3% < Cross Slope < 5%	Root System		FIRLAND ST SW - W	Other	8/28/2020
4716	WLK737	Vertical displacement < 3/4 inch	Root System		FIRLAND ST SW - W	Other	8/28/2020
4717	WLK737	Crack between 3/4 inch and 1-1/4 inch	Root System		FIRLAND ST SW - W	Other	8/28/2020
4718	WLK737	Minor Cracking	Age		FIRLAND ST SW - W	Other	8/28/2020
4719	WLK738	Minor Cracking	Age		FIRLAND ST SW - W	Other	8/28/2020
4720	WLK738	Vertical displacement < 3/4 inch	Root System		FIRLAND ST SW - W	Other	8/28/2020
4721	WLK738	Vertical displacement < 3/4 inch	Root System		FIRLAND ST SW - W	Other	8/28/2020
4722	WLK722	Crack < 3/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4723	WLK722	Vertical displacement > 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4724	WLK722	Vertical displacement > 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4725	WLK722	Vertical displacement > 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4726	WLK722	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4727	WLK722	Moderate Cracking	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4728	WLK722	Moderate Cracking	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4729	WLK721	Crack between 3/4 inch and 1-1/4 inch	Age		SOMERSET HILL DR SW - N	Other	8/28/2020
4730	WLK720	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4731	WLK720	Vertical displacement < 3/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4732	WLK720	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4733	WLK719	Vertical displacement between 3/4 inch and 1-1/4 inch			SOMERSET HILL DR SW - N	Other	8/28/2020
4734	WLK718	Vertical displacement > 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4735	WLK718	Crack < 3/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4736	WLK718	Crack > 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4737	WLK718	Crack between 3/4 inch and 1-1/4 inch	Root System		SOMERSET HILL DR SW - N	Other	8/28/2020
4738	WLK710	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE CT SW - E	Other	8/28/2020
4739	WLK710	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE CT SW - E	Other	8/28/2020
4740	WLK710	Vertical displacement < 3/4 inch	Root System		CASSIE CT SW - E	Other	8/28/2020
4741	WLK710	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE CT SW - E	Other	8/28/2020
4742	WLK705	Vertical displacement > 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4743	WLK705	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4744	WLK705	Vertical displacement > 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4745	WLK705	Vertical displacement < 3/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4746	WLK705	Vertical displacement < 3/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4747	WLK705	Vertical displacement < 3/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4748	WLK705	Vertical displacement < 3/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4749	WLK705	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4750	WLK704	Vertical displacement > 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4751	WLK704	Vertical displacement > 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4752	WLK704	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4753	WLK703	Hole between 3/4 inch and 1-1/4 inch	Age		CASSIE DR SW - W	Other	8/28/2020
4754	WLK713	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4755	WLK705	Vertical displacement < 3/4 inch	Root System		CASSIE DR SW - W	Other	8/28/2020
4756	WLK712	Minor Cracking	Root System		CASSIE DR SW - E	Other	8/28/2020
4757	WLK714	Crack < 3/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4758	WLK714	Running Slope > 8.33%	Root System		ANTSEN ST SW - W	Other	8/28/2020
4759	WLK714	Running Slope > 8.33%	Root System		ANTSEN ST SW - W	Other	8/28/2020
4760	WLK714	Minor Cracking	Settlement		ANTSEN ST SW - W	Other	8/28/2020
4761	WLK714	5% < Running Slope < 8.33%	Root System		ANTSEN ST SW - W	Other	8/28/2020
4762	WLK714	3% < Cross Slope < 5%	Root System		ANTSEN ST SW - W	Other	8/28/2020
4763	WLK715	3% < Cross Slope < 5%	Root System		ANTSEN ST SW - E	Other	8/28/2020
4764	WLK701	Vertical displacement > 1-1/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4765	WLK701	Crack < 3/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4766	WLK701	3% < Cross Slope < 5%	Root System		ANTSEN ST SW - W	Other	8/28/2020
4767	WLK701	Vertical displacement < 3/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4768	WLK701	Vertical displacement < 3/4 inch	Root System		ANTSEN ST SW - W	Other	8/28/2020
4769	WLK715	3% < Cross Slope < 5%			ANTSEN ST SW - E	Other	8/28/2020
4770	WLK715	Vertical displacement < 3/4 inch	Root System		ANTSEN ST SW - E	Other	8/28/2020
4771	WLK715	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ANTSEN ST SW - E	Other	8/28/2020
4772	WLK726	Cross Slope > 5%	Root System		MOTTMAN RD SW - S	Commercial/Industrial Collector	8/28/2020
4773	WLK726	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MOTTMAN RD SW - S	Commercial/Industrial Collector	8/28/2020
4774	WLK726	Vertical displacement > 1-1/4 inch	Root System		MOTTMAN RD SW - S	Commercial/Industrial Collector	8/28/2020
4775	WLK726	3% < Cross Slope < 5%	Driveway/Driveway Flare		MOTTMAN RD SW - S	Commercial/Industrial Collector	8/28/2020
4776	WLK724	2% < Cross Slope < 3%			MOTTMAN RD SW - N	Commercial/Industrial Collector	8/28/2020
4777	WLK724	2% < Cross Slope < 3%			MOTTMAN RD SW - N	Commercial/Industrial Collector	8/28/2020
4778	WLK723	3% < Cross Slope < 5%			MOTTMAN RD SW - S	Commercial/Industrial Collector	8/28/2020
4779	WLK561	Vertical displacement < 3/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	8/28/2020
4780	WLK558	Vertical displacement < 3/4 inch	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4781	WLK558	Running Slope > 8.33%	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4782	WLK558	3% < Cross Slope < 5%			MOTTMAN RD SW - S	Other	8/28/2020
4783	WLK558	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4784	WLK558	Vertical displacement < 3/4 inch	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4785	WLK558	Vertical displacement < 3/4 inch	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4786	WLK558	Minor Spalling	Age		MOTTMAN RD SW - S	Other	8/28/2020
4787	WLK557	2% < Cross Slope < 3%			MOTTMAN RD SW - S	Other	8/28/2020
4788	WLK557	Moderate Spalling	Age		MOTTMAN RD SW - S	Other	8/28/2020
4789	WLK557	Cross Slope > 5%	Driveway/Driveway Flare		MOTTMAN RD SW - S	Other	8/28/2020
4790	WLK557	Hole between 3/4 inch and 1-1/4 inch	Age		MOTTMAN RD SW - S	Other	8/28/2020
4791	WLK557	Cross Slope > 5%	Driveway/Driveway Flare		MOTTMAN RD SW - S	Other	8/28/2020
4792	WLK557	Cross Slope > 5%	Driveway/Driveway Flare		MOTTMAN RD SW - S	Other	8/28/2020
4793	WLK557	Vertical displacement < 3/4 inch	Root System		MOTTMAN RD SW - S	Other	8/28/2020
4794	WLK724	5% < Running Slope < 8.33%	Driveway/Driveway Flare		MOTTMAN RD SW - N	Commercial/Industrial Collector	8/28/2020
4795	WLK697	Vertical displacement > 1-1/4 inch	Root System		SAPP RD SW - S	Urban Collector	8/28/2020
4796	WLK697	Vertical displacement > 1-1/4 inch	Root System		SAPP RD SW - S	Urban Collector	8/28/2020
4797	WLK700	Crack < 3/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4798	WLK700	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4799	WLK700	Vertical displacement > 1-1/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4800	WLK700	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4801	WLK700	Vertical displacement < 3/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4802	WLK700	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4803	WLK700	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SAPP RD SW - N	Urban Collector	8/28/2020
4804	WLK693	Minor Cracking			BLACKSTONE DR SW - N	Other	8/28/2020
4805	WLK694	Vertical displacement < 3/4 inch			SAPP RD SW - S	Urban Collector	8/28/2020
4806	WLK695	No passing space			SAPP RD SW - S	Urban Collector	8/28/2020
4807	WLK696	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SAPP RD SW - S	Urban Collector	8/28/2020
4808	WLK681	Vertical displacement < 3/4 inch	Root System		GROTTO CT SW - N	Other	8/28/2020
4809	WLK681	Vertical displacement < 3/4 inch	Root System		GROTTO CT SW - N	Other	8/28/2020
4810	WLK682	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GROTTO CT SW - N	Other	8/28/2020
4811	WLK681	Vertical displacement < 3/4 inch	Root System		GROTTO CT SW - N	Other	8/28/2020
4812	WLK682	Crack < 3/4 inch	Age		GROTTO CT SW - N	Other	8/28/2020
4813	WLK690	3% < Cross Slope < 5%			BLACKSTONE DR SW - S	Other	8/28/2020
4814	WLK690	Vertical displacement < 3/4 inch	Root System		BLACKSTONE DR SW - S	Other	8/28/2020
4815	WLK689	Vertical displacement < 3/4 inch	Root System		BLACKSTONE CT SW - N	Other	8/28/2020
4816	WLK687	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACKSTONE DR SW - W	Other	8/28/2020
4817	WLK248	Vertical displacement between 3/4 inch and 1-1/4 inch			LAMBSKIN ST SW - E	Other	8/28/2020
4818	WLK816	No passing space			SUNSET WAY SE - E	Other	9/1/2020
4819	WLK816	No passing space			SUNSET WAY SE - E	Other	9/1/2020
4820	WLK816	Vertical displacement > 1-1/4 inch	Root System		SUNSET WAY SE - E	Other	9/1/2020
4821	WLK816	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SUNSET WAY SE - E	Other	9/1/2020
4823	WLK818	Crack < 3/4 inch	Root System		SUNSET WAY SE - E	Other	9/1/2020
4824	WLK818	Crack < 3/4 inch	Root System		SUNSET WAY SE - E	Other	9/1/2020
4825	WLK818	Crack < 3/4 inch	Root System		SUNSET WAY SE - E	Other	9/1/2020
4826	WLK820	Minor Cracking	Age		CARLYON AVE SE - S	Other	9/1/2020
4827	WLK820	No passing space			CARLYON AVE SE - S	Other	9/1/2020
4828	WLK820	Minor Cracking	Age		CARLYON AVE SE - S	Other	9/1/2020
4829	WLK820	Moderate Cracking	Age		CARLYON AVE SE - S	Other	9/1/2020
4830	WLK820	Crack < 3/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4831	WLK820	Crack < 3/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4832	WLK820	Crack between 3/4 inch and 1-1/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4833	WLK820	Vertical displacement < 3/4 inch	Settlement		CARLYON AVE SE - S	Other	9/1/2020
4834	WLK820	Vertical displacement < 3/4 inch	Settlement		CARLYON AVE SE - S	Other	9/1/2020
4835	WLK820	Crack < 3/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4836	WLK820	Crack > 1-1/4 inch	Settlement		CARLYON AVE SE - S	Other	9/1/2020
4837	WLK820	Crack > 1-1/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4838	WLK820	Crack > 1-1/4 inch	Settlement		CARLYON AVE SE - S	Other	9/1/2020
4839	WLK820	Crack < 3/4 inch	Age		CARLYON AVE SE - S	Other	9/1/2020
4840	WLK820	3% < Cross Slope < 5%	Settlement		CARLYON AVE SE - S	Other	9/1/2020
4857	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4858	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4859	WLK801	3% < Cross Slope < 5%			MOORE ST SE - W	Other	9/1/2020
4860	WLK801	Vertical displacement > 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4861	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4862	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4863	WLK810	3% < Cross Slope < 5%	Driveway/Driveway Flare		VISTA AVE SE - S	Other	9/1/2020
4864	WLK801	3% < Cross Slope < 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4865	WLK801	Crack < 3/4 inch	Settlement		MOORE ST SE - W	Other	9/1/2020
4866	WLK801	Cross Slope > 5%			MOORE ST SE - W	Other	9/1/2020
4867	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4868	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4869	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4870	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4871	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4872	WLK801	3% < Cross Slope < 5%			MOORE ST SE - W	Other	9/1/2020
4873	WLK801	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4874	WLK801	3% < Cross Slope < 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4875	WLK801	Minor Cracking	Age		MOORE ST SE - W	Other	9/1/2020
4876	WLK801	Cross Slope > 5%	Settlement		MOORE ST SE - W	Other	9/1/2020
4877	WLK801	Vertical displacement between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4878	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4879	WLK801	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4880	WLK801	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4881	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4882	WLK801	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		MOORE ST SE - W	Other	9/1/2020
4883	WLK801	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4884	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4885	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4886	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4887	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4888	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4889	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4890	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4891	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4892	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4893	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4894	WLK801	Vertical displacement < 3/4 inch	Settlement		MOORE ST SE - W	Other	9/1/2020
4895	WLK801	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4896	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4897	WLK801	Cross Slope > 5%	Root System		MOORE ST SE - W	Other	9/1/2020
4898	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4899	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4900	WLK801	Vertical displacement > 1-1/4 inch	Root System		MOORE ST SE - W	Other	9/1/2020
4901	WLK801	Vertical displacement > 1-1/4 inch	Settlement		MOORE ST SE - W	Other	9/1/2020
4902	WLK801	Crack > 1-1/4 inch	Settlement		MOORE ST SE - W	Other	9/1/2020
4903	WLK801	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4904	WLK801	Crack < 3/4 inch	Age		MOORE ST SE - W	Other	9/1/2020
4905	WLK801	3% < Cross Slope < 5%	Driveway/Driveway Flare		MOORE ST SE - W	Other	9/1/2020
4906	WLK800	No passing space			MOORE ST SE - E	Other	9/1/2020
4907	WLK800	Crack > 1-1/4 inch	Root System		MOORE ST SE - E	Other	9/1/2020
4908	WLK800	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		MOORE ST SE - E	Other	9/1/2020
4909	WLK800	Crack < 3/4 inch	Age		MOORE ST SE - E	Other	9/1/2020
4910	WLK800	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - E	Other	9/1/2020
4911	WLK800	Cross Slope > 5%			MOORE ST SE - E	Other	9/1/2020
4912	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4913	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4914	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4915	WLK800	Crack between 3/4 inch and 1-1/4 inch	Settlement		MOORE ST SE - E	Other	9/1/2020
4916	WLK800	2% < Cross Slope < 3%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4917	WLK800	Severe Cracking	Settlement		MOORE ST SE - E	Other	9/1/2020
4918	WLK800	Vertical displacement < 3/4 inch	Age		MOORE ST SE - E	Other	9/1/2020
4919	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4920	WLK800	Crack between 3/4 inch and 1-1/4 inch	Age		MOORE ST SE - E	Other	9/1/2020
4921	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4922	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4923	WLK800	Minor Cracking	Settlement		MOORE ST SE - E	Other	9/1/2020
4924	WLK800	Cross Slope > 5%	Driveway/Driveway Flare		MOORE ST SE - E	Other	9/1/2020
4925	WLK800	Crack < 3/4 inch	Age		MOORE ST SE - E	Other	9/1/2020
4931	WLK812	Crack < 3/4 inch	Settlement		FAIRFIELD RD SE - W	Other	9/1/2020
4932	WLK815	Crack < 3/4 inch	Age		SUNSET WAY SE - W	Other	9/1/2020
4933	WLK817	Crack < 3/4 inch	Age		VISTA AVE SE - N	Other	9/1/2020
4934	WLK817	Crack < 3/4 inch	Age		VISTA AVE SE - N	Other	9/1/2020
4935	WLK817	3% < Cross Slope < 5%			VISTA AVE SE - N	Other	9/1/2020
4952	WLK811	Crack < 3/4 inch	Age		VISTA AVE SE - S	Other	9/1/2020
4953	WLK811	Crack < 3/4 inch	Age		VISTA AVE SE - S	Other	9/1/2020
4954	WLK811	Vertical displacement < 3/4 inch	Age		VISTA AVE SE - S	Other	9/1/2020
4955	WLK811	Crack between 3/4 inch and 1-1/4 inch	Age		VISTA AVE SE - S	Other	9/1/2020
4956	WLK811	Crack < 3/4 inch	Age		VISTA AVE SE - S	Other	9/1/2020
4957	WLK814	3% < Cross Slope < 5%	Root System		VISTA AVE SE - N	Other	9/1/2020
4958	WLK814	Crack < 3/4 inch	Age		VISTA AVE SE - N	Other	9/1/2020
4959	WLK812	3% < Cross Slope < 5%			FAIRFIELD RD SE - W	Other	9/1/2020
4960	WLK812	Crack < 3/4 inch	Age		FAIRFIELD RD SE - W	Other	9/1/2020
4961	WLK812	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
4962	WLK812	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
4963	WLK812	Running Slope > 8.33%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
4964	WLK812	Crack < 3/4 inch	Settlement		FAIRFIELD RD SE - W	Other	9/1/2020
4965	WLK812	Vertical displacement > 1-1/4 inch	Root System		FAIRFIELD RD SE - W	Other	9/1/2020
4966	WLK813	3% < Cross Slope < 5%			FAIRFIELD RD SE - E	Other	9/1/2020
4967	WLK813	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4968	WLK813	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4969	WLK813	Vertical displacement < 3/4 inch	Root System		FAIRFIELD RD SE - E	Other	9/1/2020
4970	WLK808	Crack < 3/4 inch	Root System		FAIRFIELD RD SE - E	Other	9/1/2020
4971	WLK808	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4972	WLK808	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4973	WLK808	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - E	Other	9/1/2020
4974	WLK808	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4975	WLK808	Crack < 3/4 inch	Age		FAIRFIELD RD SE - E	Other	9/1/2020
4976	WLK808	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - E	Other	9/1/2020
4977	WLK808	3% < Cross Slope < 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - E	Other	9/1/2020
4978	WLK808	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - E	Other	9/1/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
4979	WLK807	3% < Cross Slope < 5%			BLOSS AVE SE - N	Other	9/1/2020
4999	WLK806	Crack < 3/4 inch	Age		BLOSS AVE SE - N	Other	9/1/2020
5000	WLK806	3% < Cross Slope < 5%			BLOSS AVE SE - N	Other	9/1/2020
5001	WLK806	3% < Cross Slope < 5%	Driveway/Driveway Flare		BLOSS AVE SE - N	Other	9/1/2020
5002	WLK806	Crack < 3/4 inch	Age		BLOSS AVE SE - N	Other	9/1/2020
5003	WLK806	No passing space			BLOSS AVE SE - N	Other	9/1/2020
5053	WLK804	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5054	WLK804	No passing space			BLOSS AVE SE - S	Other	9/1/2020
5055	WLK804	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5056	WLK804	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5057	WLK804	Crack < 3/4 inch	Age		BLOSS AVE SE - S	Other	9/1/2020
5058	WLK804	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5059	WLK804	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5060	WLK805	Minor Cracking	Age		BLOSS AVE SE - S	Other	9/1/2020
5061	WLK805	3% < Cross Slope < 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5062	WLK805	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5063	WLK805	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5064	WLK805	Cross Slope > 5%	Driveway/Driveway Flare		BLOSS AVE SE - S	Other	9/1/2020
5065	WLK809	3% < Cross Slope < 5%			FAIRFIELD RD SE - W	Other	9/1/2020
5066	WLK809	Minor Cracking	Age		FAIRFIELD RD SE - W	Other	9/1/2020
5067	WLK809	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
5068	WLK809	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
5069	WLK809	Vertical displacement > 1-1/4 inch	Age		FAIRFIELD RD SE - W	Other	9/1/2020
5070	WLK809	Crack between 3/4 inch and 1-1/4 inch	Age		FAIRFIELD RD SE - W	Other	9/1/2020
5071	WLK809	Crack < 3/4 inch	Root System		FAIRFIELD RD SE - W	Other	9/1/2020
5072	WLK809	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		FAIRFIELD RD SE - W	Other	9/1/2020
5073	WLK809	Cross Slope > 5%	Driveway/Driveway Flare		FAIRFIELD RD SE - W	Other	9/1/2020
5074	WLK771	Vertical displacement < 3/4 inch	Root System		SCHMIDT PL SW - E	Other	9/1/2020
5075	WLK769	Running Slope > 8.33%			CUSTER WAY SW - N	Minor Arterial	9/1/2020
5076	WLK767	Running Slope > 8.33%	Driveway/Driveway Flare		CUSTER WAY SW - S	Minor Arterial	9/1/2020
5077	WLK768	Cross Slope > 5%	Driveway/Driveway Flare		CUSTER WAY SW - S	Minor Arterial	9/1/2020
5078	WLK840	No passing space			CLARK PL SE - W	Other	9/1/2020
5079	WLK840	3% < Cross Slope < 5%	Driveway/Driveway Flare		CLARK PL SE - W	Other	9/1/2020
5080	WLK840	3% < Cross Slope < 5%	Driveway/Driveway Flare		CLARK PL SE - W	Other	9/1/2020
5081	WLK840	Cross Slope > 5%	Driveway/Driveway Flare		CLARK PL SE - W	Other	9/1/2020
5082	WLK840	Cross Slope > 5%	Driveway/Driveway Flare		CLARK PL SE - W	Other	9/1/2020
5083	WLK841	Minor Cracking	Age		CLARK PL SE - E	Other	9/1/2020
5084	WLK841	2% < Cross Slope < 3%	Driveway/Driveway Flare		CLARK PL SE - E	Other	9/1/2020
5085	WLK841	Cross Slope > 5%	Driveway/Driveway Flare		CLARK PL SE - E	Other	9/1/2020
5086	WLK841	Vertical displacement > 1-1/4 inch	Driveway/Driveway Flare		CLARK PL SE - E	Other	9/1/2020
5087	WLK841	3% < Cross Slope < 5%	Driveway/Driveway Flare		CLARK PL SE - E	Other	9/1/2020
5088	WLK841	Moderate Cracking	Age		CLARK PL SE - E	Other	9/1/2020
5089	WLK775	3% < Cross Slope < 5%	Driveway/Driveway Flare		CUSTER WAY SW - N	Minor Arterial	9/1/2020
5090	WLK774	Cross Slope > 5%	Driveway/Driveway Flare		CUSTER WAY SW - S	Minor Arterial	9/1/2020
5091	WLK837	Minor Cracking	Age		BATES ST SE - S	Other	9/1/2020
5092	WLK836	Moderate Cracking	Age		BATES ST SE - N	Other	9/1/2020
5093	WLK836	No passing space			BATES ST SE - N	Other	9/1/2020
5094	WLK836	Minor Cracking	Age		BATES ST SE - N	Other	9/1/2020
5095	WLK843	Minor Spalling	Age		ERIE ST SE - E	Other	9/1/2020
5096	WLK843	Cross Slope > 5%	Driveway/Driveway Flare		ERIE ST SE - E	Other	9/1/2020
5097	WLK843	Cross Slope > 5%	Driveway/Driveway Flare		ERIE ST SE - E	Other	9/1/2020
5098	WLK842	No passing space			ERIE ST SE - W	Other	9/1/2020
5099	WLK842	Minor Cracking	Age		ERIE ST SE - W	Other	9/1/2020
5100	WLK842	Cross Slope > 5%	Driveway/Driveway Flare		ERIE ST SE - W	Other	9/1/2020
5101	WLK842	Severe Cracking	Settlement		ERIE ST SE - W	Other	9/1/2020
5102	WLK838	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5103	WLK838	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5104	WLK838	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5105	WLK838	3% < Cross Slope < 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5106	WLK837	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5107	WLK837	Crack < 3/4 inch	Settlement		BATES ST SE - S	Other	9/1/2020
5108	WLK836	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - N	Other	9/1/2020
5109	WLK837	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5110	WLK837	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5111	WLK837	Cross Slope > 5%	Driveway/Driveway Flare		BATES ST SE - S	Other	9/1/2020
5112	WLK775	Cross Slope > 5%	Driveway/Driveway Flare		CUSTER WAY SW - N	Minor Arterial	9/1/2020
5113	WLK770	Crack < 3/4 inch	Age		CUSTER WAY SW - N	Minor Arterial	9/1/2020
5114	WLK771	Cross Slope > 5%			SCHMIDT PL SW - E	Other	9/1/2020
5115	WLK1112	No passing space			DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5116	WLK1114	5% < Running Slope < 8.33%	Driveway/Driveway Flare		DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5117	WLK1115	Running Slope > 8.33%	Driveway/Driveway Flare		DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5118	WLK1115	Running Slope > 8.33%	Driveway/Driveway Flare		DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5119	WLK1115	Running Slope > 8.33%	Driveway/Driveway Flare		DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5120	WLK1127	Cross Slope > 5%	Driveway/Driveway Flare		TUMWATER VALLEY DR SE - W	Other	9/1/2020
5121	WLK1118	3% < Cross Slope < 5%			DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5122	WLK1118	2% < Cross Slope < 3%			DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5123	WLK1118	3% < Cross Slope < 5%			DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5124	WLK1118	3% < Cross Slope < 5%			DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5125	WLK1118	Crack < 3/4 inch	Settlement		DESCHUTES PKWY SW - E	Minor Arterial	9/1/2020
5126	WLK1119	Cross Slope > 5%	Driveway/Driveway Flare		C ST SW - S	Other	9/1/2020
5127	WLK1062	Crack < 3/4 inch	Age				9/1/2020
5128	WLK1062	Cross Slope > 5%	Driveway/Driveway Flare				9/1/2020
5129	WLK1062	3% < Cross Slope < 5%	Driveway/Driveway Flare				9/1/2020
5130	WLK1062	Cross Slope > 5%	Driveway/Driveway Flare				9/1/2020
5131	WLK1062	Cross Slope > 5%	Driveway/Driveway Flare				9/1/2020
5132	WLK1132	2% < Cross Slope < 3%			RAINIER AVE SE - W	Other	9/1/2020
5133	WLK1132	Cross Slope > 5%	Driveway/Driveway Flare		RAINIER AVE SE - W	Other	9/1/2020
5134	WLK1133	Cross Slope > 5%	Driveway/Driveway Flare		RAINIER AVE SE - W	Other	9/1/2020
5135	WLK1137	Crack > 1-1/4 inch	Settlement		RAINIER AVE SE - E	Other	9/1/2020
5136	WLK1136	Cross Slope > 5%	Driveway/Driveway Flare		O ST SE - S	Other	9/1/2020
5137	WLK1136	3% < Cross Slope < 5%	Driveway/Driveway Flare		O ST SE - S	Other	9/1/2020
5138	WLK1136	Crack > 1-1/4 inch	Age		O ST SE - S	Other	9/1/2020
5139	WLK1136	Cross Slope > 5%	Driveway/Driveway Flare		O ST SE - S	Other	9/1/2020
5140	WLK1136	Minor Cracking	Age		O ST SE - S	Other	9/1/2020
5141	WLK1134	Cross Slope > 5%	Driveway/Driveway Flare		RAINIER AVE SE - E	Other	9/1/2020
5142	WLK1134	Cross Slope > 5%	Driveway/Driveway Flare		RAINIER AVE SE - E	Other	9/1/2020
5143	WLK1134	Severe Cracking			RAINIER AVE SE - E	Other	9/1/2020
5144	WLK1135	Cross Slope > 5%	Root System		M ST SE - S	Other	9/1/2020
5145	WLK1135	Crack < 3/4 inch	Age		M ST SE - S	Other	9/1/2020
5146	WLK1135	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Other	9/1/2020
5147	WLK1135	Vertical displacement < 3/4 inch	Settlement		M ST SE - S	Other	9/1/2020
5148	WLK1135	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Other	9/1/2020
5149	WLK1135	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Other	9/1/2020
5150	WLK1131	No passing space		Dirt on Sidewalk	M ST SE - S	Other	9/1/2020
5151	WLK1164	Vertical displacement < 3/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5152	WLK1164	3% < Cross Slope < 5%			M ST SE - S	Principal Arterial	9/2/2020
5153	WLK1163	3% < Cross Slope < 5%			M ST SE - S	Principal Arterial	9/2/2020
5154	WLK1163	Crack < 3/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5155	WLK1163	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5156	WLK1163	Crack < 3/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5157	WLK1163	Crack < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5158	WLK1163	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5159	WLK1163	Severe Cracking	Root System		M ST SE - S	Principal Arterial	9/2/2020
5160	WLK1163	Severe Cracking			M ST SE - S	Principal Arterial	9/2/2020
5161	WLK1163	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5162	WLK1163	Crack < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5163	WLK1163	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5164	WLK1163	Cross Slope > 5%	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5165	WLK1163	Vertical displacement < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5166	WLK1163	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5167	WLK1163	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5168	WLK1158	Vertical displacement < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5169	WLK1158	Crack < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5170	WLK1158	Severe Cracking	Age		M ST SE - S	Principal Arterial	9/2/2020
5171	WLK1536	Cross Slope > 5%	Driveway/Driveway Flare		T ST SW - N	Other	9/2/2020
5172	WLK1156	Minor Cracking	Settlement			Principal Arterial	9/2/2020
5173	WLK1157	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5174	WLK1157	Minor Cracking	Root System		M ST SE - S	Principal Arterial	9/2/2020
5175	WLK1157	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5176	WLK1154	Minor Cracking	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5177	WLK1154	Crack < 3/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5178	WLK1153	Vertical displacement < 3/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5179	WLK1153	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5180	WLK1153	Crack between 3/4 inch and 1-1/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5181	WLK1150	2% < Cross Slope < 3%			M ST SE - S	Principal Arterial	9/2/2020
5182	WLK1150	Running Slope > 8.33%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5183	WLK1150	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5184	WLK1150	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5185	WLK1150	Minor Cracking	Root System		M ST SE - S	Principal Arterial	9/2/2020
5186	WLK1147	Cross Slope > 5%			M ST SE - S	Principal Arterial	9/2/2020
5187	WLK1141	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5188	WLK1141	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5189	WLK1141	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5190	WLK1141	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5191	WLK1141	Crack < 3/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5192	WLK1141	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5193	WLK1141	Cross Slope > 5%			M ST SE - S	Principal Arterial	9/2/2020
5194	WLK1141	3% < Cross Slope < 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5195	WLK1141	3% < Cross Slope < 5%			M ST SE - S	Principal Arterial	9/2/2020
5196	WLK1141	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5206	WLK1138	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5207	WLK1138	Crack < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5208	WLK1138	Vertical displacement < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5209	WLK1138	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5210	WLK1138	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5211	WLK1138	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5212	WLK1138	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5213	WLK1138	Vertical displacement between 3/4 inch and 1-1/4 inch			M ST SE - S	Principal Arterial	9/2/2020
5214	WLK1130	5% < Running Slope < 8.33%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5215	WLK1129	3% < Cross Slope < 5%	Root System			Principal Arterial	9/2/2020
5216	WLK1129	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5217	WLK1129	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5218	WLK1129	Passing Space > 400'				Principal Arterial	9/2/2020
5219	WLK1129	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5220	WLK1129	Crack < 3/4 inch	Age			Principal Arterial	9/2/2020
5221	WLK1129	Crack between 3/4 inch and 1-1/4 inch	Settlement			Principal Arterial	9/2/2020
5222	WLK1129	Crack < 3/4 inch	Settlement			Principal Arterial	9/2/2020
5223	WLK1129	Crack < 3/4 inch	Age			Principal Arterial	9/2/2020
5224	WLK1129	Crack < 3/4 inch	Age			Principal Arterial	9/2/2020
5225	WLK1129	Crack < 3/4 inch	Age			Principal Arterial	9/2/2020
5226	WLK1139	Hole between 3/4 inch and 1-1/4 inch	Age			Principal Arterial	9/2/2020
5227	WLK1139	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5228	WLK1139	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5229	WLK1139	Moderate Cracking	Age			Principal Arterial	9/2/2020
5230	WLK1139	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5231	WLK1139	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5232	WLK1140	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5233	WLK1140	3% < Cross Slope < 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5234	WLK1140	3% < Cross Slope < 5%				Principal Arterial	9/2/2020
5235	WLK1140	Severe Cracking	Age			Principal Arterial	9/2/2020
5236	WLK1140	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5237	WLK1144	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5238	WLK1145	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5239	WLK1145	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5240	WLK1145	Severe Cracking	Age			Principal Arterial	9/2/2020
5241	WLK1145	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5242	WLK1145	Vertical displacement > 1-1/4 inch	Settlement			Principal Arterial	9/2/2020
5243	WLK1145	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5244	WLK1145	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement			Principal Arterial	9/2/2020
5245	WLK1146	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5246	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5247	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5248	WLK1166	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System			Principal Arterial	9/2/2020
5249	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5250	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5251	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5252	WLK1166	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5253	WLK1168	Vertical displacement > 1-1/4 inch	Root System			Principal Arterial	9/2/2020
5254	WLK1168	3% < Cross Slope < 5%	Root System			Principal Arterial	9/2/2020
5255	WLK1168	3% < Cross Slope < 5%	Root System			Principal Arterial	9/2/2020
5256	WLK1168	Crack < 3/4 inch	Root System			Principal Arterial	9/2/2020
5257	WLK1168	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5258	WLK1168	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5259	WLK1171	3% < Cross Slope < 5%	Root System			Principal Arterial	9/2/2020
5260	WLK1171	Cross Slope > 5%	Root System			Principal Arterial	9/2/2020
5261	WLK1171	5% < Running Slope < 8.33%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5262	WLK1172	Running Slope > 8.33%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5263	WLK1172	Running Slope > 8.33%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5264	WLK1174	Crack between 3/4 inch and 1-1/4 inch	Root System			Principal Arterial	9/2/2020
5265	WLK1177	5% < Running Slope < 8.33%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5266	WLK1175	3% < Cross Slope < 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5267	WLK1175	Vertical displacement < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5268	WLK1175	Vertical displacement > 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5269	WLK1175	3% < Cross Slope < 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5270	WLK1173	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5271	WLK1173	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5272	WLK1171	3% < Cross Slope < 5%	Root System			Principal Arterial	9/2/2020
5273	WLK1170	Vertical displacement < 3/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5274	WLK1170	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5275	WLK1170	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5276	WLK1170	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5277	WLK1170	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5278	WLK1170	3% < Cross Slope < 5%			M ST SE - S	Principal Arterial	9/2/2020
5279	WLK1171	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5280	WLK1170	3% < Cross Slope < 5%			M ST SE - S	Principal Arterial	9/2/2020
5281	WLK1169	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5282	WLK1169	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5283	WLK1169	Crack < 3/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5284	WLK1169	Cross Slope > 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5285	WLK1169	3% < Cross Slope < 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5286	WLK1167	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5287	WLK1167	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5288	WLK1167	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5289	WLK1167	3% < Cross Slope < 5%	Root System		M ST SE - S	Principal Arterial	9/2/2020
5290	WLK1167	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5291	WLK1167	Vertical displacement > 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5292	WLK1125	Running Slope > 8.33%	Driveway/Driveway Flare		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5293	WLK1123	Minor Spalling	Age			Principal Arterial	9/2/2020
5294	WLK1123	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5295	WLK1123	Minor Cracking	Settlement			Principal Arterial	9/2/2020
5296	WLK825	Cross Slope > 5%			CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5297	WLK825	Minor Cracking	Age		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5298	WLK825	Crack < 3/4 inch	Settlement		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5299	WLK825	Cross Slope > 5%	Age		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5300	WLK825	3% < Cross Slope < 5%			CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5301	WLK825	Moderate Spalling	Age		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5302	WLK825	Vertical displacement > 1-1/4 inch	Settlement		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5303	WLK825	Vertical displacement > 1-1/4 inch	Settlement		CAPITOL BLVD SW - W	Principal Arterial	9/2/2020
5304	WLK824	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5305	WLK824	3% < Cross Slope < 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5306	WLK824	Cross Slope > 5%	Driveway/Driveway Flare			Principal Arterial	9/2/2020
5307	WLK822	Vertical displacement < 3/4 inch	Root System			Principal Arterial	9/2/2020
5308	WLK822	Crack < 3/4 inch	Settlement			Principal Arterial	9/2/2020
5309	WLK822	Crack < 3/4 inch	Age			Principal Arterial	9/2/2020
5310	WLK826	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		M ST SE - S	Principal Arterial	9/2/2020
5311	WLK826	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5312	WLK826	Cross Slope > 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5313	WLK826	3% < Cross Slope < 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5314	WLK826	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5315	WLK826	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5316	WLK826	3% < Cross Slope < 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5317	WLK826	3% < Cross Slope < 5%	Driveway/Driveway Flare		M ST SE - S	Principal Arterial	9/2/2020
5318	WLK1124	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5319	WLK1124	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5320	WLK1124	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		M ST SE - S	Principal Arterial	9/2/2020
5321	WLK1124	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5322	WLK1124	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5323	WLK1124	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5324	WLK1124	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5325	WLK1124	Crack > 1-1/4 inch	Age		M ST SE - S	Principal Arterial	9/2/2020
5326	WLK1123	Cross Slope > 5%				Principal Arterial	9/2/2020
5327	WLK1658	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - S	Other	9/2/2020
5328	WLK1658	Moderate Cracking	Age		EMERSON ST SW - S	Other	9/2/2020
5329	WLK1658	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - S	Other	9/2/2020
5330	WLK1658	No passing space			EMERSON ST SW - S	Other	9/2/2020
5331	WLK475	Crack > 1-1/4 inch	Age		EMERSON ST SW - N	Other	9/2/2020
5332	WLK475	Crack > 1-1/4 inch	Age		EMERSON ST SW - N	Other	9/2/2020
5333	WLK475	Crack between 3/4 inch and 1-1/4 inch	Age		EMERSON ST SW - N	Other	9/2/2020
5334	WLK475	Crack > 1-1/4 inch	Age		EMERSON ST SW - N	Other	9/2/2020
5335	WLK475	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - N	Other	9/2/2020
5336	WLK506	Crack > 1-1/4 inch	Age		GRANT ST SW - N	Other	9/2/2020
5337	WLK475	Cross Slope > 5%	Driveway/Driveway Flare		EMERSON ST SW - N	Other	9/2/2020
5338	WLK565	3% < Cross Slope < 5%			CROSBY BLVD SW - N	Minor Arterial	9/2/2020
5339	WLK570	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5340	WLK570	Cross Slope > 5%	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5341	WLK570	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5342	WLK570	3% < Cross Slope < 5%			CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5343	WLK570	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5344	WLK570	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5345	WLK570	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5346	WLK570	Cross Slope > 5%			CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5347	WLK570	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5348	WLK568	Cross Slope > 5%	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5349	WLK568	Cross Slope > 5%	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5350	WLK566	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - S	Minor Arterial	9/2/2020
5351	WLK561	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5352	WLK561	Vertical displacement < 3/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5353	WLK561	Vertical displacement < 3/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5354	WLK561	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5355	WLK561	Vertical displacement > 1-1/4 inch	Root System		CROSBY BLVD SW - E	Minor Arterial	9/2/2020
5356	WLK562	Crack < 3/4 inch	Root System		CROSBY BLVD SW - W	Minor Arterial	9/2/2020
5357	WLK564	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - N	Minor Arterial	9/2/2020
5358	WLK564	Cross Slope > 5%	Driveway/Driveway Flare		CROSBY BLVD SW - N	Minor Arterial	9/2/2020
5359	WLK1404	No passing space			73RD AVE SE - S	Other	9/2/2020
5360	WLK1404	3% < Cross Slope < 5%			73RD AVE SE - S	Other	9/2/2020
5361	WLK1405	No passing space			HENDERSON CT SE - W	Other	9/2/2020
5362	WLK1405	No passing space			HENDERSON CT SE - W	Other	9/2/2020
5363	WLK1181	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		OLD HWY 99 - E	Minor Arterial	9/2/2020
5364	WLK1181	Vertical displacement < 3/4 inch	Settlement		OLD HWY 99 - E	Minor Arterial	9/2/2020
5365	WLK1181	Severe Cracking	Settlement		OLD HWY 99 - E	Minor Arterial	9/2/2020
5366	WLK1181	Vertical displacement < 3/4 inch	Settlement		OLD HWY 99 - E	Minor Arterial	9/2/2020
5367	WLK1182	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		OLD HWY 99 - E	Minor Arterial	9/2/2020
5368	WLK1182	Vertical displacement < 3/4 inch	Root System		OLD HWY 99 - E	Minor Arterial	9/2/2020
5369	WLK1182	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		OLD HWY 99 - E	Minor Arterial	9/2/2020
5370	WLK1182	5% < Running Slope < 8.33%	Root System		OLD HWY 99 - E	Minor Arterial	9/2/2020
5371	WLK1184	No passing space			OLD HWY 99 - E	Minor Arterial	9/2/2020
5372	WLK1186	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT ST SE - S	Other	9/2/2020
5373	WLK1186	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT ST SE - S	Other	9/2/2020
5374	WLK231	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GOLD CREEK DR SW - E	Other	9/3/2020
5375	WLK231	3% < Cross Slope < 5%	Root System		GOLD CREEK DR SW - E	Other	9/3/2020
5376	WLK231	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		GOLD CREEK DR SW - E	Other	9/3/2020
5377	WLK231	Vertical displacement < 3/4 inch	Root System		GOLD CREEK DR SW - E	Other	9/3/2020
5378	WLK231	Vertical displacement < 3/4 inch	Root System		GOLD CREEK DR SW - E	Other	9/3/2020
5379	WLK231	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - E	Other	9/3/2020
5380	WLK231	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - E	Other	9/3/2020
5381	WLK231	Crack < 3/4 inch	Age		GOLD CREEK DR SW - E	Other	9/3/2020
5382	WLK231	Vertical displacement < 3/4 inch	Settlement		GOLD CREEK DR SW - E	Other	9/3/2020
5383	WLK231	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - E	Other	9/3/2020
5384	WLK231	2% < Cross Slope < 3%	Driveway/Driveway Flare		GOLD CREEK DR SW - E	Other	9/3/2020
5385	WLK231	Crack > 1-1/4 inch	Age		GOLD CREEK DR SW - E	Other	9/3/2020
5386	WLK231	Crack > 1-1/4 inch	Age		GOLD CREEK DR SW - E	Other	9/3/2020
5387	WLK231	Crack < 3/4 inch	Age		GOLD CREEK DR SW - E	Other	9/3/2020
5388	WLK232	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - W	Other	9/3/2020
5389	WLK232	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - W	Other	9/3/2020
5390	WLK232	5% < Running Slope < 8.33%	Root System		GOLD CREEK CT SW - W	Other	9/3/2020
5391	WLK232	Running Slope > 8.33%	Root System		GOLD CREEK CT SW - W	Other	9/3/2020
5392	WLK232	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - W	Other	9/3/2020
5393	WLK232	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - W	Other	9/3/2020
5394	WLK233	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - E	Other	9/3/2020
5395	WLK233	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK CT SW - E	Other	9/3/2020
5396	WLK233	Crack < 3/4 inch	Root System		GOLD CREEK CT SW - E	Other	9/3/2020
5397	WLK234	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - S	Other	9/3/2020
5398	WLK234	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - S	Other	9/3/2020
5399	WLK234	Crack < 3/4 inch	Settlement		GOLD CREEK DR SW - S	Other	9/3/2020
5400	WLK234	3% < Cross Slope < 5%			GOLD CREEK DR SW - S	Other	9/3/2020
5401	WLK234	Crack < 3/4 inch	Root System		GOLD CREEK DR SW - S	Other	9/3/2020
5402	WLK236	Crack > 1-1/4 inch	Age		MINER DR SW - W	Urban Collector	9/3/2020
5403	WLK236	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5404	WLK236	Crack < 3/4 inch	Settlement		MINER DR SW - W	Urban Collector	9/3/2020
5405	WLK236	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5406	WLK236	Running Slope > 8.33%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5407	WLK236	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5408	WLK236	Vertical displacement < 3/4 inch	Root System		MINER DR SW - W	Urban Collector	9/3/2020
5409	WLK236	Vertical displacement > 1-1/4 inch	Root System		MINER DR SW - W	Urban Collector	9/3/2020
5410	WLK237	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - N	Urban Collector	9/3/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5411	WLK237	Crack > 1-1/4 inch	Age		MINER DR SW - N	Urban Collector	9/3/2020
5412	WLK237	Severe Cracking	Age		MINER DR SW - N	Urban Collector	9/3/2020
5413	WLK237	Severe Cracking	Age		MINER DR SW - N	Urban Collector	9/3/2020
5414	WLK237	Minor Cracking	Age		MINER DR SW - N	Urban Collector	9/3/2020
5415	WLK237	Crack > 1-1/4 inch	Age		MINER DR SW - N	Urban Collector	9/3/2020
5416	WLK237	Crack > 1-1/4 inch	Age		MINER DR SW - N	Urban Collector	9/3/2020
5417	WLK237	Crack > 1-1/4 inch	Age		MINER DR SW - N	Urban Collector	9/3/2020
5418	WLK237	Crack > 1-1/4 inch	Age		MINER DR SW - N	Urban Collector	9/3/2020
5419	WLK238	Crack < 3/4 inch	Root System		MINER CT SW - E	Other	9/3/2020
5420	WLK238	Cross Slope > 5%	Root System		MINER CT SW - E	Other	9/3/2020
5421	WLK238	Crack > 1-1/4 inch	Root System		MINER CT SW - E	Other	9/3/2020
5422	WLK238	3% < Cross Slope < 5%	Root System		MINER CT SW - E	Other	9/3/2020
5423	WLK238	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER CT SW - E	Other	9/3/2020
5424	WLK238	3% < Cross Slope < 5%	Root System		MINER CT SW - E	Other	9/3/2020
5425	WLK238	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MINER CT SW - E	Other	9/3/2020
5426	WLK238	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER CT SW - E	Other	9/3/2020
5427	WLK238	Cross Slope > 5%	Driveway/Driveway Flare		MINER CT SW - E	Other	9/3/2020
5428	WLK239	Cross Slope > 5%	Driveway/Driveway Flare		MINER CT SW - W	Other	9/3/2020
5429	WLK239	3% < Cross Slope < 5%	Root System		MINER CT SW - W	Other	9/3/2020
5430	WLK239	2% < Cross Slope < 3%	Driveway/Driveway Flare		MINER CT SW - W	Other	9/3/2020
5431	WLK239	3% < Cross Slope < 5%	Root System		MINER CT SW - W	Other	9/3/2020
5432	WLK239	Vertical displacement < 3/4 inch	Root System		MINER CT SW - W	Other	9/3/2020
5433	WLK239	Cross Slope > 5%	Root System		MINER CT SW - W	Other	9/3/2020
5434	WLK240	Crack > 1-1/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5435	WLK240	Crack > 1-1/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5436	WLK240	Crack > 1-1/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5437	WLK240	Crack > 1-1/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5438	WLK240	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5439	WLK240	Vertical displacement between 3/4 inch and 1-1/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5440	WLK240	Cross Slope > 5%	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5441	WLK240	Vertical displacement < 3/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5442	WLK240	Vertical displacement < 3/4 inch	Age		MINER DR SW - E	Urban Collector	9/3/2020
5443	WLK240	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5444	WLK240	3% < Cross Slope < 5%	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5445	WLK240	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5446	WLK240	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5447	WLK240	2% < Cross Slope < 3%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5448	WLK240	Vertical displacement < 3/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5449	WLK240	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5450	WLK240	5% < Running Slope < 8.33%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5451	WLK234	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - S	Other	9/3/2020
5452	WLK234	Vertical displacement > 1-1/4 inch	Root System		GOLD CREEK DR SW - S	Other	9/3/2020
5453	WLK240	Vertical displacement > 1-1/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5454	WLK241	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5455	WLK241	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5456	WLK241	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5457	WLK241	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - E	Urban Collector	9/3/2020
5458	WLK241	Vertical displacement > 1-1/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5459	WLK241	Crack < 3/4 inch	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5460	WLK241	3% < Cross Slope < 5%	Root System		MINER DR SW - E	Urban Collector	9/3/2020
5461	WLK242	Crack between 3/4 inch and 1-1/4 inch	Root System		MINER DR SW - W	Urban Collector	9/3/2020
5462	WLK242	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5463	WLK242	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5464	WLK242	Cross Slope > 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5465	WLK242	3% < Cross Slope < 5%	Driveway/Driveway Flare		MINER DR SW - W	Urban Collector	9/3/2020
5466	WLK235	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - N	Other	9/3/2020
5467	WLK235	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - N	Other	9/3/2020
5468	WLK235	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - N	Other	9/3/2020
5469	WLK235	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - N	Other	9/3/2020
5470	WLK230	Hole < 3/4 inch	Age		GOLD CREEK DR SW - W	Other	9/3/2020
5471	WLK230	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5472	WLK230	Crack between 3/4 inch and 1-1/4 inch	Root System		GOLD CREEK DR SW - W	Other	9/3/2020
5473	WLK230	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5474	WLK230	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5475	WLK230	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5476	WLK230	Cross Slope > 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5477	WLK230	3% < Cross Slope < 5%	Driveway/Driveway Flare		GOLD CREEK DR SW - W	Other	9/3/2020
5478	WLK229	Crack between 3/4 inch and 1-1/4 inch	Age		70TH AVE SW - N	Urban Collector	9/3/2020
5479	WLK229	No passing space			70TH AVE SW - N	Urban Collector	9/3/2020
5480	WLK229	Vertical displacement > 1-1/4 inch	Settlement		70TH AVE SW - N	Urban Collector	9/3/2020
5481	WLK229	Moderate Cracking	Settlement		70TH AVE SW - N	Urban Collector	9/3/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5482	WLK229	No passing space			70TH AVE SW - N	Urban Collector	9/3/2020
5483	WLK218	3% < Cross Slope < 5%	Driveway/Driveway Flare		MIRASETT ST SW - W	Other	9/3/2020
5484	WLK222	Vertical displacement < 3/4 inch	Root System		MIRASETT ST SW - E	Other	9/3/2020
5485	WLK222	Vertical displacement < 3/4 inch	Root System		MIRASETT ST SW - E	Other	9/3/2020
5487	WLK223	5% < Running Slope < 8.33%			MIRASETT ST SW - E	Other	9/3/2020
5488	WLK224	Vertical displacement < 3/4 inch	Age		MIRASETT ST SW - E	Other	9/3/2020
5489	WLK227	2% < Cross Slope < 3%			LAZY CT SW - W	Other	9/3/2020
5490	WLK227	Vertical displacement < 3/4 inch	Root System		LAZY CT SW - W	Other	9/3/2020
5491	WLK227	Crack < 3/4 inch	Root System		LAZY CT SW - W	Other	9/3/2020
5492	WLK227	Cross Slope > 5%	Root System		LAZY CT SW - W	Other	9/3/2020
5493	WLK227	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		LAZY CT SW - W	Other	9/3/2020
5494	WLK215	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		71ST WAY SW - S	Other	9/3/2020
5495	WLK213	Vertical displacement > 1-1/4 inch	Root System		SOUTHWICK CT SW - W	Other	9/3/2020
5496	WLK214	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		SOUTHWICK CT SW - E	Other	9/3/2020
5497	WLK217	Vertical displacement < 3/4 inch	Root System		SOUTHWICK CT SW - S	Other	9/3/2020
5498	WLK217	3% < Cross Slope < 5%			SOUTHWICK CT SW - S	Other	9/3/2020
5499	WLK210	Minor Cracking	Age		70TH AVE SW - S	Urban Collector	9/3/2020
5500	WLK207	Vertical displacement > 1-1/4 inch	Settlement		70TH AVE SW - N	Urban Collector	9/3/2020
5501	WLK207	Vertical displacement > 1-1/4 inch	Settlement		70TH AVE SW - N	Urban Collector	9/3/2020
5502	WLK207	Crack < 3/4 inch	Age		70TH AVE SW - N	Urban Collector	9/3/2020
5503	WLK210	3% < Cross Slope < 5%			70TH AVE SW - S	Urban Collector	9/3/2020
5504	WLK210	Vertical displacement < 3/4 inch	Root System		70TH AVE SW - S	Urban Collector	9/3/2020
5505	WLK195	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5506	WLK195	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5507	WLK195	3% < Cross Slope < 5%	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5508	WLK195	3% < Cross Slope < 5%	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5509	WLK195	Moderate Cracking	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5510	WLK194	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5511	WLK194	Crack < 3/4 inch	Age		BRONINGTON DR SW - N	Other	9/3/2020
5512	WLK194	5% < Running Slope < 8.33%	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5513	WLK194	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5514	WLK194	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - N	Other	9/3/2020
5515	WLK193	Vertical displacement < 3/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5516	WLK193	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5517	WLK193	Crack between 3/4 inch and 1-1/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5518	WLK193	Crack between 3/4 inch and 1-1/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5519	WLK193	Vertical displacement < 3/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5520	WLK193	Crack < 3/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5521	WLK193	Crack < 3/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5522	WLK193	Vertical displacement > 1-1/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5523	WLK193	Crack < 3/4 inch	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5524	WLK193	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5525	WLK193	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - W	Other	9/3/2020
5526	WLK187	Running Slope > 8.33%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5527	WLK187	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5528	WLK187	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5529	WLK187	Vertical displacement < 3/4 inch	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5530	WLK187	Cross Slope > 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5531	WLK187	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5532	WLK187	Cross Slope > 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5533	WLK187	3% < Cross Slope < 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5534	WLK160	Crack < 3/4 inch	Age		KIRSOP VILLAGE DR SW - W	Other	9/3/2020
5535	WLK187	2% < Cross Slope < 3%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5536	WLK187	2% < Cross Slope < 3%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5537	WLK187	Cross Slope > 5%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5538	WLK187	Running Slope > 8.33%	Root System		ROTHENBERG DR SW - E	Other	9/3/2020
5539	WLK181	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5540	WLK181	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5541	WLK180	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5542	WLK180	5% < Running Slope < 8.33%	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5543	WLK180	3% < Cross Slope < 5%	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5544	WLK180	Running Slope > 8.33%	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5545	WLK180	Vertical displacement > 1-1/4 inch	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5546	WLK180	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BRONINGTON DR SW - S	Other	9/3/2020
5547	WLK179	Vertical displacement < 3/4 inch	Settlement		BRONINGTON DR SW - W	Other	9/3/2020
5548	WLK179	Crack < 3/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5549	WLK179	Cross Slope > 5%	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5550	WLK179	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5551	WLK179	Vertical displacement < 3/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5552	WLK179	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5553	WLK179	5% < Running Slope < 8.33%	Root System		BRONINGTON DR SW - W	Other	9/3/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5554	WLK179	Crack < 3/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5555	WLK178	Crack < 3/4 inch	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5556	WLK178	3% < Cross Slope < 5%	Root System		BRONINGTON DR SW - W	Other	9/3/2020
5557	WLK191	Crack < 3/4 inch	Root System		BRONINGTON DR SW - E	Other	9/3/2020
5558	WLK190	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		70TH WAY SW - N	Other	9/3/2020
5559	WLK190	Vertical displacement < 3/4 inch	Root System		70TH WAY SW - N	Other	9/3/2020
5560	WLK189	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		70TH WAY SW - N	Other	9/3/2020
5561	WLK189	Vertical displacement < 3/4 inch	Root System		70TH WAY SW - N	Other	9/3/2020
5562	WLK188	Crack < 3/4 inch	Root System		70TH WAY SW - S	Other	9/3/2020
5563	WLK192	3% < Cross Slope < 5%	Root System		70TH WAY SW - S	Other	9/3/2020
5564	WLK192	3% < Cross Slope < 5%	Root System		70TH WAY SW - S	Other	9/3/2020
5565	WLK192	3% < Cross Slope < 5%	Root System		70TH WAY SW - S	Other	9/3/2020
5566	WLK171	Crack < 3/4 inch	Root System		68TH AVE SW - N	Other	9/3/2020
5567	WLK171	Vertical displacement > 1-1/4 inch	Root System		68TH AVE SW - N	Other	9/3/2020
5568	WLK171	3% < Cross Slope < 5%	Root System		68TH AVE SW - N	Other	9/3/2020
5569	WLK171	Vertical displacement > 1-1/4 inch	Root System		68TH AVE SW - N	Other	9/3/2020
5570	WLK171	Vertical displacement > 1-1/4 inch	Root System		68TH AVE SW - N	Other	9/3/2020
5571	WLK173	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		KIRSOP VILLAGE DR SW - E	Other	9/3/2020
5572	WLK174	Crack < 3/4 inch	Root System		70TH AVE SW - N	Other	9/3/2020
5573	WLK174	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		70TH AVE SW - N	Other	9/3/2020
5574	WLK174	Vertical displacement < 3/4 inch	Root System		70TH AVE SW - N	Other	9/3/2020
5575	WLK174	Vertical displacement < 3/4 inch	Root System		70TH AVE SW - N	Other	9/3/2020
5576	WLK175	Vertical displacement < 3/4 inch	Root System		66TH AVE SW - S	Urban Collector	9/3/2020
5577	WLK160	Vertical displacement > 1-1/4 inch	Root System		KIRSOP VILLAGE DR SW - W	Other	9/3/2020
5578	WLK160	3% < Cross Slope < 5%	Root System		KIRSOP VILLAGE DR SW - W	Other	9/3/2020
5579	WLK160	Vertical displacement > 1-1/4 inch	Root System		KIRSOP VILLAGE DR SW - W	Other	9/3/2020
5580	WLK163	Vertical displacement < 3/4 inch			68TH AVE SW - W	Other	9/3/2020
5581	WLK164	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		68TH AVE SW - W	Other	9/3/2020
5582	WLK170	Vertical displacement < 3/4 inch	Root System		68TH AVE SW - S	Other	9/3/2020
5583	WLK170	Vertical displacement > 1-1/4 inch	Root System		68TH AVE SW - S	Other	9/3/2020
5584	WLK168	Vertical displacement < 3/4 inch	Root System		KIRSOP LN SW - E	Other	9/3/2020
5585	WLK168	Vertical displacement < 3/4 inch	Root System		KIRSOP LN SW - E	Other	9/3/2020
5586	WLK206	Vertical displacement > 1-1/4 inch		plants in sidewalk cracks	KIRSOP RD SW - S	Urban Collector	9/3/2020
5587	WLK206	Cross Slope > 5%	Driveway/Driveway Flare		KIRSOP RD SW - S	Urban Collector	9/3/2020
5588	WLK206	Crack < 3/4 inch	Settlement		KIRSOP RD SW - S	Urban Collector	9/3/2020
5589	WLK206	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		KIRSOP RD SW - S	Urban Collector	9/3/2020
5590	WLK206	Vertical displacement < 3/4 inch	Root System		KIRSOP RD SW - S	Urban Collector	9/3/2020
5591	WLK206	Moderate Cracking	Age		KIRSOP RD SW - S	Urban Collector	9/3/2020
5592	WLK206	Cross Slope > 5%	Driveway/Driveway Flare		KIRSOP RD SW - S	Urban Collector	9/3/2020
5593	WLK206	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		KIRSOP RD SW - S	Urban Collector	9/3/2020
5594	WLK206	Cross Slope > 5%	Driveway/Driveway Flare		KIRSOP RD SW - S	Urban Collector	9/3/2020
5595	WLK206	Crack < 3/4 inch	Root System		KIRSOP RD SW - S	Urban Collector	9/3/2020
5596	WLK142	5% < Running Slope < 8.33%	Driveway/Driveway Flare		CAVALIER ST SW - W	Other	9/3/2020
5597	WLK142	5% < Running Slope < 8.33%	Driveway/Driveway Flare		CAVALIER ST SW - W	Other	9/3/2020
5598	WLK142	Cross Slope > 5%	Driveway/Driveway Flare		CAVALIER ST SW - W	Other	9/3/2020
5599	WLK142	Cross Slope > 5%	Driveway/Driveway Flare		CAVALIER ST SW - W	Other	9/3/2020
5600	WLK142	Cross Slope > 5%	Driveway/Driveway Flare		CAVALIER ST SW - W	Other	9/3/2020
5601	WLK142	No passing space			CAVALIER ST SW - W	Other	9/3/2020
5602	WLK143	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		67TH CT SW - N	Other	9/3/2020
5603	WLK143	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		67TH CT SW - N	Other	9/3/2020
5604	WLK143	3% < Cross Slope < 5%	Root System		67TH CT SW - N	Other	9/3/2020
5605	WLK145	No passing space			CAVALIER ST SW - W	Other	9/3/2020
5606	WLK145	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CAVALIER ST SW - W	Other	9/3/2020
5607	WLK145	Vertical displacement > 1-1/4 inch	Root System		CAVALIER ST SW - W	Other	9/3/2020
5608	WLK145	Severe Cracking	Root System		CAVALIER ST SW - W	Other	9/3/2020
5609	WLK146	Cross Slope > 5%			68TH CT SW - N	Other	9/3/2020
5610	WLK146	3% < Cross Slope < 5%	Root System		68TH CT SW - N	Other	9/3/2020
5611	WLK146	3% < Cross Slope < 5%			68TH CT SW - N	Other	9/3/2020
5612	WLK146	Crack between 3/4 inch and 1-1/4 inch	Root System		68TH CT SW - N	Other	9/3/2020
5613	WLK147	No passing space			68TH CT SW - W	Other	9/3/2020
5614	WLK147	Vertical displacement < 3/4 inch	Settlement		68TH CT SW - W	Other	9/3/2020
5615	WLK147	Cross Slope > 5%	Driveway/Driveway Flare		68TH CT SW - W	Other	9/3/2020
5616	WLK147	3% < Cross Slope < 5%			68TH CT SW - W	Other	9/3/2020
5617	WLK148	3% < Cross Slope < 5%			CAVALIER ST SW - W	Other	9/3/2020
5618	WLK148	3% < Cross Slope < 5%			CAVALIER ST SW - W	Other	9/3/2020
5619	WLK152	Vertical displacement > 1-1/4 inch	Root System		CAVALIER ST SW - E	Other	9/3/2020
5620	WLK149	Crack < 3/4 inch	Age		CAVALIER LOOP SW - N	Other	9/3/2020
5621	WLK149	2% < Cross Slope < 3%			CAVALIER LOOP SW - N	Other	9/3/2020
5622	WLK149	3% < Cross Slope < 5%			CAVALIER LOOP SW - N	Other	9/3/2020
5623	WLK149	3% < Cross Slope < 5%	Root System		CAVALIER LOOP SW - N	Other	9/3/2020
5624	WLK149	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		CAVALIER LOOP SW - N	Other	9/3/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5625	WLK149	Cross Slope > 5%	Root System		CAVALIER LOOP SW - N	Other	9/3/2020
5626	WLK149	3% < Cross Slope < 5%			CAVALIER LOOP SW - N	Other	9/3/2020
5627	WLK150	Vertical displacement > 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5628	WLK150	Severe Cracking			CAVALIER LOOP SW - E	Other	9/3/2020
5629	WLK150	Moderate Cracking			CAVALIER LOOP SW - E	Other	9/3/2020
5630	WLK150	Vertical displacement < 3/4 inch	Settlement		CAVALIER LOOP SW - E	Other	9/3/2020
5631	WLK150	3% < Cross Slope < 5%			CAVALIER LOOP SW - E	Other	9/3/2020
5632	WLK150	Vertical displacement > 1-1/4 inch			CAVALIER LOOP SW - E	Other	9/3/2020
5633	WLK150	Crack > 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5634	WLK150	3% < Cross Slope < 5%	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5635	WLK150	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		CAVALIER LOOP SW - E	Other	9/3/2020
5636	WLK150	3% < Cross Slope < 5%			CAVALIER LOOP SW - E	Other	9/3/2020
5637	WLK150	Crack between 3/4 inch and 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5638	WLK150	2% < Cross Slope < 3%			CAVALIER LOOP SW - E	Other	9/3/2020
5639	WLK150	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5640	WLK151	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5641	WLK151	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CAVALIER LOOP SW - E	Other	9/3/2020
5642	WLK153	No passing space			CAVALIER LOOP SW - W	Other	9/3/2020
5643	WLK153	Cross Slope > 5%	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5644	WLK153	Vertical displacement > 1-1/4 inch	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5645	WLK153	3% < Cross Slope < 5%			CAVALIER LOOP SW - W	Other	9/3/2020
5646	WLK153	Crack < 3/4 inch			CAVALIER LOOP SW - W	Other	9/3/2020
5647	WLK153	Vertical displacement between 3/4 inch and 1-1/4 inch			CAVALIER LOOP SW - W	Other	9/3/2020
5648	WLK149	2% < Cross Slope < 3%	Root System		CAVALIER LOOP SW - N	Other	9/3/2020
5649	WLK153	Moderate Cracking	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5650	WLK153	Crack < 3/4 inch	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5651	WLK153	Minor Cracking	Age		CAVALIER LOOP SW - W	Other	9/3/2020
5652	WLK156	Vertical displacement > 1-1/4 inch	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5653	WLK156	Cross Slope > 5%	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5654	WLK156	Vertical displacement > 1-1/4 inch	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5655	WLK156	Vertical displacement < 3/4 inch			CAVALIER LOOP SW - W	Other	9/3/2020
5656	WLK156	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5657	WLK156	Severe Cracking	Root System		CAVALIER LOOP SW - W	Other	9/3/2020
5658	WLK157	No passing space			71ST CT SW - W	Other	9/3/2020
5659	WLK157	Vertical displacement > 1-1/4 inch	Root System		71ST CT SW - W	Other	9/3/2020
5660	WLK157	Vertical displacement between 3/4 inch and 1-1/4 inch			71ST CT SW - W	Other	9/3/2020
5661	WLK157	3% < Cross Slope < 5%	Root System		71ST CT SW - W	Other	9/3/2020
5662	WLK158	2% < Cross Slope < 3%			71ST CT SW - N	Other	9/3/2020
5663	WLK159	No passing space			CAVALIER LOOP SW - W	Other	9/3/2020
5664	WLK152	Cross Slope > 5%			CAVALIER ST SW - E	Other	9/3/2020
5665	WLK152	Vertical displacement > 1-1/4 inch	Root System		CAVALIER ST SW - E	Other	9/3/2020
5666	WLK152	Crack between 3/4 inch and 1-1/4 inch	Settlement		CAVALIER ST SW - E	Other	9/3/2020
5667	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5668	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5669	WLK138	3% < Cross Slope < 5%			CORTEZ LOOP SW - S	Other	9/3/2020
5670	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5671	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5672	WLK138	Hole < 3/4 inch	Age		CORTEZ LOOP SW - S	Other	9/3/2020
5673	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5674	WLK138	Vertical displacement > 1-1/4 inch	Settlement		CORTEZ LOOP SW - S	Other	9/3/2020
5675	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5676	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5677	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5678	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5679	WLK138	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5680	WLK132	Running Slope > 8.33%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5681	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5682	WLK132	Crack between 3/4 inch and 1-1/4 inch	Settlement		LIDO CT SW - W	Other	9/3/2020
5683	WLK132	Crack between 3/4 inch and 1-1/4 inch	Settlement		LIDO CT SW - W	Other	9/3/2020
5684	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5685	WLK132	Crack < 3/4 inch	Settlement		LIDO CT SW - W	Other	9/3/2020
5686	WLK132	3% < Cross Slope < 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5687	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5688	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5689	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5690	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5691	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5692	WLK132	Vertical displacement between 3/4 inch and 1-1/4 inch			LIDO CT SW - W	Other	9/3/2020
5693	WLK132	Cross Slope > 5%	Driveway/Driveway Flare		LIDO CT SW - W	Other	9/3/2020
5694	WLK129	Minor Cracking	Age		CORTEZ LOOP SW - N	Other	9/3/2020
5695	WLK129	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5696	WLK135	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5697	WLK135	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5698	WLK136	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5699	WLK136	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5700	WLK136	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5701	WLK136	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - S	Other	9/3/2020
5702	WLK137	Vertical displacement > 1-1/4 inch	Age		CORTEZ LOOP SW - N	Other	9/3/2020
5703	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5704	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5705	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5706	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5707	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5708	WLK137	Cross Slope > 5%	Driveway/Driveway Flare		CORTEZ LOOP SW - N	Other	9/3/2020
5709	WLK1227	3% < Cross Slope < 5%	Driveway/Driveway Flare		89TH AVE SE - N	Other	9/4/2020
5710	WLK1230	3% < Cross Slope < 5%			89TH AVE SE - S	Other	9/4/2020
5711	WLK1230	3% < Cross Slope < 5%			89TH AVE SE - S	Other	9/4/2020
5712	WLK1229	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		89TH AVE SE - S	Other	9/4/2020
5713	WLK1229	Vertical displacement < 3/4 inch	Root System		89TH AVE SE - S	Other	9/4/2020
5714	WLK1228	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		89TH AVE SE - N	Other	9/4/2020
5715	WLK1228	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		89TH AVE SE - N	Other	9/4/2020
5716	WLK1228	Vertical displacement > 1-1/4 inch	Root System		89TH AVE SE - N	Other	9/4/2020
5717	WLK1228	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		89TH AVE SE - N	Other	9/4/2020
5718	WLK1227	3% < Cross Slope < 5%			89TH AVE SE - N	Other	9/4/2020
5719	WLK1227	2% < Cross Slope < 3%			89TH AVE SE - N	Other	9/4/2020
5720	WLK1238	3% < Cross Slope < 5%			89TH AVE SE - S	Other	9/4/2020
5721	WLK1241	Vertical displacement > 1-1/4 inch	Root System		89TH AVE SE - S	Other	9/4/2020
5722	WLK1241	Vertical displacement > 1-1/4 inch	Root System		89TH AVE SE - S	Other	9/4/2020
5723	WLK1254	2% < Cross Slope < 3%			BUTTERCUP ST SE - W	Other	9/4/2020
5724	WLK1254	2% < Cross Slope < 3%			BUTTERCUP ST SE - W	Other	9/4/2020
5725	WLK1254	3% < Cross Slope < 5%			BUTTERCUP ST SE - W	Other	9/4/2020
5726	WLK1254	3% < Cross Slope < 5%			BUTTERCUP ST SE - W	Other	9/4/2020
5727	WLK1255	2% < Cross Slope < 3%			BUTTERCUP ST SE - E	Other	9/4/2020
5728	WLK1237	3% < Cross Slope < 5%			BUTTERCUP ST SE - E	Other	9/4/2020
5729	WLK1233	3% < Cross Slope < 5%			ASTER ST SE - W		9/4/2020
5730	WLK1252	2% < Cross Slope < 3%			ASTER ST SE - W		9/4/2020
5731	WLK1252	2% < Cross Slope < 3%			ASTER ST SE - W		9/4/2020
5732	WLK1253	2% < Cross Slope < 3%			ASTER ST SE - E	Other	9/4/2020
5733	WLK1214	Vertical displacement > 1-1/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5734	WLK1214	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5735	WLK1214	Vertical displacement < 3/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5736	WLK1214	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5737	WLK1214	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5738	WLK1212	Vertical displacement < 3/4 inch	Root System		TRADEWINDS DR SE - E		9/4/2020
5739	WLK1207	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SELECT CT SE - E		9/4/2020
5740	WLK1206	Vertical displacement < 3/4 inch	Root System		88TH AVE SE - S		9/4/2020
5741	WLK1205	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		88TH AVE SE - S		9/4/2020
5742	WLK1205	Vertical displacement > 1-1/4 inch	Root System		88TH AVE SE - S		9/4/2020
5743	WLK1205	Vertical displacement > 1-1/4 inch	Root System		88TH AVE SE - S		9/4/2020
5744	WLK1208	Vertical displacement < 3/4 inch	Root System		SELECT CT SE - E		9/4/2020
5745	WLK1208	Minor Cracking	Age		SELECT CT SE - E		9/4/2020
5746	WLK1211	Vertical displacement < 3/4 inch	Root System		TRADEWINDS DR SE - W		9/4/2020
5747	WLK1213	Vertical displacement > 1-1/4 inch	Root System		TRADEWINDS DR SE - W		9/4/2020
5748	WLK1213	Vertical displacement > 1-1/4 inch	Root System		TRADEWINDS DR SE - W		9/4/2020
5749	WLK1242	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5750	WLK1242	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5751	WLK1223	Vertical displacement > 1-1/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5752	WLK1223	Vertical displacement > 1-1/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5753	WLK1223	Vertical displacement > 1-1/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5754	WLK1223	Vertical displacement < 3/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5755	WLK1223	Vertical displacement < 3/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5756	WLK1220	3% < Cross Slope < 5%			YARROW CT SE - W	Other	9/4/2020
5757	WLK1220	Vertical displacement < 3/4 inch	Root System		YARROW CT SE - W	Other	9/4/2020
5758	WLK1243	3% < Cross Slope < 5%			SILVERSPOT DR SE - E	Other	9/4/2020
5759	WLK1243	Cross Slope > 5%			SILVERSPOT DR SE - E	Other	9/4/2020
5760	WLK1244	Vertical displacement < 3/4 inch	Root System		SILVERSPOT DR SE - E	Other	9/4/2020
5761	WLK1244	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - E	Other	9/4/2020
5762	WLK1245	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - E	Other	9/4/2020
5763	WLK1245	Vertical displacement < 3/4 inch	Root System		SILVERSPOT DR SE - E	Other	9/4/2020
5764	WLK1246	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - E	Other	9/4/2020
5765	WLK1246	Vertical displacement < 3/4 inch			SILVERSPOT DR SE - E	Other	9/4/2020
5766	WLK1250	2% < Cross Slope < 3%			SILVERSPOT DR SE - W		9/4/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5767	WLK1250	3% < Cross Slope < 5%			SILVERSPOT DR SE - W		9/4/2020
5768	WLK1248	Vertical displacement < 3/4 inch			SILVERSPOT CT SE	Other	9/4/2020
5769	WLK1247	5% < Running Slope < 8.33%	Root System		SILVERSPOT DR SE - N	Other	9/4/2020
5770	WLK1247	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - N	Other	9/4/2020
5771	WLK1247	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		SILVERSPOT DR SE - N	Other	9/4/2020
5772	WLK1689	Vertical displacement < 3/4 inch			SILVERSPOT DR SE - W		9/4/2020
5773	WLK1689	Vertical displacement < 3/4 inch	Root System		SILVERSPOT DR SE - W		9/4/2020
5774	WLK1259	3% < Cross Slope < 5%			91ST AVE SE - N	Other	9/4/2020
5775	WLK1265	Crack > 1-1/4 inch			91ST AVE SE - S	Other	9/4/2020
5776	WLK120	2% < Cross Slope < 3%			TROSPER ST SW - E	Urban Collector	9/8/2020
5777	WLK120	2% < Cross Slope < 3%			TROSPER ST SW - E	Urban Collector	9/8/2020
5778	WLK120	2% < Cross Slope < 3%			TROSPER ST SW - E	Urban Collector	9/8/2020
5779	WLK121	2% < Cross Slope < 3%			TROSPER ST SW - W	Urban Collector	9/8/2020
5790	WLK125	No passing space			BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5791	WLK125	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5792	WLK125	2% < Cross Slope < 3%			BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5793	WLK125	Vertical displacement < 3/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5794	WLK125	3% < Cross Slope < 5%	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5795	WLK122	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - W	Urban Collector	9/8/2020
5796	WLK126	Cross Slope > 5%	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5797	WLK126	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5798	WLK126	Vertical displacement < 3/4 inch			BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5799	WLK126	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5800	WLK126	Vertical displacement > 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5801	WLK128	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5802	WLK128	Crack between 3/4 inch and 1-1/4 inch	Settlement		JODY CT SW - W	Other	9/8/2020
5803	WLK128	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5804	WLK128	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5805	WLK128	Crack < 3/4 inch	Age		JODY CT SW - W	Other	9/8/2020
5806	WLK128	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5807	WLK128	Running Slope > 8.33%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5808	WLK128	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5809	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5810	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5811	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5812	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5813	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5814	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5815	WLK134	Crack < 3/4 inch	Age		JODY CT SW - W	Other	9/8/2020
5816	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5817	WLK134	Crack < 3/4 inch	Age		JODY CT SW - W	Other	9/8/2020
5818	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5819	WLK134	Cross Slope > 5%	Driveway/Driveway Flare		JODY CT SW - W	Other	9/8/2020
5820	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5821	WLK130	Crack > 1-1/4 inch	Settlement		NEWPORT CT SW - W	Other	9/8/2020
5822	WLK130	Crack < 3/4 inch	Settlement		NEWPORT CT SW - W	Other	9/8/2020
5823	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5824	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5825	WLK130	Crack < 3/4 inch	Settlement		NEWPORT CT SW - W	Other	9/8/2020
5826	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5827	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5828	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5829	WLK130	Cross Slope > 5%	Driveway/Driveway Flare		NEWPORT CT SW - W	Other	9/8/2020
5830	WLK139	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5831	WLK139	3% < Cross Slope < 5%			BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5832	WLK1064	Vertical displacement between 3/4 inch and 1-1/4 inch	Settlement		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5833	WLK1064	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5834	WLK1064	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5835	WLK1064	Vertical displacement < 3/4 inch	Root System		BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5836	WLK1064	3% < Cross Slope < 5%			BLACK LAKE - BELMORE RD SW - E	Urban Collector	9/8/2020
5837	WLK122	Vertical displacement > 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - W	Urban Collector	9/8/2020
5838	WLK122	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - W	Urban Collector	9/8/2020
5839	WLK122	Vertical displacement > 1-1/4 inch	Root System		BLACK LAKE - BELMORE RD SW - W	Urban Collector	9/8/2020
5840	WLK123	Vertical displacement > 1-1/4 inch	Root System		61ST AVE SW - N	Other	9/8/2020
5841	WLK123	Vertical displacement > 1-1/4 inch	Root System		61ST AVE SW - N	Other	9/8/2020
5842	WLK123	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		61ST AVE SW - N	Other	9/8/2020
5843	WLK123	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		61ST AVE SW - N	Other	9/8/2020
5844	WLK123	Minor Cracking			61ST AVE SW - N	Other	9/8/2020
5845	WLK123	Minor Cracking	Age		61ST AVE SW - N	Other	9/8/2020
5846	WLK123	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		61ST AVE SW - N	Other	9/8/2020
5847	WLK124	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		61ST AVE SW - S	Other	9/8/2020

City of Tumwater - Sidewalk Self-Evaluation

OBJECTID	SidewalkID	RATING	CAUSE	COMMENT	STREET	STREET TYPE	SURVEY DATE
5848	WLK124	Minor Cracking	Age		61ST AVE SW - S	Other	9/8/2020
5849	WLK124	Vertical displacement > 1-1/4 inch	Root System		61ST AVE SW - S	Other	9/8/2020
5850	WLK124	Vertical displacement > 1-1/4 inch	Root System		61ST AVE SW - S	Other	9/8/2020
5851	WLK124	Vertical displacement > 1-1/4 inch	Root System		61ST AVE SW - S	Other	9/8/2020
5867	WLK1199	2% < Cross Slope < 3%			CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5868	WLK1199	Cross Slope > 5%	Driveway/Driveway Flare		CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5869	WLK1199	3% < Cross Slope < 5%			CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5870	WLK1199	3% < Cross Slope < 5%	Driveway/Driveway Flare		CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5871	WLK1199	Cross Slope > 5%	Driveway/Driveway Flare		CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5872	WLK1199	Vertical displacement < 3/4 inch	Root System		CENTER ST SW - E	Commercial/Industrial Collector	9/8/2020
5880	WLK1197	3% < Cross Slope < 5%			83RD AVE SW - N	Urban Collector	9/8/2020
5881	WLK1197	3% < Cross Slope < 5%			83RD AVE SW - N	Urban Collector	9/8/2020
5882	WLK1197	5% < Running Slope < 8.33%	Driveway/Driveway Flare		83RD AVE SW - N	Urban Collector	9/8/2020
5883	WLK1197	2% < Cross Slope < 3%			83RD AVE SW - N	Urban Collector	9/8/2020
5884	WLK1197	5% < Running Slope < 8.33%	Driveway/Driveway Flare		83RD AVE SW - N	Urban Collector	9/8/2020
5885	WLK1196	3% < Cross Slope < 5%			KIMMIE ST SW - E	Urban Collector	9/8/2020
5886	WLK1196	Running Slope > 8.33%	Driveway/Driveway Flare		KIMMIE ST SW - E	Urban Collector	9/8/2020
5887	WLK1196	3% < Cross Slope < 5%			KIMMIE ST SW - E	Urban Collector	9/8/2020
5888	WLK1196	Running Slope > 8.33%	Driveway/Driveway Flare		KIMMIE ST SW - E	Urban Collector	9/8/2020
5889	WLK1194	No passing space			KIMMIE ST SW - E	Urban Collector	9/8/2020
5890	WLK1195	No passing space			KIMMIE ST SW - E	Urban Collector	9/8/2020
5894	WLK1193	No passing space			KIMMIE ST SW - E	Other	9/8/2020
5895	WLK1193	3% < Cross Slope < 5%			KIMMIE ST SW - E	Other	9/8/2020
5896	WLK1193	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		KIMMIE ST SW - E	Other	9/8/2020
5897	WLK2	No passing space			LATHROP INDUSTRIAL DR SW - E	Other	9/8/2020
5898	WLK1217	Vertical displacement > 1-1/4 inch	Root System		85TH AVE SE - S		9/8/2020
5899	WLK1217	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		85TH AVE SE - S		9/8/2020
5900	WLK1217	Vertical displacement between 3/4 inch and 1-1/4 inch	Root System		85TH AVE SE - S		9/8/2020